6.1 Speed and distance measuring device (through the water)6 .....
6.2 Speed and distance measuring device (over the ground in the forward and athwartship direction)6 .....
6.3 Echo-sounding device6 .....
7.1 Rudder, propeller, thrust, pitch and operational mode indicator 6 .....
7.2 Rate-of-turn indicator6 .....
8 Sound reception system6 .....

SOURCE: MSC.503(105).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.503(105).pdf
8 Sound reception system6 .....
9 Telephone to emergency steering position6 .....
10 Daylight signalling lamp6 .....
11 Radar reflector6 .....
12 International Code of Signals .....
13 IAMSAR Manual, Volume III .....

THIS IS TO CERTIFY that this Record is correct in all respects.

SOURCE: MSC.503(105).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.503(105).pdf
THIS IS TO CERTIFY that this Record is correct in all respects.

Issued at .....
(Place of issue of the Record)

....
(Date of issue) (Signature of duly authorized official issuing the Record)

(Seal or stamp of the issuing authority, as appropriate)"

***

4 Delete as appropriate.

6 Alternative means of meeting this requirement are permitted under regulation V/19. In case of other means, they should
be specified.

RESOLUTION MSC.503(105) (adopted on 28 April 2022)
AMENDMENTS TO THE CODE OF SAFETY FOR SPECIAL PURPOSE SHIPS, 2008
(2008 SPS CODE)

SOURCE: MSC.559(108).pdf

URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.559(108).pdf
RESOLUTION MSC.559(108) (adopted on 23 May 2024)
AMENDMENTS TO THE REQUIREMENTS FOR MAINTENANCE, THOROUGH EXAMINATION, OPERATIONAL TESTING, OVERHAUL AND REPAIR OF LIFEBOATS AND RESCUE BOATS, LAUNCHING APPLIANCES AND RELEASE GEAR (RESOLUTION MSC.402(96))
RESOLUTION MSC.559(108)
(adopted on 23 May 2024)
AMENDMENTS TO THE REQUIREMENTS FOR MAINTENANCE, THOROUGH EXAMINATION, OPERATIONAL TESTING, OVERHAUL AND REPAIR OF LIFEBOATS AND RESCUE BOATS, LAUNCHING APPLIANCES AND RELEASE GEAR
(RESOLUTION MSC.402(96))
THE MARITIME SAFETY COMMITTEE,
RECALLING Article 28(b) of the Convention on the International Maritime Organization concerning the functions of the Committee,
RECALLING ALSO resolution MSC.402(96), by which it adopted the Requirements for maintenance, thorough examination, operational testing, overhaul and repair of lifeboats and rescue boats, launching appliances and release gear ("the Requirements"), which has become
---
SOURCE: MSC.559(108).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.559(108).pdf
rescue boats, launching appliances and release gear ("the Requirements"), which has become mandatory under chapter III of the International Convention for the Safety of Life at Sea (SOLAS), 1974 ("the Convention"), as amended by resolution MSC.404(96),
RECALLING FURTHER article VIII(b) and regulation III/3.25 of the Convention concerning the procedure for amending the Requirements,
TAKING INTO ACCOUNT the amendments to the LSA Code adopted by resolution MSC.535(107), with respect to ventilation means, and openings of the ventilation system and their means of closing for totally enclosed lifeboats,
RECOGNIZING the need to keep the Requirements up to date with regard to annual thorough examination and operational testing of ventilation systems,
HAVING CONSIDERED, at its 108th session, amendments to the Requirements, proposed and circulated in accordance with VIII(b)(i) of the Convention,
1 ADOPTS, in accordance with Article VIII(b)(iv) of the Convention, amendments to the
---
SOURCE: MSC.559(108).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.559(108).pdf
1 ADOPTS, in accordance with Article VIII(b)(iv) of the Convention, amendments to the Requirements for maintenance, thorough examination, operational testing, overhaul and repair of lifeboats and rescue boats, launching appliances and release gear, the text of which is set out in the annex to the present resolution;
2 DETERMINES, in accordance with article VIII(b)(vi)(2)(bb) of the Convention, that the amendments shall be deemed to have been accepted on 1 July 2025, unless, prior to that date, more than one third of the Contracting Governments to the Convention or Cont racting Governments the combined merchant fleets of which constitute not less than 50% of the gross tonnage of the world's merchant fleet have notified the Secretary -General of their objections to the amendments;
3 INVITES SOLAS Contracting Governments to note that, in accordance with article VIII(b)(vii)(2) of the Convention, the amendments shall enter into force

---
SOURCE: MSC.559(108).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.559(108).pdf
with article VIII(b)(vii)(2) of the Convention, the amendments shall enter into force on 1 January 2026 upon their acceptance in accordance with paragraph 2 above;
4 REQUESTS the Secretary -General, in conformity with Article VIII(b)(v) of the Convention, to transmit certified copies of the present resolution and the text of the amendments contained in the annex to all Contracting Governments to the Convention;
5 ALSO REQUESTS the Secretary-General to transmit copies of this resolution and its annex to Members of the Organization which are not Contracting Governments to the Convention.
RESOLUTION MSC.559(108) (adopted on 23 May 2024)
AMENDMENTS TO THE REQUIREMENTS FOR MAINTENANCE, THOROUGH EXAMINATION, OPERATIONAL TESTING, OVERHAUL AND REPAIR OF LIFEBOATS AND RESCUE BOATS, LAUNCHING APPLIANCES AND RELEASE GEAR (RESOLUTION MSC.402(96))
MSC 108/20/Add.1
Annex 28, page 2
ANNEX
AMENDMENTS TO THE REQUIREMENTS FOR MAINTENANCE, THOROUGH

SOURCE: MSC.559(108).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.559(108).pdf
MSC 108/20/Add.1
Annex 28, page 2
ANNEX
AMENDMENTS TO THE REQUIREMENTS FOR MAINTENANCE, THOROUGH EXAMINATION, OPERATIONAL TESTING, OVERHAUL AND REPAIR OF LIFEBOATS AND RESCUE BOATS, LAUNCHING APPLIANCES AND RELEASE GEAR (RESOLUTION MSC.402(96))
6 SPECIFIC PROCEDURES FOR INSPECTION, MAINTENANCE, THOROUGH EXAMINATION, OPERATIONAL TESTING, OVERHAUL AND REPAIR
6.2 Annual thorough examination and operational test
1 Paragraph 6.2.3 is replaced by the following:
"6.2.3 For lifeboats (including free-fall lifeboats), rescue boats and fast rescue boats, the following items shall be thoroughly examined and checked for satisfactory condition and operation:
.1 condition of the boat structure including fixed and loose equipment (including a visual examination of the external boundaries of the void spaces, as far as practicable);
.2 engine and propulsion system;
.3 sprinkler system, where fitted;
.4 air supply system, where fitted;
.5 manoeuvring system;

SOURCE: MSC.559(108).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.559(108).pdf
.2 engine and propulsion system;
.3 sprinkler system, where fitted;

.4 air supply system, where fitted;
.5 manoeuvring system;
.6 power supply system;
.7 bailing system;
.8 fender/skate arrangements;
.9 rescue boat righting system, where fitted; and
.10 ventilation system, where fitted."
RESOLUTION MSC.559(108) (adopted on 23 May 2024)
AMENDMENTS TO THE REQUIREMENTS FOR MAINTENANCE, THOROUGH EXAMINATION, OPERATIONAL TESTING, OVERHAUL AND REPAIR OF LIFEBOATS AND RESCUE BOATS, LAUNCHING APPLIANCES AND RELEASE GEAR (RESOLUTION MSC.402(96))
RESOLUTION MSC.559(108) (adopted on 23 May 2024)
AMENDMENTS TO THE REQUIREMENTS FOR MAINTENANCE, THOROUGH EXAMINATION, OPERATIONAL TESTING, OVERHAUL AND REPAIR OF LIFEBOATS AND RESCUE BOATS, LAUNCHING APPLIANCES AND RELEASE GEAR (RESOLUTION MSC.402(96))

SOURCE: MSC.490(103).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.490(103).pdf
RESOLUTION MSC.490(103) (adopted 14 May 2021)
RECOMMENDED ACTION TO PRIORITIZE COVID-19 VACCINATION OF SEAFARERS
MSC 103/21/Add.1
Annex 15, page 1

I:\MSC\103\MSC 103/21/Add.1
ANNEX 15

RESOLUTION MSC.490(103)
(adopted 14 May 2021)

RECOMMENDED ACTION TO PRIORITIZE COVID-19 VACCINATION OF SEAFARERS

THE MARITIME SAFETY COMMITTEE,

RECALLING Article 28(b) of the Convention on the International Maritime Organization concerning the functions of the Committee,

RECALLING ALSO that the Council, at its thirty-first extraordinary session, urged flag and port States to ensure the welfare of seafarers, in particular that their rights to wages, shore leave,