marking on deckhead and bulkhead and on the vertical boundaries allowing easy identification of the sections o f the fixed fire -extinguishing system. Suitable signage and markings shall be adapted to typical patterns of crew movement taking into consideration obstruction by cargo or fixed installations. Section number signs shall be of photoluminescent material . The section numbering indicated inside the space shall be same as section valve identification and section identification at the safety centre or continuously manned control station."

Regulation 23

Safety centre on passenger ships

6 Control and monitoring of safety systems

19 Paragraph 6.10 is replaced by the following:

".10 fire detection and fire alarm system;"

SOURCE: MSC.550(108).pdf

URL:

https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.550(108).pdf

19 Paragraph 6.10 is replaced by the following:

".10 fire detection and fire alarm system;"

CHAPTER V

SAFETY OF NAVIGATION

Regulation 31

Danger messages

20 The following new paragraphs are inserted after existing paragraph 1:

"2.1 The master of every ship involved in the loss of freight container(s), shall communicate the particulars of such an incident by appropriate means without delay and to the fullest extent possible to ships in the vicinity, to the nearest coastal State, and also to the flag State.

2.2 In the event of the ship referred to in paragraph 2.1 being abandoned, or in the event of a report from such a ship being incomplete or unobtainable, the company, as defined in regulation IX/1.2, shall, to the fullest extent possible, assume the obligations placed upon the master by this regulation.

SOURCE: MSC.550(108).pdf

URL:

https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.550(108).pdf

as defined in regulation IX/1.2, shall, to the fullest extent possible, assume the obligations placed upon the master by this regulation.

2.3 The flag State, once informed in accordance with paragraph 2.1, shall report to the Organization on the loss of freight container(s).

2.4 The master of every ship that observes freight container(s) drifting at sea, shall communicate the particulars of such an observation by appropriate means without delay and to the fullest extent possible to ships in the vicinity and to the nearest coastal State."

21 Existing paragraphs 2, 3 and 4 are renumbered as paragraphs 3, 4 and 5, respectively.

Regulation 32

Information required in danger messages

22 The following new paragraph is inserted after existing paragraph 2 (Tropical cyclones (storms)):

"3 Loss or observation of freight container(s)

.1 Loss of freight container(s) from a ship

It is recognized that at the time of the initial reporting, not all of the information

---

SOURCE: MSC.550(108).pdf

URL:

https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.550(108).pdf

.1 Loss of freight container(s) from a ship

It is recognized that at the time of the initial reporting, not all of the information

elements may be available. Any subsequent and/or additional information shall be reported by the master at the earliest opportunity after the initial reporting.

The report shall include:

.1 General information

- Type of report: Loss of freight container(s) from a ship
- Time (Universal Coordinated Time) and date
- Ship's identity (IMO number/name/call sign/MMSI)
- From: Master of the ship, or contact details of their representative reporting on master's behalf

- To: Nearest coastal State where the incident occurred and flag State
- The message number: In chronological order if other freight container loss messages are sent following the first one.

SOURCE: MSC.550(108).pdf

URL:

https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.550(108).pdf

flag State

- The message number: In chronological order if other freight container loss messages are sent following the first one.

At the earliest, safe and practicable opportunity, a thorough inspection shall be conducted. The number or estimated number of lost freight container(s) shall be verified. A message containing this verified number shall be marked as "final" and sent to the same recipients.

.2 Position reporting

Position in latitude and longitude, or true bearing and distance in nautical miles from a clearly identified landmark (where possible)

- Position of the ship when freight container(s) were lost; or
- If the position of the ship when the freight container(s) were lost is not known, the estimated position of the ship when the freight container(s) were lost; or
- If an estimated position of the ship when the freight container(s) were lost is not known or cannot be determined, the position of the ship upon discovery of the loss.

SOURCE: MSC.550(108).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.550(108).pdf
container(s) were lost is not known or cannot be
determined, the position of the ship upon discovery of the
loss.
.3 Total number or estimated number of freight container(s) lost, as
appropriate:
.4 Type of goods in freight container(s):
- Dangerous goods: Yes/No
- UN number (if known)
.5 Description of freight container(s) lost as far as available and
practicable:
.1 Dimension of freight container(s) (e.g. 20 foot);
.2 Type(s) of freight container(s) (e.g. reefer); and
.3 Number or estimated number of empty freight
container(s).
.6 The master may provide additional information, if available and
practicable, for example but not limited to:
- Cargo description according to the dangerous goods
manifest (if applicable)
- Description of any cargo spill
RESOLUTION MSC.550(108) (adopted on 23 May 2024)
AMENDMENTS TO CHAPTERS II-2 AND V OF THE
INTERNATIONAL CONVENTION FOR THE SAFETY OF LIFE AT SEA, 1974
- 12 -
- Wind direction and speed
- Sea current direction and speed

SOURCE: MSC.550(108).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.550(108).pdf
INTERNATIONAL CONVENTION FOR THE SAFETY OF LIFE AT SEA, 1974
- 12 -
- Wind direction and speed
- Sea current direction and speed
- Estimated drift direction and speed of lost freight
container(s)
- Sea state and wave height
.2 Observation of freight container(s) drifting at sea
.1 General information
- Type of report: Observation of freight container(s) drifting
at sea
- Time (Universal Coordinated Time) and date
- Ship's identity (IMO number/name/call sign/MMSI)
- From: Master of the ship
- To: Nearest coastal State to the position of observation
.2 Position reporting
Time (Universal Coordinated Time), date and position of the
observed freight container(s) in latitude and longitude, or true
bearing and distance in nautical miles from a clearly identified

landmark (where possible)
.3 Total number of freight container(s) observed
.4 The master may provide additional information, if available and
practicable, for example but not limited to:

SOURCE: MSC.550(108).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.550(108).pdf
.4 The master may provide additional information, if available and
practicable, for example but not limited to:
- Dimension of freight container(s) (e.g. 20 foot)
- Type(s) of freight container(s) (e.g. reefer)
- Description of any cargo spill
- Wind direction and speed
- Sea current direction and speed
- Estimated drift direction and speed of observed freight
container(s)
- Sea state and wave height "
23 Existing paragraphs 3, 4 and 5 are re numbered as paragraphs 4, 5 and 6 ,
respectively.
RESOLUTION MSC.550(108) (adopted on 23 May 2024)
AMENDMENTS TO CHAPTERS II-2 AND V OF THE
INTERNATIONAL CONVENTION FOR THE SAFETY OF LIFE AT SEA, 1974
RESOLUTION MSC.550(108) (adopted on 23 May 2024)
AMENDMENTS TO CHAPTERS II-2 AND V OF THE
INTERNATIONAL CONVENTION FOR THE SAFETY OF LIFE AT SEA, 1974

SOURCE: MSC.552(108).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.552(108).pdf
RESOLUTION MSC.552(108) (adopted on 23 May 2024)
AMENDMENTS TO THE INTERNATIONAL CODE
FOR THE SAFE CARRIAGE OF GRAIN IN BULK (RESOLUTION MSC.23(59))
RESOLUTION MSC.552(108)
(adopted on 23 May 2024)
AMENDMENTS TO THE INTERNATIONAL CODE