11 Fire safety
11.3 Regulations for fire protection
20 Paragraph 11.3.1 is replaced by the following:
"11.3.1 For ships constructed on or after 1 January 2026, fuel preparation rooms shall, for the purpose of the application of SOLAS regulation II-2/9, be regarded as a machinery space of category A."
RESOLUTION MSC.551(108) (adopted on 23 May 2024)
AMENDMENTS TO THE INTERNATIONAL CODE OF SAFETY
FOR SHIPS USING GASES OR OTHER LOW-FLASHPOINT FUELS (IGF CODE)
- 8 -
11.6 Regulations for dry chemical powder fire-extinguishing system
21 Paragraph 11.6.2 is replaced by the following:

SOURCE: MSC.551(108).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.551(108).pdf
- 8 -
11.6 Regulations for dry chemical powder fire-extinguishing system
21 Paragraph 11.6.2 is replaced by the following:
"11.6.2 In addition to any other portable fire extinguishers that may be required elsewhere in IMO instruments, one portable dry powder extinguisher of at least 5 kg capacity shall be located near the bunkering station and in the fuel preparation room. For ships constructed before 1 January 2026, the portable dry powder extinguisher shall be provided in the fuel preparation room not later than the first survey on or after 1 January 2026."
12 Explosion prevention
12.5 Hazardous area zones
22 Paragraph 12.5.1 is replaced by the following:
"12.5.1 Hazardous area zone 0
For ships constructed on or after 1 January 2026, this zone includes, but is not limited to, the interiors of fuel tanks, any pipework for pressure relief or other venting systems for fuel tanks, pipes and equipment containing fuel, and interbarrier spaces as defined
---
SOURCE: MSC.551(108).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.551(108).pdf
for fuel tanks, pipes and equipment containing fuel, and interbarrier spaces as defined by paragraph 2.2.15.2."
12.5.2 Hazardous area zone 1
23 Paragraph 12.5.2.1 is replaced by the following:
".1 for ships constructed on or after 1 January 2026, tank connection spaces and fuel storage hold spaces;"
15 Control, monitoring and safety systems
15.4 Regulations for bunkering and liquefied gas fuel tank monitoring
15.4.1 Level indicators for liquefied gas fuel tanks
24 Paragraph 15.4.1.3 is replaced by the following:
".3 For ships constructed on or after 1 January 2026, liquefied gas fuel tank liquid level gauges may be of the following types:
.1 indirect devices which determine the amount of fuel by means such as weighing or in-line flow metering;
.2 closed devices which do not penetrate the liquefied gas fuel tank, such as devices using radioisotopes or ultrasonic devices; or

.3 closed devices which penetrate the liquefied gas fuel tank but which
---
SOURCE: MSC.551(108).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.551(108).pdf
such as devices using radioisotopes or ultrasonic devices; or
.3 closed devices which penetrate the liquefied gas fuel tank but which
form part of a closed system and keep the gas fuel from being
released. Such devices shall be considered as tank connections. If
the closed gauging device is not mounted directly onto th e tank, it
shall be provided with a shut off valve located as close as possible
to the tank."
RESOLUTION MSC.551(108) (adopted on 23 May 2024)
AMENDMENTS TO THE INTERNATIONAL CODE OF SAFETY
FOR SHIPS USING GASES OR OTHER LOW-FLASHPOINT FUELS (IGF CODE)
- 9 -
Part B-1
16 Manufacture, workmanship and testing
16.3 Welding of metallic materials and non -destructive testing for the fuel
containment system
16.3.5 Production weld tests
25 Paragraph 16.3.5.1 is replaced by the following:
"16.3.5.1 For all fuel tanks and process pressure vessels except membrane
tanks, production weld tests shall generally be performed for approximately
---
SOURCE: MSC.551(108).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.551(108).pdf
tanks, production weld tests shall generally be performed for approximately
each 50 m of butt -weld joints and shall be representative of each welding position.
For secondary barriers, the same type production tests as required for primary
barriers shall be performed, except that the number of tests may be reduced subject
to agreement with the Administration. Tests, other than those specified in 16.3.5.2
to 16.3.5.5, may be required for fuel tanks or secondary barriers."
Part C-1
18 Operation
18.4 Regulations for bunkering operations
18.4.1 Responsibilities
26 Paragraph 18.4.1.1.1 is replaced by the following:
"18.4.1.1 Before any bunkering operation commences, the master of the
receiving ship or their representative and the representative of the bunkering source
(Persons In Charge, PIC) shall:
.1 agree in writing the transfer procedure, including cooling down and
if necessary, gassing up; the maximum transfer rate at all stages ;

SOURCE: MSC.551(108).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.551(108).pdf
.1 agree in writing the transfer procedure, including cooling down and
if necessary, gassing up; the maximum transfer rate at all stages ;
minimum and maximum limiting transfer pressure and temperature;

bunkering line PRVs settings; and volume to be transferred;"
RESOLUTION MSC.551(108) (adopted on 23 May 2024)
AMENDMENTS TO THE INTERNATIONAL CODE OF SAFETY
FOR SHIPS USING GASES OR OTHER LOW-FLASHPOINT FUELS (IGF CODE)
RESOLUTION MSC.551(108) (adopted on 23 May 2024)
AMENDMENTS TO THE INTERNATIONAL CODE OF SAFETY
FOR SHIPS USING GASES OR OTHER LOW-FLASHPOINT FUELS (IGF CODE)

SOURCE: MSC.553(108).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.553(108).pdf
RESOLUTION MSC.553(108) (adopted on 23 May 2024)
AMENDMENTS TO THE INTERNATIONAL CODE ON THE ENHANCED PROGRAMME
OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS, 2011 (2011 ESP CODE)
RESOLUTION MSC.553(108)
(adopted on 23 May 2024)
AMENDMENTS TO THE INTERNATIONAL CODE ON THE ENHANCED PROGRAMME
OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS, 2011
(2011 ESP CODE)
THE MARITIME SAFETY COMMITTEE,
RECALLING Article 28(b) of the Convention on the International Maritime Organization
concerning the functions of the Committee,
NOTING resolution A.1049(27), by which the Assembly adopted the International Code on the
Enhanced Programme of Inspections during Surveys of Bulk Carriers and Oil Tankers, 2011
("the 2011 ESP Code"), which has become mandatory under chapter XI-1 of the International
Convention for the Safety of Life at Sea, 1974 ("the Convention"),
NOTING ALSO article VIII(b) and regulation XI -1/2 of the Convention concerning the
---
SOURCE: MSC.553(108).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.553(108).pdf
NOTING ALSO article VIII(b) and regulation XI -1/2 of the Convention concerning the
procedure for amending the 2011 ESP Code,
HAVING CONSIDERED, at its 108th session, amendments to the 2011 ESP Code, proposed
and circulated in accordance with article VIII(b)(i) of the Convention:
1 ADOPTS, in accordance with article VIII(b)(iv) of the Convention, amendments to
the 2011 ESP Code the text of which is set out in the annex to the present resolution;
2 DETERMINES, in accordance with article VIII(b)(vi)(2)(bb) of the Convention, that the
said amendments shall be deemed to have been accepted on 1 July 2025, unless, prior to that
date, more than one third of the Contracting Governments to the Convention or Contracting
Governments the combined merchant fleets of which constitute not less than 50% of the gross
tonnage of the world's merchant fleet have notified the Secretary -General of their objections
to the amendments;

SOURCE: MSC.553(108).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.553(108).pdf
tonnage of the world's merchant fleet have notified the Secretary -General of their objections
to the amendments;
3 INVITES Contracting Governments to the Convention to note that, in accordance with

article VIII(b)(vii)(2) of the Convention, the amendments shall enter into force on 1 January 2026 upon their acceptance in accordance with paragraph 2 above;

4 REQUESTS the Secretary -General, for the purposes of article VIII(b)(v) of the Convention, to transmit certified copies of the present resolution and the text of the amendments contained in the annex to all Contracting Governments to the Convention;

5 ALSO REQUESTS the Secretary-General to transmit copies of this resolution and its annex to Members of the Organization which are not Contracting Governments to the Convention.

RESOLUTION MSC.553(108) (adopted on 23 May 2024)

AMENDMENTS TO THE INTERNATIONAL CODE ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS, 2011 (2011 ESP CODE)

SOURCE: MSC.553(108).pdf

URL:

https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.553(108).pdf

AMENDMENTS TO THE INTERNATIONAL CODE ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS, 2011 (2011 ESP CODE)

ANNEX

AMENDMENTS TO THE INTERNATIONAL CODE ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS, 2011 (2011 ESP CODE)

ANNEX A

CODE ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS

Part A

Code on the enhanced programme of inspections during surveys of bulk carriers having single-side skin construction

Annex 5

Procedures for approval and certification of a firm engaged in thickness measurement of hull structures

2 Procedures for approval and certification

Auditing of the firm

1 Paragraph 2.2 is replaced by the following:

"2.2 Upon reviewing of the documents submitted with satisfactory results, the firm shall be audited by the Administration in order to ascertain that the firm is duly

---

SOURCE: MSC.553(108).pdf

URL:

https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.553(108).pdf

shall be audited by the Administration in order to ascertain that the firm is duly