events, should be provided. For this, paragraph 18.3 of the Code requires that the information shall be on board and available to all concerned, giving the necessary data for the safe carriage of cargo. In detail, the Code requires such information on action to be taken in the event of spills or leak, countermeasures agai nst accidental personal contact, procedures for cargo transfer, and emergency procedures to be on board. With regard to the manuals on procedures for liquefied hydrogen during carriage and transfer operations, the requirements in the Code are applicable and no special requirement is necessary.

4.5 Low density and high diffusivity

Though low density and high diffusivity of hydrogen may reduce the possibility of formation of a flammable atmosphere in open spaces, adequate ventilation is necessary for enclosed

---

SOURCE: MSC.565(108).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.565(108).pdf

a flammable atmosphere in open spaces, adequate ventilation is necessary for enclosed spaces in cargo areas where formation of hydrogen -oxygen/air mixture may occur. Paragraph 12.2 of the Code requires fixed ventilation systems or portable mechanical ventilation for such enclosed spaces. These requirements in the Code are applicable to liquefied hydrogen carriers and no special requirement is necessary in this regard.

4.6 Ignitability

4.6.1 The Code requires electrical bonds of the piping and the cargo tanks in paragraph 5.7.4, exclusion of all sources of ignition in paragraph 11.1.2, electrical installations to minimize the risk of fire and explosion from flammable products in paragraph 10.2.1 and so on, in order to prevent ignition of flammable cargoes.

4.6.2 The Code requires compliance with the relevant standards issued by the International

---

SOURCE: MSC.565(108).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.565(108).pdf
Annex 20, page 12

I:\MSC\108\MSC 108-20-Add.1.docx

4.6.2 The Code requires compliance with the relevant standards issued by the International Electrotechnical Commission (IEC) and the IEC standards specify the details of such safety measures depending on the respective properties of flammable gases including hydrogen. No special requirement is necessary with regard to ignitability of hydrogen.*

4.7 Fire hazard

4.7.1 Safety of personnel in case of fire

To avoid the effects of flame and UV radiation produced by a hydrogen fire, it is effective to use fire-fighter's outfits and protective equipment. The Code already requires fire -fighter's

outfits for ships carrying flammable products in paragraph 11.6.1 and safety equipment in paragraph 14.3. This issue should be considered as the matter of cargo information required by paragraph 18.3 of the Code. Due consideration should be given to the invisible nature of hydrogen fire.

SOURCE: MSC.565(108).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.565(108).pdf
by paragraph 18.3 of the Code. Due consideration should be given to the invisible nature of hydrogen fire.

4.7.2 Compatibility of fire-extinguishing systems

Dry chemical powder fire -extinguishing or carbon dioxide fire -extinguishing systems are considered to be effective in case of hydrogen fire and such fire -extinguishing systems are already required by paragraphs 11.4 and 11.5 of the Code. Special requiremen ts for installation of other types of fire -extinguishing systems are considered unnecessary, except with regard to the increased of amount of carbon dioxide required, as mentioned in the next paragraph in this document.

4.7.3 Increase of the amount of gas for carbon dioxide fire-extinguishing systems

4.7.3.1 Paragraph 11.5.1 of the Code requires as follows:

"Enclosed spaces meeting the criteria of cargo machinery spaces in 1.2.10, and the cargo motor room within the cargo area of any ship, shall be provided with a fixed
---
SOURCE: MSC.565(108).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.565(108).pdf
the cargo motor room within the cargo area of any ship, shall be provided with a fixed fire-extinguishing system complying with the provisions of the FSS Code and taking into account the necessary concentrations/application rate required for extinguishing gas fires."

4.7.3.2 Chapter 5 of the FSS Code, i.e. Fixed gas fire -extinguishing systems, requires that the quantity of carbon dioxide for cargo spaces, unless otherwise provided, shall be sufficient to give a minimum volume of free gas equal to 30% of the gross volume of the largest cargo space to be protected in the ship, in paragraph 2.2.1.1.

4.7.3.3 On the other hand, NFPA 123) requires that the design quantity of carbon dioxide for hydrogen fire should be 75% or more of the gross volume of the protected space. The special requirement for an increased amount of carbon dioxide should be provided for carbon dioxide fire-extinguishing systems.

4.7.4 Features of hydrogen fire

SOURCE: MSC.565(108).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.565(108).pdf
fire-extinguishing systems.

4.7.4 Features of hydrogen fire

Hydrogen burns at high temperature, but generally gives off less radiant heat than propane or other hydrocarbons (e.g. only about 10% of that radiated by an equal -sized propane flame). Although the heat radiated by a hydrogen flame is also relatively low compared to hydrocarbons, it is important to take into account the differences in heats of combustion,

* Electrical equipment used in hydrogen/air mixture should be, at least, the type of "II-C" and "T-1" as the group based on the maximum experimental safe gap for flameproof enclosures and the temperature class based on maximum surface temperature, respectively, according to ISO/IEC 80079-20-14).

burning rate and flame size. Hydrogen flames are colourless or nearly colourless. Both of these
---
SOURCE: MSC.565(108).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.565(108).pdf
I:\MSC\108\MSC 108-20-Add.1.docx
burning rate and flame size. Hydrogen flames are colourless or nearly colourless. Both of these characteristics make it more difficult to detect a hydrogen fire. Even relatively small hydrogen fires are very difficult to extinguish. The only reliable approach to extinguish a fire is to shut off the source of hydrogen supply.

4.8 High pressure hazard

4.8.1 High pressure is a hazard common to hydrogen and other flammable gases listed in the Code. To prevent overpressure, the Code requires various measures such as pressure control and pressure design. Specifically, paragraph 8.2, in regard to the provision of pressure control of cargo tanks, requires fittings of pressure relief valves to the cargo tanks. Furthermore, paragraph 7.1.1 requires temperature control by the use of mechanical refrigeration and/or design to withstand possible increases of tempera ture and pressure. In
---
SOURCE: MSC.565(108).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.565(108).pdf
refrigeration and/or design to withstand possible increases of tempera ture and pressure. In addition, paragraph 15.2 specifies the filling limit of cargo tanks taking into account cargo volume increase by its thermal expansion. These requirements are applicable for hydrogen and no special requirement is considered necessary in this regard.

4.8.2 Boil-off may be a more significant issue for hydrogen than for LNG in particular when insulation properties have deteriorated. Means of handling boil -off gas should be carefully considered taking into account the following issues:

.1 Re-liquefaction of hydrogen involves very specific and costly equipment. Cargo cooling in order to avoid boil-off shows the same kind of issues; and

.2 Notwithstanding the provision in paragraph 7.4.1 of the Code, thermal

oxidation of hydrogen may be permitted in accordance with paragraph 1.3 of the Code.

4.8.3 The special requirements in these aspects are considered necessary.

SOURCE: MSC.565(108).pdf
URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.565(108).pdf

the Code.

4.8.3 The special requirements in these aspects are considered necessary.

4.9 Health hazard

4.9.1 Human safety concern under low temperature

With regard to the influences of cold hydrogen on persons' bodies, suitable protective equipment is effective. In this aspect, paragraph 14.1 of the Code requires suitable protective equipment taking into account the character of the products, therefore, no special requirement is considered necessary.

4.9.2 Static electricity

Hydrogen ignition energy is very low and hydrogen can be easily ignitable by static electricity and due consideration should be given to this issue, in accordance with the requirement in the Code on suitable protective equipment.

4.9.3 Oxygen depletion and asphyxiation

Leakage of hydrogen may cause low level of oxygen and associated asphyxiation.

4.10 Wide range of flammable limits

4.10.1 Extinguishing hydrogen fire

SOURCE: MSC.565(108).pdf
URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.565(108).pdf

4.10 Wide range of flammable limits