FISH MEAL (FISH SCRAP), STABILIZED Anti-oxidant treated
In the individual schedule for "FISH MEAL (FISH SCRAP), STABILIZED Anti-oxidant treated"
(as adopted by resolution MSC.539(107)), BCSN is replaced to read "FISH MEAL (FISH
RESOLUTION MSC.575(110) (adopted on 26 June 2025)

SOURCE: MSC.575(110).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf
(as adopted by resolution MSC.539(107)), BCSN is replaced to read "FISH MEAL (FISH
RESOLUTION MSC.575(110) (adopted on 26 June 2025)

SCRAP), STABILIZED UN 2216 Anti -oxidant treated. Moisture content greater than 5% but
not exceeding 12%, by mass. Fat content not more than 15%"; in the section for "Description",
the words "Moisture content: greater than 5% but not exceeding 12%, by mass." and the words
"Fat content: not more than 15%, by mass." are deleted; and in the table for "Characteristics",
in the box for "Class", the words "Not applicable" are replaced by the number "9"; and in the
box for "MHB", the word "SH" is replaced by the wo rd "Not applicable". In the section for
"Precautions", the text in paragraph 1 is replaced to read as follows:
"1 Stabilization of fish meal shall be achieved to prevent spontaneous
combustion by the effective application of ethoxyquin or BHT (butylated
---
SOURCE: MSC.575(110).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf
"1 Stabilization of fish meal shall be achieved to prevent spontaneous
combustion by the effective application of ethoxyquin or BHT (butylated
hydroxytoluene) or tocopherols at the time of production. The said
application shall occur within 12 months prior to shipment. Fish scrap or fish
meal shall contain remnant measurable anti -oxidant levels of at
least 100 ppm (mg/kg) of ethoxyquin, or 100 ppm (mg/kg) of BHT or 250 ppm
(mg/kg) of tocopherol at the time of shipment."
IRON ORE PELLETS
In the individual schedule for "IRON ORE PELLETS", in the section for "Description", the
second and third sentences are replaced to read "This iron oxide is formed into pellets by using
binders, such as clay, and then hardening by firing at 1,200°C to 1,31 5°C. Moisture content:
up to 6%."; and in the table for "Characteristics", in the box for "Bulk density", "1,900" is
replaced by "1,800"; and in the box for "Stowage factor", the terms "0.45" and "0.52" are
---
SOURCE: MSC.575(110).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf
replaced by "1,800"; and in the box for "Stowage factor", the terms "0.45" and "0.52" are
replaced by the terms "0.42 and 0.56", respectively.
New individual schedules
The following new individual schedules are inserted in alphabetical order:
"ALUMINIUM SULPHATE GRANULAR
Description
Aluminium sulphate granular consists of inorganic white granules. Hygroscopic in nature.
Soluble in water. Used as a coagulant for drinking and wastewater treatment.

Characteristics
Physical properties
Size Angle of repose Bulk density (kg/m3) Stowage factor (m3 /t)
less than 3 mm 40° to 45° 900 to 1,100 0.91 to 1.11
Hazard classification
Class Subsidiary hazard(s) MHB Group
Not applicable Not applicable CR B
Hazard
Causes serious eye damage.
This cargo is hygroscopic and will cake if wet.
This cargo is highly soluble and will be acidic when wet.
This cargo is non-combustible or has a low fire risk.
Stowage and segregation

SOURCE: MSC.575(110).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf
This cargo is highly soluble and will be acidic when wet.
This cargo is non-combustible or has a low fire risk.
Stowage and segregation
Contact with certain metals, e.g. aluminium and zinc, may form hydrogen gas.
"Separated from" most other cargoes since it is a drinking water product.
Hold cleanliness
Clean and dry as relevant to the quality and hazards of the cargo.
RESOLUTION MSC.575(110) (adopted on 26 June 2025)
AMENDMENTS TO THE INTERNATIONAL MARITIME SOLID
BULK CARGOES CODE (IMSBC CODE)
- 6 -
Weather precautions
This cargo shall be kept as dry as practicable. It shall not be handled during precipitation.
During handling of this cargo, all non-working hatches of the cargo spaces into which this cargo is loaded, or to be loaded, shall be closed.
Loading
Trim in accordance with the relevant provisions required under sections 4 and 5 of this Code.
Precautions
Persons who may be exposed to the dust of the cargo shall wear protective gloves and goggles
---
SOURCE: MSC.575(110).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf
Precautions
Persons who may be exposed to the dust of the cargo shall wear protective gloves and goggles
or other equivalent dust eye -protection, face protection and dust filter masks, as necessary.
Minimize dust generation when loading.
Ventilation
The cargo spaces carrying this cargo shall not be ventilated during the voyage.
Carriage
Hatches of the cargo spaces shall be weathertight to prevent water ingress.
Discharge
This cargo is hygroscopic and may cake in overhangs, impairing safety during discharge. If this cargo has hardened, it shall be trimmed to avoid the formation of overhangs, as necessary.
Clean-up

After discharge of this cargo, the cargo spaces and the bilge wells shall be swept clean and then thoroughly washed out.
Emergency procedures
Special emergency equipment to be carried
Protective clothing (gloves, boots, face protection and coveralls).
Self-contained breathing apparatus.
Emergency procedures

SOURCE: MSC.575(110).pdf
URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf
Protective clothing (gloves, boots, face protection and coveralls).
Self-contained breathing apparatus.
Emergency procedures
Wear protective clothing and self-contained breathing apparatus.
Emergency action in the event of fire
Use extinguishers appropriate for surrounding materials. The cargo itself is not combustible.
Medical first aid
Refer to the Medical First Aid Guide (MFAG), as amended.
"
RESOLUTION MSC.575(110) (adopted on 26 June 2025)
AMENDMENTS TO THE INTERNATIONAL MARITIME SOLID BULK CARGOES CODE (IMSBC CODE)
- 7 -
"APATITE CONCENTRATE
Description
Crystalline fine powder of grey colour.
Characteristics
Physical properties
Size Angle of repose Bulk density (kg/m3) Stowage factor (m3/t)
Less than 0.5 mm Not applicable 1,429 to 2,000 0.5 to 0.7
Hazard classification
Class Subsidiary hazard(s) MHB Group
Not applicable Not applicable Not applicable A
Hazard
This cargo may liquefy if shipped at a moisture content in excess of its transportable moisture
---
SOURCE: MSC.575(110).pdf
URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf
Hazard
This cargo may liquefy if shipped at a moisture content in excess of its transportable moisture limit (TML). See sections 7 and 8 of this Code.
This cargo is non-combustible or has a low fire risk.
Stowage and segregation
No special requirements.
Hold cleanliness
No special requirements.
Weather precautions
When a cargo is carried in a ship other than a ship complying with the requirements in 7.3.2 of this Code, the following provisions shall be complied with:

.1 the moisture content of the cargo shall be kept less than its TML during loading operations and the voyage;
.2 unless expressly provided otherwise in this individual schedule, the cargo shall not be handled during precipitation;
.3 unless expressly provided otherwise in this individual schedule, during handling of the cargo, all non-working hatches of the cargo spaces into which the cargo is loaded, or to be loaded, shall be closed;

SOURCE: MSC.575(110).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf
handling of the cargo, all non-working hatches of the cargo spaces into which the cargo is loaded, or to be loaded, shall be closed;
.4 the cargo may be handled during precipitation under the conditions stated in the procedures required in 4.3.3 of this Code; and
.5 the cargo in a cargo space may be discharged during precipitation provided that the total amount of the cargo in the cargo space is to be discharged in the port.
Loading
Hatch covers, manholes and vent openings shall be checked for weather-tightness. Prior to loading, the holds shall be surveyed carefully to ensure a proper condition of ballast, bilge, fire-extinguishing and other systems. Additionally, manholes of the ballast tanks shall be checked for water leakage into the cargo spaces.
This cargo shall be trimmed to ensure that the height difference between peaks and troughs does not exceed 5% of the ship's breadth and that the cargo slopes uniformly from the hatch
---
SOURCE: MSC.575(110).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf
does not exceed 5% of the ship's breadth and that the cargo slopes uniformly from the hatch boundaries to the bulkheads and to avoid steep surfaces of cargo that collapse during the voyage. When the stowage factor of this cargo is equal to or less than 0.56 m 3/t, the tank top

may be overstressed unless the cargo is evenly spread across the tank top to equalize the weight distribution. Due consideration shall be given to ensure that the tank top is not overstressed during the voyage and during loading by a pile of the cargo forming.