May cause an allergic skin reaction due to sensitization.
Causes serious eye damage.
This cargo is highly soluble and will be acidic when wet.
This cargo is hygroscopic and will cake if wet.
This cargo may be subject to decomposition if heated strongly. Decomposition may produce gases that are toxic (sulphur oxides). However, this cargo is not subject to an explosion hazard.
Corrodes metals under the influence of moisture.
This cargo is non-combustible or has a low fire risk.
Stowage and segregation
"Away from" certain metals, e.g. aluminium and zinc, that may form hydrogen gas in case of contact with the cargo.
Avoid contact with unalloyed steel or galvanized surfaces; materials not resistant to acid, copper, aluminium and iron.
"Away" from sources of heat.
Hold cleanliness
Clean and dry as relevant to the hazards of the cargo.
Weather precautions
---
SOURCE: MSC.575(110).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf
"Away" from sources of heat.
Hold cleanliness
Clean and dry as relevant to the hazards of the cargo.
Weather precautions
This cargo shall be kept as dry as practicable. It shall not be handled during precipitation.
During handling of this cargo, all non-working hatches of the cargo spaces into which this cargo is loaded, or to be loaded, shall be closed.
Loading
Trim in accordance with the relevant provisions required under sections 4 and 5 of this Code.
RESOLUTION MSC.575(110) (adopted on 26 June 2025)
AMENDMENTS TO THE INTERNATIONAL MARITIME SOLID
BULK CARGOES CODE (IMSBC CODE)
- 12 -
Precautions
Avoid contact with eyes and skin. Persons who may be exposed to the dust of the cargo shall wear protective clothing, gloves and eye -protection, as necessary. Minimize dust generation when loading.
Bilge wells shall be clean, dry and covered, as appropriate, to prevent ingress of the cargo.
Ventilation
---
SOURCE: MSC.575(110).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf
when loading.
Bilge wells shall be clean, dry and covered, as appropriate, to prevent ingress of the cargo.
Ventilation
The cargo spaces carrying this cargo shall not be ventilated during the voyage.
Carriage
Hatches of the cargo spaces shall be weathertight to prevent water ingress.
Discharge
The product is hygroscopic and may cake in overhangs, impairing safety during discharge.

If this cargo has hardened, it shall be trimmed to avoid the formation of overhangs, as necessary. No discharge operations during precipitation.
Clean-up
After discharge of this cargo, the cargo spaces and the bilge wells shall be swept clean and then thoroughly washed out.
Emergency procedures
Special emergency equipment to be carried
Protective clothing (gloves, boots and coveralls).
Self-contained breathing apparatus.
Emergency procedures
Wear protective clothing and self-contained breathing apparatus.
Emergency action in the event of fire
---
SOURCE: MSC.575(110).pdf
URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf
Emergency procedures
Wear protective clothing and self-contained breathing apparatus.
Emergency action in the event of fire
Use extinguishers appropriate for surrounding materials. The cargo itself is not combustible.
Medical first aid
Refer to the Medical First Aid Guide (MFAG), as amended.
"
"FISH MEAL (FISH SCRAP), STABILIZED
This schedule shall only apply to fish meal that does not meet any of the criteria on dangerous goods or materials hazardous only in bulk specified in sections 9.2.2 or 9.2.3, respectively.
Description
Fresh whole pelagic fish or trimmings for food grade fillet factories that are cooked, dried, with added anti-oxidants and milled before storage. The product is light brown to brown in colour. Water content between 5% to 10%, Fat content below 12%. Most particles between 0.08 mm to 1.2 mm. Smells of fish.
Characteristics
Physical properties
Size Angle of repose Bulk density (kg/m3) Stowage factor (m3/t)
---
SOURCE: MSC.575(110).pdf
URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf
to 1.2 mm. Smells of fish.
Characteristics
Physical properties
Size Angle of repose Bulk density (kg/m3) Stowage factor (m3/t)
Not applicable Not applicable 300 to 700 1.43 to 3.33
Hazard classification
Class Subsidiary hazard(s) MHB Group
Not applicable Not applicable Not applicable C
Hazard
Liable to cause oxygen depletion in cargo space.
RESOLUTION MSC.575(110) (adopted on 26 June 2025)
AMENDMENTS TO THE INTERNATIONAL MARITIME SOLID BULK CARGOES CODE (IMSBC CODE)

This cargo is non-combustible or has a low fire risk.
Stowage and segregation
No special requirements.
Hold cleanliness
Clean and dry as relevant to the hazards of the cargo.
Weather precautions
This cargo shall be kept as dry as practicable. This cargo shall not be handled during precipitation. During handling of this cargo, all non -working hatches of the cargo spaces into which this cargo is loaded, or to be loaded, shall be closed.
Loading
---
SOURCE: MSC.575(110).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf
which this cargo is loaded, or to be loaded, shall be closed.
Loading
Trim in accordance with the relevant provisions required under sections 4 and 5 of this Code.
The cargo shall not be accepted for loading when the temperature of the cargo exceeds 35°C or 5°C above the ambient temperature, whichever is higher. The cargo may be loaded without weathering/curing prior to loading.
A certificate from an entity recognized by the competent authority of the port of loading shall be provided by the shipper prior to loading, stating that the material does not meet the MHB (SH) criteria specified in 9.2.3.3 of this Code.
Precautions
The shipper shall further provide the master with a certificate issued by an entity recognized by the competent authority of the port of loading specifying:
.1 moisture content;
.2 fat content; and
.3 details of anti-oxidant treatment.
A suitable equipment for quantitative measurement of the concentration of oxygen in the cargo
---
SOURCE: MSC.575(110).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf
.3 details of anti-oxidant treatment.
A suitable equipment for quantitative measurement of the concentration of oxygen in the cargo space shall be provided on board the ship. Entry of personnel into cargo spaces for this cargo shall not be permitted until tests have been carried out and it has been established that the oxygen content has been restored to a normal level.
Ventilation
No special requirements.
Carriage
No special requirements.
Discharge
No special requirements.
Clean-up
No special requirements."
"IRON ORE BRIQUETTES
Description
This cargo is composed of hard briquettes generated in the process of cold agglomeration of iron ore and binders, such as sodium silicate. Iron ore briquettes are odourless and vary in

colour, from beige to dark grey, always granular in form, pillow -shaped, not soluble in water
---
SOURCE: MSC.575(110).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf
BULK CARGOES CODE (IMSBC CODE)
- 14 -
colour, from beige to dark grey, always granular in form, pillow -shaped, not soluble in water
and resistant to ageing.
Characteristics
Physical properties
Size Angle of repose Bulk density (kg/m3) Stowage factor (m3/t)
10 mm to 40 mm Not applicable 1,800 to 2,400 0.42 to 0.56
Hazard classification
Class Subsidiary hazard(s) MHB Group
Not applicable Not applicable Not applicable C
Hazard
This cargo may affect magnetic compasses.
This cargo is non-combustible or has a low fire risk.
Stowage and segregation
No special requirements.
Hold cleanliness
No special requirements.
Weather precautions
No special requirements.
Loading
Trim in accordance with the relevant provisions required under sections 4 and 5 of this Code.
As the density of the cargo is extremely high, the tank top may be overstressed unless the
cargo is evenly spread across the tank top to equalize the weight distribution.
---
SOURCE: MSC.575(110).pdf
URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf