3 AA s b e s t o sEngi ne r oom .Pi pi ng/f l ange Packi ng PCHM
4 AH C F C 2nd deck Ref . pr ovi si on pl ant Ref r i ger ant ( R22) 20. 00 1 Rei t o C o. Y Ma k e r ' s d wg
5 BL e a d N av. B r. deckB atte rie s 6 16 D enchi C o. Y E-300
I nvent or y Par t I -3
1 A Asbest os Upper deck Back deck cei l i ngs Engi ne r oom cei l i ng 20m2 Unknow n cei l i ng Unknow n O -25
*1 H azardous M ateri al s: M ateri al cl assi f i cati on
*2
*3 Pr ocedur e of check: V=Vi sual check, S=Sam pl i ng check
*4

---CHUNK---

SOURCE: MEPC.197(62).pdf
1 A Asbest os Upper deck Back deck cei l i ngs Engi ne r oom cei l i ng 20m2 Unknow n cei l i ng Unknow n O -25
*1 H azardous M ateri al s: M ateri al cl assi f i cati on
*2
*3 Pr ocedur e of check: V=Vi sual check, S=Sam pl i ng check
*4
Resul t of docum ent s anal ysi s: Y=C ont ai ned, N=Not cont ai ned, Unk n o w n , P C H M = p o te n tia lly c o n ta in in g H a z a rd o u s M a te ria l.
Resul t of check: Y=C ont ai ned, N=N ot cont ai ned, PC HM
Not es
A N A L Y S IS A N D D E F IN IT IO N O F S C O P E O F A S S E S S M E N T F O R " S A M P L E S HIP "
Res ul t
of
DOC * 2
Tbl
A/B
Pr ocedur e
of check
* 3
R e s u lt o f
check
* 4
Ref er ence/D W G No.
Ha z a r dous
Ma t e r i a l s
*1
I nvent or y Par t I -1
No.
Checklist (Step 2)
Locat i on
O n Aug. 200X, seal er coat
a p p lie d to a ll o v e r s u b m e rg e d
a re a b e fo re tin fre e c o a tin g .
P ain tin g & c o atin g A / F p ain ts
M anuf acturer/brand
nam e
Q u an tity
C om ponentN a m e o f e q u ip m e n t

RESOLUTION MEPC.197(62)
Adopted on 15 July 2011

---CHUNK---

SOURCE: MEPC.197(62).pdf
P ain tin g &  c o atin g A / F  p ain ts
M anuf acturer/brand
nam e
Q u an tity
C om ponentN a m e  o f e q u ip m e n t




4 Step 3: Preparation of visual/sampling check plan

Each item classified as "Contained" or "Not contained" in Step 2 should be subjected to a visual check on board, and the entry "V" should be made in the "Check procedure" column to denote "Visual check".

For each item categorized as "unknown", a decision should be made as to whether to apply a sampling check.  However, any item categorized as "unknown" may be classed as "potentially containing Hazardous Material" provided comprehensive justification is given, or if it can be assumed that there will be little or no effect on disassembly as a unit and later ship recycling and disposal operations.  For example, in the following checklist, in order to carry out a sampling check for "Packing with aux. boiler" the shipowner needs to

---CHUNK---

SOURCE: MEPC.197(62).pdf
ship recycling and disposal operations.  For example, in the following checklist, in order to carry out a sampling check for "Packing with aux. boiler" the shipowner needs to disassemble the auxiliary boiler in a repair yard.  The costs of this check are significantly higher than the later disposal costs at a Ship Recycling Facility.  In this case, therefore, the classification as "potentially containing Hazardous Material" is justifiable.




Un i t
(k g ) No. Tot al  (k g )
1 AT B T T o p  s i d e NI LPai nt s C o. /m ar i ne P1000 NV
2 AT B T F l a t  b o t t o m 3000m 2 Unk nown AF Un k n own S

I nvent or y Par t I -2
1 AA s b e s t o sLower deck M a in e n g in e E x h .p ip e p a c k in g 0 .2 5 1 4 D ie s e l C o . Y V M -100
2 AA s b e s t o s3rd deck A u x .b o ile r L a g g in g 1 2 U nknow n l aggi ng Un k n own S M -300
3 AA s b e s t o sEngi ne r oom Pi pi ng/f l ange Packi ng PCHM V

---CHUNK---

SOURCE: MEPC.197(62).pdf
2 AA s b e s t o s3rd deck A u x .b o ile r L a g g in g 1 2 U nknow n l aggi ng Un k n own S M -300
3 AA s b e s t o sEngi ne r oom Pi pi ng/f l ange Packi ng PCHM V
4 AH C F C 2nd deck R e f. p ro v is io n p la n t R e frig e ra n t (R 2 2 ) 2 0 .0 0 1 R e ito C o . Y V Ma k e r ' s d wg
5 BL e a d Na v . Br . deckBa t t er i es 6 16 D enchi C o. Y V E-300
I nvent or y Par t I -3
1 A Asbestos Upper deck Back deck cei l i ngs Engi ne r oom cei l i ng 20m2 Unknown cei l i ng Unknown S O -25
*1 H azardous M ateri al s: M ateri al cl assi f i cati on
*2
*3 Pr ocedur e of check: V=Vi sual check, S=Sam pl i ng check
*4
Locat i on
O n Aug. 200X, seal er coat
appl i ed t o al l over subm er ged
ar ea bef or e ti n f ree coati ng.
P ain tin g & c o atin g A / F p ain ts
M anuf act ur er /Br and
nam e
Qu a n t i t y
Resul t of docum ent s anal ysi s: Y=C ont ai ned, N=Not cont ai ned, Unkn o w n , P C H M = p o te n tia lly c o n ta in in g H a z a rd o u s M a te ria l
Resul t of check: Y=C ont ai ned, N=Not cont ai ned, PC HM
No. Co mp o n e n tNam e of Equi pm ent
Checklist (Step 3)
Not es

---CHUNK---

SOURCE: MEPC.197(62).pdf
Resul t of check: Y=C ont ai ned, N=Not cont ai ned, PC HM
No. Co mp o n e n tNam e of Equi pm ent
Checklist (Step 3)
Not es
A N A L Y S IS A N D D E F IN IT IO N O F S C O P E O F A S S E S S M E N T F O R " S A M P L E S H IP"
Res ul t
of
DOC * 2
Tbl
A/B
Pr ocedur e
of check
* 3
Res ul t
of check
* 4
Ref er ence/D W G No.
Ha z a r dou s

Ma t e r i a l s
*1
I nvent or y Par t I -1

RESOLUTION MEPC.197(62)
Adopted on 15 July 2011
2011 GUIDELINES FOR THE DEVELOPMENT OF THE INVENTORY
OF HAZARDOUS MATERIALSMEPC 62/24
Annex 3, page 34

I:\MEPC\62\24.doc
Before any visual/sampling check on board is conducted, a "visual/sampling check plan" should be prepared. An example of such a plan is shown below.

To prevent any incidents during the visual/sam pling check, a schedule should be established to eliminate interference with other ongoing work on board. To prevent potential exposure to Hazardous Materials during the visual/sampling check, safety precautions should be in place on board. For example, sampling of potential asbestos containing materials could release

---CHUNK---

SOURCE: MEPC.197(62).pdf