Hazardous Materials during the visual/sampling check, safety precautions should be in place on board. For example, sampling of potential asbestos containing materials could release fibres into the atmosphere. Therefore, appropriate personnel safety and containment procedures should be implemented prior to sampling.

Items listed in the visual/sampling check should be arranged in sequence so that the onboard check is conducted in a structured manner (e.g., from a lower level to an upper level and from a fore part to an aft part).

Example of visual/sampling check plan

Name of ship XXXXXXXXXX
IMO Number XXXXXXXXXX
Gross Tonnage 28,000 GT
L x B x D xxx.xx × xx.xx × xx.xx m
Date of delivery dd.mm.1987
Shipowner XXXXXXXXXX
Contact point
(Tel.,Fax, E-mail, address)
XXXXXXXXXX
Tel: XXXX-XXXX
Fax: XXXX-XXXX
E-mail: abcdefg@hijk.co.net
Check schedule Visual check dd, mm, 20XX
Sampling check dd, mm, 20XX
Site of check XX shipyard, No. Dock
In charge of check XXXX XXXX
Check engineer XXXX XXXX, YYYY YYYY, ZZZZ ZZZZ
Sampling engineer Person with specialized knowledge of sampling
Sampling method and anti-scattering
measure for asbestos

---CHUNK---

SOURCE: MEPC.197(62).pdf
Site of check XX shipyard, No. Dock
In charge of check XXXX XXXX
Check engineer XXXX XXXX, YYYY YYYY, ZZZZ ZZZZ
Sampling engineer Person with specialized knowledge of sampling
Sampling method and anti-scattering
measure for asbestos
Wet the sampling location prior to cutting and allow it
to harden after cutting to prevent scatter.
Notes: Workers performing sampling activities shall
wear protective equipment.
Sampling of fragments of paints Paints suspected to contain TBT should be collected
and analysed from load line, directly under bilge keel
and flat bottom near amidships.
Laboratory QQQQ QQQQ
Chemical analysis method Method by ISO/DIS 22262-1 Bulk materials--Part 1:
Sampling and qualitative determination of asbestos in
commercial bulk materials and ISO/CD 22262-2 Bulk
materials Part 2: Quantitative determination of
asbestos by gravimetric and microscopic methods.

ICP Luminous analysis (TBT)
Location of visual/sampling check Refe r to lists for visual/sampling check

RESOLUTION MEPC.197(62)
Adopted on 15 July 2011
2011 GUIDELINES FOR THE DEVELOPMENT OF THE INVENTORY
OF HAZARDOUS MATERIALSMEPC 62/24
Annex 3, page 35

I:\MEPC\62\24.doc

---CHUNK---

SOURCE: MEPC.197(62).pdf
RESOLUTION MEPC.197(62)
Adopted on 15 July 2011
2011 GUIDELINES FOR THE DEVELOPMENT OF THE INVENTORY
OF HAZARDOUS MATERIALSMEPC 62/24
Annex 3, page 35

I:\MEPC\62\24.doc
Listing for equipment, system and/or area for visual check
See attached "Analysis and definition of scope of investigation for sample ship"

List of equipment, system and/or area for sampling check
Location Equipment, machinery and/or zone Name of parts Materials Result of doc. checking
Upper Deck Back deck ceilings Engine-room
ceiling
Asbestos Unknown
Engine-room Exhaust gas pipe Insulation Asbestos Unknown
Engine-room Pipe/flange Gasket Asbestos Unknown

Refer to attached "Analysis and definition of scope of investigation for sample ship" and
"Location plan of Hazardous Materials for sample ship"

List of equipment, system and/or area classed as PCHM
Location Equipment, machinery and/or zone Name of part Material Result of doc. checking
Floor Propeller cap Gasket Asbestos PCHM
Engine-room Air operated shut-off
valve
Gland
packing
Asbestos PCHM

Refer to attached "Analysis and definition of scope of investigation for sample ship" and

---CHUNK---

SOURCE: MEPC.197(62).pdf
Floor Propeller cap Gasket Asbestos PCHM
Engine-room Air operated shut-off
valve

Gland
packing
Asbestos PCHM

Refer to attached "Analysis and definition of scope of investigation for sample ship" and "Location plan of Hazardous Materials for sample ship"

This plan is established in accordance with the Guidelines for the development of the Inventory of
Hazardous Materials

Document check date/place
dd, mm, 20XX at XX Lines Co. Ltd.

Preparation date of plan dd. mm, 20XX

Prepared by XXXX XXXX
Tel. YYYY-YYYY
E-Mail XXXX@ZZZZ.co.net
RESOLUTION MEPC.197(62)
Adopted on 15 July 2011
2011 GUIDELINES FOR THE DEVELOPMENT OF THE INVENTORY
OF HAZARDOUS MATERIALSMEPC 62/24
Annex 3, page 36

I:\MEPC\62\24.doc
5 Step 4: Onboard visual/sampling check

The visual/sampling check should be conducted according to the plan. Check points should be marked in the ship's plan or recorded with photographs.

A person taking samples should be protected by the appropriate safety equipment relevant to

---CHUNK---

SOURCE: MEPC.197(62).pdf
The visual/sampling check should be conducted according to the plan. Check points should be marked in the ship's plan or recorded with photographs.

A person taking samples should be protected by the appropriate safety equipment relevant to the suspected type of hazardous materials encountered. Appropriate safety precautions should also be in place for passengers, crewmembers and other persons on board, to minimize the potential exposure to hazardous materials. Safety precautions could include the posting of signs or other verbal or written notification for personnel to avoid such areas during sampling. The personnel taking samples should ensure compliance with relevant national regulations.

The results of visual/sampling checks should be recorded in the checklist. Any equipment,

systems and/or areas of the ship that cannot be accessed for checks should be classified as "potentially containing Hazardous Material". In this case, the entry in the "Result of check" column should be "PCHM".

6 Step 5: Preparation of Part I of the Inventory and related documentation

6.1 Development of Part I of the Inventory

---CHUNK---

SOURCE: MEPC.197(62).pdf
"potentially containing Hazardous Material". In this case, the entry in the "Result of check" column should be "PCHM".

6 Step 5: Preparation of Part I of the Inventory and related documentation

6.1 Development of Part I of the Inventory

The results of the check and the estimated quantity of Hazardous Materials should be recorded on the checklist. Part I of the Inventory should be developed with reference to the checklist.

6.2 Development of location diagram of Hazardous Materials