SOURCE: MEPC.269(68).pdf
1.3-1 Asbestos Engine-room ceiling Accommodation
plan

When a component or coating is determined to contain hazardous materials, a "Y" should be entered in the column for "Result of document analysis" in the checklist, to denote "Contained". Likewise, when an item is determined not to contain Hazardous Materials, the entry "N" should be made in the column to denote "Not contained". When a determination cannot be made as to the hazardous materials content, the column should be completed with the entry "Unknown".
RESOLUTION MEPC.269(68)
(adopted on 15 May 2015)
2015 GUIDELINES FOR THE DEVELOPMENT OF THE
INVENTORY OF HAZARDOUS MATERIALSMEPC 68/21/Add.1
Annex 17, page 35

https://edocs.imo.org/Final Documents/English/MEPC 68-21-ADD.1 (E).doc

RESOLUTION MEPC.269(68)
(adopted on 15 May 2015)
2015 GUIDELINES FOR THE DEVELOPMENT OF THE
INVENTORY OF HAZARDOUS MATERIALSMEPC 68/21/Add.1
Annex 17, page 36

https://edocs.imo.org/Final Documents/English/MEPC 68-21-ADD.1 (E).doc
4 STEP 3 PREPARATION OF VISUAL/SAMPLING CHECK PLAN

4.1 Each item classified as "Contained" or "Not contained" in step 2 should be subjected

---CHUNK---

SOURCE: MEPC.269(68).pdf
Annex 17, page 36

https://edocs.imo.org/Final Documents/English/MEPC 68-21-ADD.1 (E).doc
4 STEP 3 PREPARATION OF VISUAL/SAMPLING CHECK PLAN

4.1 Each item classified as "Contained" or "Not contained" in step 2 should be subjected to a visual check on board, and the entry "V" should be made in the "Check procedure" column to denote "Visual check".

4.2 For each item categorized as "unknown", a decision should be made as to whether to apply a sampling check. However, any item categorized as "unknown" may be classed as "potentially containing hazardous material" provided comprehensive justification is given, or if it can be assumed that there will be little or no effect on disassembly as a unit and later ship

recycling and disposal operations. For example, in the following checklist, in order to carry out a sampling check for "Packing with aux. boiler" the shipowner needs to disassemble the auxiliary boiler in a repair yard. The costs of this check are significantly higher than the later disposal costs at a ship recycling facility. In this case, therefore, the classification as "potentially containing hazardous material" is justifiable.

---CHUNK---

SOURCE: MEPC.269(68).pdf
disposal costs at a ship recycling facility. In this case, therefore, the classification as "potentially containing hazardous material" is justifiable.

RESOLUTION MEPC.269(68)
(adopted on 15 May 2015)
2015 GUIDELINES FOR THE DEVELOPMENT OF THE
INVENTORY OF HAZARDOUS MATERIALSMEPC 68/21/Add.1

4.3 Before any visual/sampling check on board is conducted, a "visual/sampling check plan" should be prepared. An example of such a plan is shown below.

4.4 To prevent any incidents during the visual/sampling check, a schedule should be established to eliminate interference with other ongoing work on board. To prevent potential exposure to Hazardous Materials during the visual/sampling check, safety precautions should be in place on board. For example, sampling of potential asbestos containing

---CHUNK---

SOURCE: MEPC.269(68).pdf
exposure to Hazardous Materials during the visual/sampling check, safety precautions should be in place on board. For example, sampling of potential asbestos containing materials could release fibres into the atmosphere. Therefore, appropriate personnel safety and containment procedures should be implemented prior to sampling.

4.5 Items listed in the visual/sampling check should be arranged in sequence so that the onboard check is conducted in a structured manner (e.g. from a lower level to an upper level

and from a fore part to an aft part).

Example of visual/sampling check plan

Name of ship XXXXXXXXXX
IMO Number XXXXXXXXXX
Gross Tonnage 28,000 GT
L x B x D xxx.xx × xx.xx × xx.xx m
Date of delivery dd.mm.1987
Shipowner XXXXXXXXXX
Contact point
(Address, Telephone, Fax, Email)
XXXXXXXXXX
Tel: XXXX-XXXX
Fax: XXXX-XXXX
Email: abcdefg@hijk.co.net
Check schedule Visual check dd, mm, 20XX
Sampling check dd, mm, 20XX
Site of check XX shipyard, No. Dock
In charge of check XXXX XXXX
Check engineer XXXX XXXX, YYYY YYYY, ZZZZ ZZZZ
Sampling engineer Person with specialized knowledge of sampling
Sampling method and anti-scattering
measure for asbestos

---CHUNK---

SOURCE: MEPC.269(68).pdf
Site of check XX shipyard, No. Dock
In charge of check XXXX XXXX
Check engineer XXXX XXXX, YYYY YYYY, ZZZZ ZZZZ
Sampling engineer Person with specialized knowledge of sampling
Sampling method and anti-scattering
measure for asbestos
Wet the sampling location prior to cutting and allow it
to harden after cutting to prevent scatter.
Notes: Workers performing sampling activities shall
wear protective equipment.
Sampling of fragments of paints Paints suspected to contain TBT should be collected
and analysed from load line, directly under bilge keel
and flat bottom near amidships.
Laboratory QQQQ QQQQ
Chemical analysis method Method by ISO/DIS 22262-1 Bulk materials Part 1:
Sampling and qualitative determination of asbestos in
commercial bulk materials and ISO/CD 22262-2 Bulk
materials Part 2: Quantitative determination of
asbestos by gravimetric and microscopic methods.
ICP Luminous analysis (TBT)
Location of visual/sampling check Refer to lists for visual/sampling check

RESOLUTION MEPC.269(68)
(adopted on 15 May 2015)
2015 GUIDELINES FOR THE DEVELOPMENT OF THE
INVENTORY OF HAZARDOUS MATERIALSMEPC 68/21/Add.1

---CHUNK---

SOURCE: MEPC.269(68).pdf
Location of visual/sampling check Refer to lists for visual/sampling check

RESOLUTION MEPC.269(68)
(adopted on 15 May 2015)
2015 GUIDELINES FOR THE DEVELOPMENT OF THE
INVENTORY OF HAZARDOUS MATERIALSMEPC 68/21/Add.1
Annex 17, page 39

https://edocs.imo.org/Final Documents/English/MEPC 68-21-ADD.1 (E).doc
Listing for equipment, system and/or area for visual check
See attached "Analysis and definition of scope of investigation for sample ship"

List of equipment, system and/or area for sampling check
Location
Equipment,
machinery and/or
zone