Name of
parts Materials
Result of
doc.
checking
Upper Deck Back deck ceilings Engine-room
ceiling
Asbestos Unknown
Engine-room Exhaust gas pipe Insulation Asbestos Unknown
Engine-room Pipe/flange Gasket Asbestos Unknown

Refer to attached "Analysis and definition of scope of investigation for sample ship" and "Location plan of hazardous materials for sample ship"

List of equipment, system and/or area classed as PCHM
Location
Equipment,
machinery and/or
zone
Name of part Material
Result of
doc.
checking
Floor Propeller cap Gasket Asbestos PCHM
Engine-room Air operated shut-off
valve

---CHUNK---

SOURCE: MEPC.269(68).pdf
List of equipment, system and/or area classed as PCHM
Location
Equipment,
machinery and/or
zone
Name of part Material
Result of
doc.
checking
Floor Propeller cap Gasket Asbestos PCHM
Engine-room Air operated shut-off
valve
Gland
packing
Asbestos PCHM

Refer to attached "Analysis and definition of scope of investigation for sample ship" and "Location plan of hazardous materials for sample ship"

This plan is established in accordance with the guidelines for the development of the Inventory of Hazardous Materials

Document checkdate/place
dd, mm, 20XX at XX Lines Co. Ltd.

Preparation date of plandd. mm, 20XX

Prepared by XXXX XXXX
Tel. YYYY-YYYY
Email XXXX@ZZZZ.co.net
RESOLUTION MEPC.269(68)
(adopted on 15 May 2015)
2015 GUIDELINES FOR THE DEVELOPMENT OF THE
INVENTORY OF HAZARDOUS MATERIALSMEPC 68/21/Add.1
Annex 17, page 40

https://edocs.imo.org/Final Documents/English/MEPC 68-21-ADD.1 (E).doc
5 STEP 4 ONBOARD VISUAL/SAMPLING CHECK

5.1 The visual/sampling check should be conducted according to the plan. Check points

---CHUNK---

SOURCE: MEPC.269(68).pdf
Annex 17, page 40

https://edocs.imo.org/Final Documents/English/MEPC 68-21-ADD.1 (E).doc
5 STEP 4 ONBOARD VISUAL/SAMPLING CHECK

5.1 The visual/sampling check should be conducted according to the plan. Check points
should be marked in the ship's plan or recorded with photographs.

5.2 A person taking samples should be protected by the appropriate safety equipment relevant to the suspected type of hazardous materials encountered. Appropriate safety precautions should also be in place for passengers, crewmembers and other persons on board, to minimize the potential exposure to hazardous materials. Safety precautions could include the posting of signs or other verbal or written notification for personnel to avoid such areas during sampling. The personnel taking samples should ensure compliance with relevant national regulations.

5.3 The results of visual/sampling checks should be recorded in the checklist. Any equipment, systems and/or areas of the ship that cannot be accessed for checks should be classified as "potentially containing hazardous material". In this case, the entry in the "Result of check" column should be "PCHM".

---CHUNK---

SOURCE: MEPC.269(68).pdf
equipment, systems and/or areas of the ship that cannot be accessed for checks should be classified as "potentially containing hazardous material". In this case, the entry in the "Result of check" column should be "PCHM".

6 STEP 5 PREPARATION OF PART I OF THE INVENTORY AND RELATED DOCUMENTATION

6.1 Development of part I of the Inventory

The results of the check and the estimated quantity of hazardous materials should be recorded on the checklist. Part I of the Inventory should be developed with reference to the checklist.

6.2 Development of location diagram of hazardous materials

With respect to part I of the Inventory, the development of a location diagram of hazardous materials is recommended in order to help the ship recycling facility gain a visual understanding of the Inventory.

---CHUNK---

SOURCE: MEPC.269(68).pdf
INVENTORY OF HAZARDOUS MATERIALSMEPC 68/21/Add.1
Annex 17, page 41

https://edocs.imo.org/Final Documents/English/MEPC 68-21-ADD.1 (E).doc

Example of the Inventory for existing ships

Inventory of Hazardous Materials for "Sample Ship"

Particulars of the "Sample Ship"

Distinctive number or letters XXXXNNN
Port of registry Port of World
Type of vessel Bulk carrier
Gross Tonnage 28,000 GT
IMO number NNNNNNN
Name of shipbuilder xx Shipbuilding Co. Ltd
Name of shipowner yy Maritime SA
Date of delivery MM/DD/1988

This inventory was developed in accordance with the guidelines for the development of the Inventory of Hazardous Materials.

Attachment:

1: Inventory of Hazardous Materials

2: Assessment of collected information

3: Location diagram of Hazardous Materials