17 The location of a part II or part III item should be entered in order based on its location, from a lower level to an upper level and from a fore part to an aft part. The location of
part I items is recommended to be described similarly, as far as practicable.
RESOLUTION MEPC.379(80) (adopted on 7 July 2023)
2023 GUIDELINES FOR THE DEVELOPMENT OF THE INVENTORY OF HAZARDOUS MATERIALS MEPC 80/17/Add.1
Annex 18, page 22

I:\MEPC\80\MEPC 80-17-Add.1.docx
APPENDIX 3

EXAMPLE OF THE DEVELOPMENT PROCESS FOR PART I
OF THE INVENTORY FOR NEW SHIPS

1 OBJECTIVE OF THE TYPICAL EXAMPLE

This example has been developed to give guidance and to facilitate understanding of the development process for part I of the Inventory of Hazardous Materials for new ships.

2 DEVELOPMENT FLOW FOR PART I OF THE INVENTORY

Part I of the Inventory should be developed using the following three steps. However, the order

---CHUNK---

SOURCE: MEPC.379(80).pdf
development process for part I of the Inventory of Hazardous Materials for new ships.

2 DEVELOPMENT FLOW FOR PART I OF THE INVENTORY

Part I of the Inventory should be developed using the following three steps. However, the order
of these steps is flexible and can be changed depending on the schedule of shipbuilding:

.1 collection of hazardous materials information;
.2 utilization of hazardous materials information; and
.3 preparation of the Inventory (by filling out standard format).

3 COLLECTION OF HAZARDOUS MATERIALS INFORMATION

3.1 Data-collection process for hazardous materials

Materials Declaration (MD) and Supplier's Declaration of Conformity (SDoC) for products from suppliers (tier 1 suppliers) should be requested and collected by the shipbuilding yard. Tier 1 suppliers may request from their suppliers (tier 2 suppliers) the r elevant information if they cannot develop the MD based on the information available. Thus the collection of data on hazardous materials may involve the entire shipbuilding supply chain (figure 1).

Figure 1 Process of MD (and SDoC) collection showing involvement of supply chain

Request

Submit

---CHUNK---

SOURCE: MEPC.379(80).pdf
hazardous materials may involve the entire shipbuilding supply chain (figure 1).

Figure 1 Process of MD (and SDoC) collection showing involvement of supply chain

Request

Submit

Equipment
supplier
(tier 2)

Shipbuilder
List
List
Request
MD

MD

MD
MD
MD
MD
MD

MD
MD
Equipment
supplier
(tier 1)

Submit

3.2 Declaration of hazardous materials

Suppliers should declare whether or not the hazardous materials listed in table A and table B in the MD are present in concentrations above the threshold values specified for each homogeneous material in a product.

3.2.1 Materials listed in table A

If one or more materials listed in table A are found to be present in concentrations above the specified threshold value according to the MD, the products which contain these materials shall not be installed on a ship. However, if the materials are used in a product in accordance with

---CHUNK---

SOURCE: MEPC.379(80).pdf
specified threshold value according to the MD, the products which contain these materials shall not be installed on a ship. However, if the materials are used in a product in accordance with an exemption specified by the Convention (e.g. new installations containing hydrochlorofluorocarbons (HCFCs) before 1 January 2020), the product should be listed in the Inventory.

3.2.2 Materials listed in table B

If one or more materials listed in table B are found to be present in concentrations above the specified threshold value according to the MD, the products should be listed in the Inventory.

3.3 Example of homogeneous materials

Figure 2 shows an example of four homogeneous materials which constitute a cable. In this case, sheath, intervention, insulator and conductor are all individual homogeneous materials.

Figure 2 Example of homogeneous materials (cable)

4 UTILIZATION OF HAZARDOUS MATERIALS INFORMATION

Products which contain hazardous materials in concentrations above the specified threshold values should be clearly identified in the MD. The approximate quantity of the hazardous

---CHUNK---

SOURCE: MEPC.379(80).pdf
4 UTILIZATION OF HAZARDOUS MATERIALS INFORMATION

Products which contain hazardous materials in concentrations above the specified threshold values should be clearly identified in the MD. The approximate quantity of the hazardous

materials should be calculated if the mass data for hazardous materials are declared in the MD using a unit which cannot be directly utilized in the Inventory.

5 PREPARATION OF INVENTORY (BY FILLING OUT STANDARD FORMAT)

The information received for the Inventory, as contained in table A and table B of appendix 1 of these guidelines, ought to be structured and utilized according to the following categorization for part I of the Inventory:

Part I-1 Paints and coating systems;

Part I-2 Equipment and machinery; and

Part I-3 Structure and hull.

Sheath
(PVC)
Intervention
(paper)
Insulator
(rubber)
Conductor
(copper)