installations and other equipment as referred to in 1.5.2.1 to ensure that they comply with the requirements of the Code, are

---CHUNK---

SOURCE: MSC.36(63).pdf
inspection of the structure, including the outside of the craft's bottom and related items, safety equipment, radio installations and other equipment as referred to in 1.5.2.1 to ensure that they comply with the requirements of the Code, are in satisfactory condition and are fit for the service for which the craft is intended. The inspection of the craft's bottom should be conducted with the craft out of the water under suitable conditions for close-up examination of any damaged or problem areas; and

.3 an additional survey, either general or partial according to the circumstances, should be made after a repair resulting from investigations prescribed in 1.7.3, or wherever any important repairs or renewals are made. The survey should be such as to ensure that the necessary repairs or renewals have been effectively made, that the material and workmanship of such repairs or renewals are in all respects satisfactory, and that the craft complies in all respects with the requirements of the Code.

The periodical surveys referred to in 1.5.1.3 should be endorsed on the High Speed Craft Safety Certificate.

The inspection and survey of the craft, so far as regards the

---CHUNK---

SOURCE: MSC.36(63).pdf
the craft complies in all respects with the requirements of the Code.

The periodical surveys referred to in 1.5.1.3 should be endorsed on the High Speed Craft Safety Certificate.

The inspection and survey of the craft, so far as regards the enforcement of the provisions of the Code, should be carried out by officers of the Administration. The Administration may, however, entrust the inspections and surveys either to surveyors nominated for the purpose or to organizations recognized by it.

An Administration nominating surveyors or recogn1z1ng organizations to conduct inspections and surveys as set forth in 1.5.4 should, as a minimum, empower any nominated surveyor or recognized organization to:

.1 require repairs to a craft; and

.2 carry out inspections and surveys if requested by the appropriate authorities of a port State.

The Administration should notify the Organization of the specific responsibilities and conditions of the authority delegated to nominated surveyors or recognized organizations.

When a nominated surveyor or recognized organization determines that the condition of the craft or its equipment does not correspond

---CHUNK---

SOURCE: MSC.36(63).pdf
responsibilities and conditions of the authority delegated to
nominated surveyors or recognized organizations.
When a nominated surveyor or recognized organization determines that
the condition of the craft or its equipment does not correspond
substantially with the particulars of the certificate or is such
that the craft is not fit to operate without danger to the craft or
persons on board, such surveyor or organization should immediately
ensure that corrective action is taken and should, in due course,
notify the Administration. If such corrective action is not taken
the certificate should be withdrawn and the Administration should be
W/1576n/pp/EWP
RESOLUTION MSC.36(63)
(adopted on 20 May 1994)
ADOPTION OF THE INTERNATIONAL CODE OF SAFETY
FOR HIGH SPEED CRAFT MSC 63/23/Add.2
ANNEX 18
Page 20
1.5.7
notified immediately; and, if the craft is in an area under the
jurisdiction of another Government, the appropriate authorities of
the port State should be notified immediately. When an officer of
the Administration, a nominated surveyor or recognized organization
has notified the appropriate authorities of the port State, the

---CHUNK---

SOURCE: MSC.36(63).pdf
the port State should be notified immediately. When an officer of
the Administration, a nominated surveyor or recognized organization
has notified the appropriate authorities of the port State, the
Government of the port State concerned should give such officer,
surveyor or organization any necessary assistance to carry out their
obligations under this section. When applicable, the Government of
the port State concerned should ensure that the craft should not
continue to operate until it can do so without danger to the craft
or the persons on board.
In every case, the Administration should fully guarantee the
completeness and efficiency of the inspection and survey, and should
undertake to ensure the necessary arrangements to satisfy this
obligation.
1.6 Approyals
The owner of a craft should accept the obligation to supply
sufficient information to enable the Administration to fully assess
the features of the design. It is strongly recommended that the
owner and Administration and, where appropriate, the port State or
States, commence discussions at the earliest possible stage so that
the Administration may fully evaluate the design in determining what

---CHUNK---

SOURCE: MSC.36(63).pdf
owner and Administration and, where appropriate, the port State or

States, commence discussions at the earliest possible stage so that the Administration may fully evaluate the design in determining what additional or alternative requirements should be applied to the craft to achieve the required level of safety.

1.7 Maintenance of conditions afte r survey

1.7.1 The condition of the craft and its equipment should be maintained to conform with the provisions of this Code to ensure that the craft in all respects will remain fit to operate without danger to the craft or the persons on board.

1.7.2 After any survey of the craft under 1.5 has been completed, no change should be made to structure, equipment, fittings, arrangements and materials covered by the survey, without the sanction of the Administration.

1.7.3 Whenever an accident occurs to a craft or a defect is discovered, either of which affects the safety of the craft or the efficiency or completeness of structure, equipment, fittings, arrangements and materials, the person in charge or owner of the craft should report at the earliest opportunity to the Administration, the nominated

---CHUNK---

SOURCE: MSC.36(63).pdf

completeness of structure, equipment, fittings, arrangements and materials, the person in charge or owner of the craft should report at the earliest opportunity to the Administration, the nominated surveyor or recognized organization responsible, who should cause investigations to be initiated to determine whether a survey, as required by 1.5, is necessary. If the craft is in an area under the jurisdiction of another Government, the person in charge or the owner should also report immediately to the appropriate authorities of the port State and the nominated surveyor or recognized organization should ascertain that such a report has been made.

1.8 High Speed Craft Safety Certificate

1.8.1 A certificate called a High Speed Craft Safety Certificate is issued after completion of an initial or renewal survey to a craft which complies with the requirements of the Code. The certificate should be issued or endorsed either by the Administration or by any person

---CHUNK---

SOURCE: MSC.36(63).pdf

after completion of an initial or renewal survey to a craft which complies with the requirements of the Code. The certificate should be issued or endorsed either by the Administration or by any person or organization recognized by it. In every case, that Administration assumes full responsibility for the certificate.

1.8.2 A Contracting Government to the Convention may, at the request of

the Administration, cause a craft to be surveyed and, if satisfied that the requirements of the Code are complied with, should issue or authorize the issue of a certificate to the craft and, where appropriate, endorse or authorize the endorsement of a certificate on the craft in accordance with the Code. Any certificate so issued should contain a statement to the effect that it has been issued at the request of the Government of the State the flag of which the craft is entitled to fly, and it should have the same force and receive the same recognition as a certificate issued under 1.8.1.
1.8.3
1.8.4
1.8.5
1.8.6
1.8.7
1.8.8
1.8.9
The certificate should be that of the model given in annex 1 to the Code. If the language used is neither English nor French, the text

---CHUNK---

SOURCE: MSC.36(63).pdf
1.8.3