ceases to be valid until such deficiencies are corrected or
otherwise resolved.
1.9.5 The provisions of 1.8 should apply to the issue and the period of
validity of the Permit to Operate High Speed Craft.
1.9.6 The Permit to Operate High Speed Craft should be that of the model
given in annex 2 to this Code. If the language used is neither
English nor French, the text should include a translation into one
of these languages.
1.10 Control

---CHUNK---

SOURCE: MSC.36(63).pdf
1.9.6 The Permit to Operate High Speed Craft should be that of the model
given in annex 2 to this Code. If the language used is neither
English nor French, the text should include a translation into one
of these languages.
1.10 Control
The prov~s~ons of regulation I/19 of the Convention should
be applied to include the Permit to Operate High Speed Craft
in addition to the certificate issued under 1.8.
1.11 Equivalents
1.11.1 Where this Code requires that a particular fitting, material,
appliance or apparatus, or type thereof, should be fitted or carried
in a craft, or that any particular provision should be made, the
Administration may allow any other fitting, material, appliance or
apparatus, or type thereof, to be fitted or carried, or any other
provision to be made in that craft, if it is satisfied by trial
thereof or otherwise that such fitting, material, appliance or
apparatus, or type thereof, or provision, is at least as effective
as that required by this Code.
W/1576n/pp/EWP
RESOLUTION MSC.36(63)
(adopted on 20 May 1994)
ADOPTION OF THE INTERNATIONAL CODE OF SAFETY
FOR HIGH SPEED CRAFT MSC 63/23/Add.2
ANNEX 18
Page 24

---CHUNK---

SOURCE: MSC.36(63).pdf
as that required by this Code.
W/1576n/pp/EWP
RESOLUTION MSC.36(63)
(adopted on 20 May 1994)
ADOPTION OF THE INTERNATIONAL CODE OF SAFETY
FOR HIGH SPEED CRAFT MSC 63/23/Add.2
ANNEX 18
Page 24
1.11.2 Where compliance with any of the requirements of this Code would
be impractical for the particular designs of the craft, the
Administration may substitute those with alternative requirements
provided that equivalent safety is achieved. The Administration

which allows any such substitution should communicate to the Organization particulars of these substitutions and the reasons therefor, which the Organization should circulate to its Member Governments for their information.

1.12 Information to be made available

1.12.1 The Administration should ensure that the management of the company operating the craft has provided the craft with adequate information and guidance in the form of manuals to enable the craft to be operated and maintained safely. These manuals should include a route operational manual, craft operating manual, maintenance manual and servicing schedule. Such information should be updated as necessary.

---CHUNK---

SOURCE: MSC.36(63).pdf

operated and maintained safely. These manuals should include a route operational manual, craft operating manual, maintenance manual and servicing schedule. Such information should be updated as necessary.

1.12.2 The manuals should contain at least the information specified in chapter 18 and should be in a language understood by the crew. Where this language is not English, a translation into English should be provided of at least the route operational manual and the craft operating manual.

1.13 Further developments

1.13.1 It is recognized that there is much ongoing research and development in the design of high speed craft and that new types may emerge which have different geometry to that envisaged during the formulation of this Code. It is important that this Code does not restrict this progress and the development of new designs.

1.13.2 A design may be produced which cannot comply with the provisions of this Code. In such a case the Administration should determine the extent to which the provisions of the Code are applicable to the design and, if necessary, develop additional or alternative requirements to provide an equivalent level of safety for the craft.

---CHUNK---

SOURCE: MSC.36(63).pdf

extent to which the provisions of the Code are applicable to the design and, if necessary, develop additional or alternative requirements to provide an equivalent level of safety for the craft.

1.13.3 The foregoing should be considered by the Administration when assessing the granting of equivalents under the Code.

1.14 Circulation of safety information

1.14.1 In the event that an Administration has cause to investigate an accident involving a craft to which this Code applies, that Administration should provide a copy of the official report to the Organization, which will invite Member States to note the existence of the report and to obtain a copy.

1.14.2 In the event that operational experience reveals structural or equipment failures affecting the safety of a design, craft owners should inform the Administration.

W/1576n/pp/EWP
RESOLUTION MSC.36(63)
(adopted on 20 May 1994)
ADOPTION OF THE INTERNATIONAL CODE OF SAFETY
FOR HIGH SPEED CRAFT 1.15 Reyiew of the Code
MSC 63/23/Add.2
ANNEX 18
Page 25
1.15.1 The Code should be reviewed by the Organization at intervals preferably not exceeding four years to consider revision of existing

---CHUNK---

SOURCE: MSC.36(63).pdf
FOR HIGH SPEED CRAFT 1.15 Reyiew of the Code
MSC 63/23/Add.2
ANNEX 18
Page 25
1.15.1 The Code should be reviewed by the Organization at intervals preferably not exceeding four years to consider revision of existing
requirements to take account of new developments in design and technology.
1.15.2 Where a new development in design and technology has been found acceptable to an Administration, that Administration may submit particulars of such development to the Organization for consideration for incorporation into the Code during periodical review.
W/1576n/pp/EWP
RESOLUTION MSC.36(63)
(adopted on 20 May 1994)
ADOPTION OF THE INTERNATIONAL CODE OF SAFETY
FOR HIGH SPEED CRAFT MSC 63/23/Add.2
ANNEX 18
Page 26
CHAPTER 2 - BUOYANCY, STABILITY AND SUBDIVISION
PART A - GENERAL
2.1 General
2.1.1 A craft should be provided with:
2.1. 2
2.1. 3
.1 stability characteristics and stabilization systems adequate for safety when the craft is operated in the non-displacement mode and during the transient mode;
.2 buoyancy and stability characteristics adequate for safety where the craft is operated in the displacement mode, both in

---CHUNK---

SOURCE: MSC.36(63).pdf
for safety when the craft is operated in the non-displacement mode and during the transient mode;
.2 buoyancy and stability characteristics adequate for safety where the craft is operated in the displacement mode, both in
the intact condition and the damaged condition; and

.3 stability characteristics in the non-displacement and transient modes adequate to transfer the craft safely to displacement mode in case of any system malfunction.

Account should be take n of the effect of icing in the stability calculations. An example for established practice for ice accretion allowances is given in annex 5 for the guidance of Administrations.

For the purpose of this and other chapters, unless expressly defined otherwise, the following definitions apply:

. 1 "Down flooding point" means any opening through which flooding of the spaces which comprise the reserve buoyancy could take place while the craft is in the intact or damaged condition, and heels to an angle past the angle of equilibrium .

. 2 "Fully submerged foil" means a foil having no lift components piercing the surface of the water in the foil borne mode .

---CHUNK---

SOURCE: MSC.36(63).pdf

place while the craft is in the intact or damaged condition, and heels to an angle past the angle of equilibrium .

. 2 "Fully submerged foil" means a foil having no lift components piercing the surface of the water in the foil borne mode .

. 3 "Multihull craft" means a craft which in any normally