in the accommodation not regularly occupied, such as toilets, stairway enclosures and corridors should be provided with an approved automatic smoke detection system and manually operated call points to indicate at the control station the location of outbreak of a fire in all normal operating conditions of the installations. Main propulsion machinery room(s) should in addition have detectors sensing other than smoke and be supervised by TV cameras monitored from the operating compartment. Manually operated call points should be installed throughout the accommodation spaces, service spaces and, where necessary, control stations. One manually operated call point should be located at each exit from these spaces and from areas of major fire hazard.

7.7.2 The fixed fire detection and fire alarm systems should comply with the following requirements.

7.7.2.1 General requirements

.1 Any required fixed fire detection and fire alarm system with manually operated call points should be capable of immediate operation at all times .

. 2 Power supplies and electric circuits necessary for the operation of the system should be monitored for loss of power

---CHUNK---

SOURCE: MSC.36(63).pdf

manually operated call points should be capable of immediate operation at all times .

. 2 Power supplies and electric circuits necessary for the operation of the system should be monitored for loss of power or fault conditions as appropriate. Occurrence of a fault condition should initiate a visual and audible fault signal

at the control panel which should be distinct from a fire signal

. 3 There should be not less than two sources of power supply for the electrical equipment used in the operation of the fixed fire detection and fire alarm systems, one of which should be an emergency source. The supply should be provided by separate feeders reserved solely for that purpose. Such feeders should run to an automatic change-over switch situated in or adjacent to the control panel for the fire detection system

. 4 Detectors and manually operated call points should be grouped into sections. The activation of any detector or manually operated call point should initiate a visual and audible fire

---CHUNK---

SOURCE: MSC.36(63).pdf

system
. 4 Detectors and manually operated call points should be grouped into sections. The activation of any detector or manually operated call point should initiate a visual and audible fire signal at the control panel and indicating units. If the signals have not received attention within two minutes an audible alarm should be automatically sounded throughout the crew accommodation and service spaces, control stations and machinery spaces. This alarm sounder system need not be an integral part of the fire detection system .
. 5 The control panel should be located in the operating compartment or in the main fire control station .
. 6 Indicating units should, as a minimum, denote the section in which a detector or manually operated call point has operated. At least one unit should be so located that it is easily accessible to responsible members of the crew at all times, when at sea or in port, except when the craft is out of service. One indicating unit should be located in the operating compartment if the control panel is located in the space other than the operating compartment .
. 7 Clear information should be displayed on or adjacent to each

---CHUNK---

SOURCE: MSC.36(63).pdf
of service. One indicating unit should be located in the operating compartment if the control panel is located in the space other than the operating compartment .
. 7 Clear information should be displayed on or adjacent to each indicating unit about the spaces covered and the location of the sections .
 8 Where the fire detection system does not include means of remotely identifying each detector individually, no section covering more than one deck within accommodation spaces, service spaces and control stations should normally be permitted except a section which covers an enclosed stairway. In order to avoid delay in identifying the source of fire, the number of enclosed spaces included in each section should be limited as determined by the Administration. In no case should more than 50 enclosed spaces be permitted in any section. If the detection system is fitted with remotely and individually identifiable fire detectors, the sections may cover several decks and serve any number of enclosed spaces .
. 9 In passenger craft, if there is no fire detection system capable of remotely and individually identifying each

---CHUNK---

SOURCE: MSC.36(63).pdf
individually identifiable fire detectors, the sections may cover several decks and serve any number of enclosed spaces .
. 9 In passenger craft, if there is no fire detection system capable of remotely and individually identifying each detector, a section of detectors should not serve spaces on

both sides of the craft nor on more than one deck and neither should it be situated in more than one zone according to
W/1576n/pp/EWP
RESOLUTION MSC.36(63)
(adopted on 20 May 1994)
ADOPTION OF THE INTERNATIONAL CODE OF SAFETY FOR HIGH SPEED CRAFT MSC 63/23/Add.2
ANNEX 18
Page 67
7.11.1 except that the Administration, if it is satisfied that the protection of the craft against fire will not thereby be reduced, may permit such a section of detectors to serve both sides of the craft and more than one deck. In passenger craft fitted with individually identifiable fire detectors, a section may serve spaces on both sides of the craft and on several decks .
10 A section of fire detectors which covers a control station, a service space or an accommodation space, should not include a maChinery space of major fire hazard .

---CHUNK---

SOURCE: MSC.36(63).pdf
section may serve spaces on both sides of the craft and on several decks .
10 A section of fire detectors which covers a control station, a service space or an accommodation space, should not include a maChinery space of major fire hazard .
11 Detectors should be operated by heat, smoke or other products of combustion, flame, or any combination of these factors. Detectors operated by other factors indicative of incipient fires may be considered by the Administration provided that they are no less sensitive than such detectors. Flame detectors should only be used in addition to smoke or heat detectors .
12 Suitable instructions and component spares for testing and maintenance should be provided .
. 13 The function of the detection system should be periodically tested by means of equipment producing hot air at the appropriate temperature, or smoke or aerosol particles having the appropriate range of density or particle size, or other phenomena associated with incipient fires to which the detector is designed to respond. All detectors should be of a type such that they can be tested for correct operation and

---CHUNK---

SOURCE: MSC.36(63).pdf
the appropriate range of density or particle size, or other phenomena associated with incipient fires to which the detector is designed to respond. All detectors should be of a type such that they can be tested for correct operation and
restored to normal surveillance without the renewal of any component

14 The fire detection system should not be used for any other purpose, except that closing of fire doors and similar functions may be permitted at the control panel .

. 15 Fire detection systems with a zone address identification capability should be so arranged that:

W/1576n/pp/EWP

.1 a loop cannot be damaged at more than one point by a fire;

.2 means are provided to ensure that any fault (e.g., power break; short circuit; earth) occurring in the loop should not render the whole loop ineffective;

.3 all arrangements are made to enable the initial configuration of the system to be restored in the event of failure (electl 'ical, electronic, informatic); and

.4 the first initiated fire alarm should not prevent any other detector to initiate further fire alarms.

RESOLUTION MSC.36(63)

(adopted on 20 May 1994)

ADOPTION OF THE INTERNATIONAL CODE OF SAFETY

---CHUNK---