the VHF radio installation.
The reserve source of energy may be used to supply the electrical lighting required by 14.5.2.4.
Where a reserve source of energy consists of a rechargeable accumulator battery or batteries:
.1 a means of automatically charging such batteries should be provided which should be capable of recharging them to minimum capacity requirements within 10 h; and
.2 the capacity of the battery or batteries should be checked, using an appropriate method*, at intervals not exceeding 12 months, when the craft is not at sea.
The siting and installation of accumulator batteries which provide a reserve source of energy should be such as to ensure:
.1 the highest degree of service;
.2 a reasonable lifetime;
.3 reasonable safety;
* One method of checking the capacity of an accumulator battery is to fully discharge and recharge the battery, using normal operating current and period (e.g. 10 h). Assessment of the charge condition can be made at

---CHUNK---

SOURCE: MSC.36(63).pdf
.3 reasonable safety;
* One method of checking the capacity of an accumulator battery is to fully discharge and recharge the battery, using normal operating current and period (e.g. 10 h). Assessment of the charge condition can be made at any time, but it should be done without significant discharge of the battery when the craft is at sea.
W/1687n/pp/EWP
RESOLUTION MSC.36(63)
(adopted on 20 May 1994)
ADOPTION OF THE INTERNATIONAL CODE OF SAFETY FOR HIGH SPEED CRAFT MSC 62123/Add.2
ANNEX 18
Page 142
14.12.8
.4 that the battery temperatures remain within the manufacturer's specifications whether under charge or idle; and
.5 that when fully charged, the batteries will provide at least the minimum required hours of operation under all weather conditions.
If an uninterrupted input of information from the craft's navigational or other equipment to a radio installation required by this chapter is needed to ensure its proper performance, means should be provided to ensure the continuous supply of such information in the event of failure of the craft's main or emergency source of electrical power.
14.13 _Performance standards

---CHUNK---

SOURCE: MSC.36(63).pdf
should be provided to ensure the continuous supply of such

information in the event of failure of the craft's main or emergency source of electrical power.
14.13 _Performance standards
14.13.1 All equipment to which this chapter applies should be of a type approved by the Administration. Such equipment should conform to appropriate performance standards not inferior to those adopted by the Organization*.
Refer to the following resolutions adopted by the Assembly of the Organization:
.1 Resolution A.525(13): Performance standards for narrow-band direct-printing telegraph equipment for the reception of navigational and meteorological warnings and urgent information to ships .
. 2 Resolution A.694(17): General requirements for shipborne radio equipment forming part of the global maritime distress and safety system (GMDSS) and for electronic navigational aids .
. 3 Resolution A.698(17): Performance standards for ship earth stations capable of two-way communications and resolution A.570(14): Type approval of ship earth stations .
. 4 Resoluti~n A.609(15): Performance standards for shipborne VHF radio

---CHUNK---

SOURCE: MSC.36(63).pdf
. 3 Resolution A.698(17): Performance standards for ship earth stations capable of two-way communications and resolution A.570(14): Type approval of ship earth stations .
. 4 Resoluti~n A.609(15): Performance standards for shipborne VHF radio installations capable of voice communication and digital selective calling .
. 5 Resolution A.610(15): Performance standards for shipborne MF radio installations capable of voice communication and digital selective calling .
. 6 Resolution A.613(15): Performance standards for shipborne MF/HF radio installations capable of voice communication, narrow-band direct-printing and digital selective calling .
. 7 Resolution A.695(17): Performance standards for float-free satellite emergency position-indicating radio beacons (EPIRBs) operating on 406 MHz (see also Assembly resolution A.696(17): Type approval of satellite emergency position-indicating radio beacons (EPIRBs) operating in the COSPAS-SARSAT system).
W/1687n/pp/EWP
(
RESOLUTION MSC.36(63)
(adopted on 20 May 1994)
ADOPTION OF THE INTERNATIONAL CODE OF SAFETY FOR HIGH SPEED CRAFT (Footnote continued)
MSC 62/23/Add.2
ANNEX 18
Page 143

---CHUNK---

SOURCE: MSC.36(63).pdf

operating in the COSPAS-SARSAT system).
W/1687n/pp/EWP
(
RESOLUTION MSC.36(63)
(adopted on 20 May 1994)
ADOPTION OF THE INTERNATIONAL CODE OF SAFETY
FOR HIGH SPEED CRAFT (Footnote continued)
MSC 62/23/Add.2
ANNEX 18
Page 143
.8 Resolution A.697(17): Performance standards for survival craft radar transponders for use in search and rescue operations
. 9 Resolution A.612(15): Performance standards for float-free VHF emergency position-indicating radio beacons .
. 10 Resolution A.663(16): Performance standards for INMARSAT Standard-C ship earth stations capable of transmitting and rece~v~ng direct-printing communications and resolution A.570(14): Type approval of ship earth stations .
. 11 Resolution A.664(16): Performance standards for enhanced group call equipment .
. 12 Resolution A.661(16): Performance standards for float-free satellite emergency position-indicating radio beacons operating through the geostationary INMARSAT satellite system on 1.6 GHz
. 13 Resolution A.662(16): Performance standards for float-free release and activation arrangements for emergency radio equipment .
. 14 Resolution A.699(17): System performance standard for the

---CHUNK---

SOURCE: MSC.36(63).pdf
. 13 Resolution A.662(16): Performance standards for float-free release and activation arrangements for emergency radio equipment .
. 14 Resolution A.699(17): System performance standard for the promulgation and co-ordination of maritime safety information using high-frequency narrow-band direct-printing .
. 15 Resolution A.700(17): Performance standards for narrow-band direct-printing telegraph equipment for the reception of navigational and meteorological warnings and urgent information to ships (MSI) by HF.
W/1687n/pp/EWP
RESOLUTION MSC.36(63)
(adopted on 20 May 1994)
ADOPTION OF THE INTERNATIONAL CODE OF SAFETY
FOR HIGH SPEED CRAFT MSC 62/23/Add.2
ANNEX 18
Page 144
14.14
14.14.1
14.14.2
14.14.3
14.14.4
14.14.5
14 .14.6
14.14.1

14.14.8
Maint e nance requ irements
Equipment should be so designed that the main units can be replaced readily without elaborate recalibration or readjustment.
Where applicable, equipment should be so constructed and installed that it is readily accessible for inspection and on-board maintenance purposes.
Adequate information should be provided to enable the equipment

---CHUNK---

SOURCE: MSC.36(63).pdf
Where applicable, equipment should be so constructed and installed that it is readily accessible for inspection and on-board maintenance purposes.
Adequate information should be provided to enable the equipment to be properly operated and maintained, taking into account the recommendations of the Organization*.
Adequate tools and spares should be provided to enable equipment to be maintained .
The Administration should ensure that radio equipment required by this chapter is maintained to provide the availability of the functional requirements specified in 14.4 and to meet the