The vlew of the sea surface from the operatlng station, when the navigators are seated, should not be obscured by more than one craft length forward of the bow to 90° on either side irrespective of the craft's draught, trim and deck cargo.
The field of vision from the docking workstation, if remote from the operating station, should permit one navigator to safely manoeuvre the craft to a berth.
Operating compartment
The design and arrangement of the operating compartment, including location and layout of the individual workstations, should ensure

---CHUNK---

SOURCE: MSC.36(63).pdf
operating station, should permit one navigator to safely manoeuvre the craft to a berth.
Operating compartment
The design and arrangement of the operating compartment, including location and layout of the individual workstations, should ensure the required field of vision for each function.
The craft's operating compartment should not be used for purposes other than navigation, communications and other functions essential to the safe operation of the craft, its engines, passengers and cargo.
The operating compartment should be provided with an integrated operating station for command, navigation, manoeuvring and communication and so arranged that it can accommodate those persons required to navigate the craft safely.
The arrangement of equipment and means for navigation, manoeuvring, control, communication and other essential instruments should be located sufficiently close together to enable both the officer in charge and any assisting officer to receive all necessary information and to use the ~quipment and controls, as required, while they are seated. If necessary, the equipment and means serving these functions should be duplicated.

---CHUNK---

SOURCE: MSC.36(63).pdf
charge and any assisting officer to receive all necessary information and to use the ~quipment and controls, as required, while they are seated. If necessary, the equipment and means serving these functions should be duplicated.
If a separate workstation for supervision of engine performance is placed in the operating compartment, the location and use of this workstation should not interfere with the primary functions to be performed in the operating station.
The location of the radio equipment should not interfere with the primary navigational functions in the operating station.
The design and layout of the compartment from which the crew operate

the craft and the relative positions of the primary controls should be assessed against the essential operational manning level. Where minimum manning levels are proposed, the design and layout of the primary and communication controls should form an integrated operational and emergency control centre from which the craft can be controlled under all operational and emergency events by the operating crew without the necessity for any crew member to vacate the compartment.

---CHUNK---

SOURCE: MSC.36(63).pdf
operational and emergency control centre from which the craft can be controlled under all operational and emergency events by the operating crew without the necessity for any crew member to vacate the compartment.
The relative positions of the primary controls and the seats should be such that each operating crew member, with the seat suitably adjusted, and without prejudicing compliance with 15.2 can:
.1 without interference, produce full and unrestricted movement of each control both separately and with all practical combinations of movement of other controls; and
W/1681n/pp/EWP
RESOLUTION MSC.36(63)
(adopted on 20 May 1994)
ADOPTION OF THE INTERNATIONAL CODE OF SAFETY
FOR HIGH SPEED CRAFT MSC 62123/Add.2
ANNEX 18
Page 148
15.4.9
15.4.10
15.4.11
15.4.12
15.5
15.5.1
15.5.2
15.5.3
15.5.4
15.5.5
.2 at all work stations, exert adequate control forces for the operation to be performed.
When a seat at a station from which the craft may be operated has been adjusted so as to suit the occupant, subsequent change of seat position to operate any control should not be acceptable.
In craft where the Administration considers the provision of a

---CHUNK---

SOURCE: MSC.36(63).pdf
been adjusted so as to suit the occupant, subsequent change of seat position to operate any control should not be acceptable.
In craft where the Administration considers the provision of a
safety belt necessary for use by the operating crew, it should be possible for those operating crew members, with their safety belts

correctly worn, to comply with 15.4.4 except in respect of controls which it can be shown will only be required on very rare occasions -and which are not associated with the need for safety restraint.
The integrated operating station should contain equipment which provides relevant information to enable the officer in charge and any assisting officer to carry out navigational and safety functions safely and efficiently.
Adequate arrangements should be made to prevent passengers from distracting the attention of the operating crew.
Instruments and chart table
Instruments, instrument panels and controls should be permanently mounted in consoles or other appropriate places taking into account operation, maintenance and environmental conditions. However, this should not prevent the use of new control or display techniques,

---CHUNK---

SOURCE: MSC.36(63).pdf
mounted in consoles or other appropriate places taking into account operation, maintenance and environmental conditions. However, this should not prevent the use of new control or display techniques,
provided the facilities offered are not inferior to recognized standards.
All instruments should be logically grouped according to their functions. In order to reduce to a minimum the risk of confusion, instruments should not be rationalized by sharing functions or by interswitching.
Instruments required for use by any member of the operating crew should be plainly visible and easily read:
.1 with minimum practicable deviation from his normal seating position and line of vision; and
.2 with the minimum risk of confusion under all likely operating conditions.
Instruments essential for the safe operation of the craft should be clearly marked with any limitation if this information is not otherwise clearly presented to the operating crew. The instrument panels forming the emergency control for the launching of life rafts and the monitoring of the fire-fighting systems should be in separate and clearly defined positions within the operating area.

---CHUNK---

SOURCE: MSC.36(63).pdf
panels forming the emergency control for the launching of life rafts and the monitoring of the fire-fighting systems should be in separate and clearly defined positions within the operating area.
The instruments and controls should be provided with means for screening and dimming in order to minimize glare and reflections and prevent them being obscured by strong light.
W 11687 n/ppl EWP
RESOLUTION MSC.36(63)
(adopted on 20 May 1994)
ADOPTION OF THE INTERNATIONAL CODE OF SAFETY
FOR HIGH SPEED CRAFT 15.5.6

15.5.7
15.5.8
15.6
15.6.1
15.6.2
15.6.3
15.6.4
15.6.5
15.6.6
15.7
15.7.1
15.7.2

The surfaces of console tops and instruments snould have dark glare-free colours.

Instruments and displays, providing visual information to more than one person, should be located for easy viewing by all users concurrently. If this is not possible, the instrument or display should be duplicated.

If considered necessary by the Administration, the operating compartment should be provided with a suitable table for chart