II-l/31.2.S'"
II-l/49.3'"
Column 1, table 8.2
II-l/31.2.7*
Column 1, table ~.2
II-l/31.2.8*
Columns 1&3 table 8.2
II-l/31.2.9*
Column 1, table 8.1
II-1129.11*
Columns 1 & !3,
table 8.1
II-l/30.1*
Column 1, table 8.3
II-l/30.3*
RESOLUTION MSC.39(63)
(adopted on 19 May 1994)
ADOPTION OF AMENDMENTS TO THE CODE ON
ALARMS AND INDICATORS MSC 63/23/Add.l
ANNEX 23
Page 3
Add the following to Table 9.1.1 (continued) - Location: navigating bridge
Priority
P
P
P
P
P
P
p
IMO
Instrument
1989 ttODU
Code
8.5.7
8.5.8
8.5.9

---CHUNK---

SOURCE: MSC.39(63).pdf
ALARMS AND INDICATORS MSC 63/23/Add.l
ANNEX 23
Page 3
Add the following to Table 9.1.1 (continued) - Location: navigating bridge
Priority
P
P
P
P
P
P
p
IMO

Instrument
1989 ttODU
Code
8.5.7
8.5.8
8.5.9
8.7.1
8.7.3
9.7.1
9.8
Function
Propulsion machinery
remote control failure
Prope 11 er speed/
di rect ion/pitch
Low propulsion starting
air pressure
Fault requi ri ng attention
Alarm system normal
supply failure
Fire detection
system alarm
Gas detection and
alarm system
Type Notes
A,V Column 1, table 8.2
II-l/31.2.7*
MI Column 1, table 8.3
II-l/49.6*
A,V Column 1, table 8.2
II-l/49.7*
A,V Column 1, table 8.3,
I including 8.3.5.1, I
I 8.4.1,8.8.6 and 8.9 I
I II-l/51 . 1.3* I
I I
A,V I Column 2, table 8.3 I
I II-1/5l.2.2* I
I I
A,V I Column 2, table 8.1 I
I II-2/l3* I
I I
A,V I ! Column 2, table 8.1 I
I I
I I
I I
I I
5 Add the following to Table 9.1.2 - Location: machinery space/machinery
control room
I lMO
Priority I Instrument
I
I I 1989 HODU
I Code

I
P I 4.2.7
I
I
P I 4.5.2
I
I
I s I 5.3.12
I
I s I 5.5.7
I
I
Function
Machinery failure
pre-al arm
Manual overriding
of the automatic
control indicator

---CHUNK---

SOURCE: MSC.39(63).pdf
control room
I lMO
Priority I Instrument
I
I I 1989 HODU
I Code
I
P I 4.2.7
I
I
P I 4.5.2
I
I
I s I 5.3.12
I
I s I 5.5.7
I
I
Function
Machinery failure
pre-al arm
Manual overriding
of the automatic
control indicator
Emergency battery
discharge
Electrical distribution
system low insulation
1 evel
* Cross reference to SOLAS regulation
W!1649n/EWP
Type

A,V
I
I
A or
I
Notes
Column 3, table 8.1
Column 3, table 8.1
Column 3, table 8.1
11-1/42.5.3*
! Column 3, table 8.1
II-l/45.4.2*
RESOLUTION MSC.39(63)
(adopted on 19 May 1994)
ADOPTION OF AMENDMENTS TO THE CODE ON
ALARMS AND INDICATORS MSC 63/23/Add.l
ANNEX 23
Page 4
Add the following to Table 9.1.2 (continued)
- Location: machinery space/machinery control room
Priority
P
S