- entering the port of destination in the area covered by the system.

3.3.3 Crossing the Adriatic Sea

3.3.3.1 The ship shall send the position report to the closest shore based authority of the country the ship is leaving, which shall inform the maritime authority of the port of destination.

3.3.4 Special cases

.1 The ship which, sailing northwards or southwards, enters Sector 5 shall transmit the report to, alternatively, one of the competent authorities as per annex 2, according to where the ship is going to or coming from.

.2 The ship crossing southwards the la titude 40° 25.00 N and going out either of Sector 1 or of the area covered by the sy stem shall transmit an additional final

---CHUNK---

SOURCE: MSC.139(76).pdf
according to where the ship is going to or coming from.

.2 The ship crossing southwards the la titude 40° 25.00 N and going out either of Sector 1 or of the area covered by the sy stem shall transmit an additional final
position report to Brindisi Coast Guard.

3.4 Authorities to whom the reports should be sent

3.4.1 The ships participating in the system shall transmit by radio the report to the “shore-based authorities” as in annex 2.

4 INFORMATION TO BE PROVIDED TO PARTICIPATING SHIPS AND PROCEDURES TO BE FOLLOWED

4.1 The shore-based authority which receives the first report (01/FR) shall inform the maritime authority of the ship’s destination (if in the area covered by the system) and the other shore-based authorities in between, if any.

4.2 The competent shore-based authority of Sect or 5 (as per paragraph 3.3.4) which receives the position report from the ship entering the sector will also inform the other two shore-based authorities about the entrance of the above mentioned ship.

---CHUNK---

SOURCE: MSC.139(76).pdf
the position report from the ship entering the sector will also inform the other two shore-based authorities about the entrance of the above mentioned ship.

4.3 Once received a report, the ADRIATIC TRAFFIC competent authority will provide the

ship with:

- information on navigational conditions (s tatus of aids to navigation, presence of other ships and, if necessary, their position, etc.);
- information on weather conditions; and
- any other relevant information.

5 RADIOCOMMUNICATION REQUIRED FOR THE SYSTEM, FREQUENCIES ON WHICH REPORTS SHOULD BE TRANSMITTED AND INFORMATION TO BE REPORTED

5.1 ADRIATIC TRAFFIC will be based on VHF voice radiocommunications.

5.2 The call to the appropriate shore-based au thority shall be made on the VHF channel assigned to the sector in which the ship is located, as per annex 2.

5.3 However, ship which cannot use the frequencie s listed in the annex 2 in order to transmit the reports, should use, via coast station, any other available communication equipment (e.g. MF, HF or INMARSAT) on which communication might be established.

5.4 The language used for communication shall be English, using the IMO Standard Marine

---CHUNK---

SOURCE: MSC.139(76).pdf
(e.g. MF, HF or INMARSAT) on which communication might be established.

5.4 The language used for communication shall be English, using the IMO Standard Marine Communications Phrases, where necessary.

6 RULES AND REGULATIONS IN FORCE IN THE AREA OF THE SYSTEM

6.1 The International Regulations for Preventing Collisions at Sea (COLREGs) are applicable through the whole area covered by the system.

7 SHORE-BASED FACILITIES TO SUPPORT OPERATION OF THE SYSTEM

.1 Brindisi Coast Guard (Italy)
- telephone and telefax communication facilities;
- VHF communication equipment.

.2 MRCC Bar (Yugoslavia)
- telephone and telefax communication facilities;
- VHF, MF and HF communication equipment.

.3 MRCC Rijeka (Croatia)
- telephone and telefax communication facilities;

- VHF, MF, HF and INMARSAT-C communication equipment.

.4 MRSC Ancona (Italy)
- telephone and telefax communication facilities;
- VHF, MF and HF communication equipment.

.5 MRSC Venezia (Italy)
- telephone and telefax communication facilities;

---CHUNK---

SOURCE: MSC.139(76).pdf
.4 MRSC Ancona (Italy)
- telephone and telefax communication facilities;
- VHF, MF and HF communication equipment.

.5 MRSC Venezia (Italy)
- telephone and telefax communication facilities;
- VHF, MF and HF communication equipment.

.6 MRSC Trieste (Italy)
- telephone and telefax communication facilities;
- VHF, MF and HF communication equipment.

.7 MRCC Koper (Slovenia)
- telephone and telefax communication facilities;
- VHF communication equipment.

8 ALTERNATIVE COMMUNICATION IF THE COMMUNICATION FACILITIES OF THE SHORE BASED AUTHORITIES FAIL

8.1 ADRIATIC TRAFFIC is planned with a su fficient system redundancy to cope with normal equipment failure. Since that the system is based on the VHF voice communication, each shore based facility has got at least two VHF transmitters/receivers; in addition to that, in case of failing c ontacts by VHF, the shore based authorities can operate and be contacted through phone, fax, INMARSAT-C and MF/HF facilities. In order to ensure the continuous 24-hour activity, the shore based facilities have been located and manned with properly trained and dedicated personnel in the respective

---CHUNK---

SOURCE: MSC.139(76).pdf
order to ensure the continuous 24-hour activity, the shore based facilities have been located and manned with properly trained and dedicated personnel in the respective national MRCCs/MRSCs. Should a shore based authority suffer an irretrievable breakdown and call off itself from the system until the failure is repaired, it could be relieved by one of the adjacent shore based authorities.

9 MEASURES TO BE TAKEN IF A SHIP FAILS TO COMPLY WITH THE REQUIREMENTS OF THE SYSTEM

9.1 The primary objective of the system is to s upport the safe navigation and the protection of the marine environment through the exchange of information between the ship and the shore. If a ship does not submit reports and can be positively identified, then information

will be passed to the competent Flag Stat e authorities for investigation and possible prosecution in accordance with national legisl ation. Information will be passed also to Port State Control inspectors.

I:\MSC\76\23-ADD.1.DOC
ANNEX 1

RESOLUTION MSC.139(76)
(adopted on 5 December 2002)

---CHUNK---

SOURCE: MSC.139(76).pdf
RESOLUTION MSC.139(76)