should be in a written format based on the information in annex 4A. The survey should not commence until the survey programme has been agreed.
5.1.1.1 Prior to the development of the survey programme, the survey planning questionnaire should be completed by the owner based on the information set out in annex 4B, and forwarded to the Administration."
18 The seven subitems in paragraph 5.1.2 are numbered from ".1" to ".7" and the eleven subitems in paragraph 5.1.3 are numbered from ".1" to ".II".
19 Paragraph 5.1.4 is deleted and paragraphs 5.1.5 and 5.1.6 are renumbered as 5.1.4 and 5.1.5.
20 The following new paragraphs 5.2.1.1 to 5.2.1.3 are added:
"5.2.1.1 In order to enable the attending surveyors to carry out the survey, provisions for proper and safe access should be agreed between the owner and the Administration.

---CHUNK---

SOURCE: MSC.197(80).pdf
20 The following new paragraphs 5.2.1.1 to 5.2.1.3 are added:
"5.2.1.1 In order to enable the attending surveyors to carry out the survey, provisions for proper and safe access should be agreed between the owner and the Administration.
5.2.1.2 Details of the means of access should be provided in the survey planning questionnaire.
5.2.1.3 In cases where the provisions of safety and required access are judged by the attending surveyors not to be adequate, the survey of the spaces involved should not proceed."
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 12 -
21 Existing paragraphs 5.2.2,5.2.3 and 5.2.4 are replaced by the following:
"5.2.2 Cargo holds, tanks and spaces should be safe for access. Cargo holds, tanks and spaces should be gas free and properly ventilated. Prior to entering a tank, void or enclosed space, it should be verified that the atmosphere in the tank is free from hazardous gas and contains sufficient oxygen.

---CHUNK---

SOURCE: MSC.197(80).pdf
spaces should be gas free and properly ventilated. Prior to entering a tank, void or enclosed space, it should be verified that the atmosphere in the tank is free from hazardous gas and contains sufficient oxygen.
5.2.3 Cargo holds, tanks and spaces should be sufficiently clean and free from water, scale, dirt, oil residues, sediments, etc., to reveal corrosion, deformation, fractures, damages or other structural deterioration as well as the condition of the coating. In particular this applies to areas which are subject to thickness measurement.
5.2.4 Sufficient illumination should be provided to reveal corrosion, deformation, fractures, damages or other structural deterioration as well as the condition of the coating."
22 The following new paragraphs 5.2.5 and 5.2.6 are added:
"5.2.5 The surveyor(s) should always be accompanied by at least one responsible person, assigned by the owner, experienced in tank and enclosed spaces inspection. In addition a back-up team of at least two experienced persons should be stationed at the hatch opening of the tank or space that is being surveyed. The back -up team should continuously

---CHUNK---

SOURCE: MSC.197(80).pdf
back-up team of at least two experienced persons should be stationed at the hatch opening of the tank or space that is being surveyed. The back -up team should continuously observe the work in the tank or space and should keep life-saving and evacuation equipment ready for use.
5.2.6 A communication system should be arranged between the survey party in the cargo hold, tank or space being examined, the responsible officer on deck and, as the case may be, the navigation bridge. The communication arrangements should be maintained throughout the survey."
23 In existing paragraph 5.3.2, a new subitem "portable ladders" is inserted between the third and fourth subitems.
24 The five subitems in paragraph 5.3.2 are numbered from ".1" to ".5" and the five subitems in paragraph 5.4.2 are numbered from ".1" to ".5".
25 New paragraphs 5.4.3 to 5.4.5 are added as follows:
"5.4.3 Explosimeter, oxygen-meter, breathing apparatus, lifelines, riding belts with rope and hook and whistles together with instructions and guidance on their use should be made available during the survey. A safety checklist should be provided.

---CHUNK---

SOURCE: MSC.197(80).pdf
and hook and whistles together with instructions and guidance on their use should be made available during the survey. A safety checklist should be provided.
5.4.4 Adequate and safe lighting should be provided for the safe and efficient conduct ofthe survey.
5.4.5 Adequate protective clothing should be made available and used (e.g. safety helmet, gloves, safety shoes, etc.) during the survey."
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 13 -
26 The existing paragraph 5.5.3 is replaced by the following:
"5.5.3 When rafts or boats will be used for close-up survey the following conditions should be observed:
.1 only rough duty, inflatable rafts or boats, having satisfactory residual buoyancy and stability even if one chamber is ruptured, should be used;
.2 the boat or raft should be tethered to the access ladder and an additional person should be stationed down the access ladder with a clear view of the boat or raft;
.3 appropriate lifejackets should be available for all participants;

---CHUNK---

SOURCE: MSC.197(80).pdf
.2 the boat or raft should be tethered to the access ladder and an additional person should be stationed down the access ladder with a clear view of the boat or raft;
.3 appropriate lifejackets should be available for all participants;
.4 the surface of water in the tank or hold should be calm (under all foreseeable conditions the expected rise of water within the tank should not exceed 0.25 m) and the water level either stationary or falling. On no

account should the level of the water be rising while the boat or raft is
III use;
.5 the tank, hold or space must contain clean ballast water only. Even a thin
sheen of oil on the water is not acceptable; and
.6 at no time should the water level be allowed to be within I m of the
deepest under-deck web face flat so that the survey team is not isolated
from a direct escape route to the tank hatch. Filling to levels above the
deck transverses should only be contemplated if a deck access manhole is
fitted and open in the bay being examined, so that an escape route for the
survey party is available at all times. Other effective means of escape to
the deck may be considered."

---CHUNK---

SOURCE: MSC.197(80).pdf
fitted and open in the bay being examined, so that an escape route for the
survey party is available at all times. Other effective means of escape to
the deck may be considered."
27 The following new paragraphs 5.5.4 to 5.5.6 are added:
"5.5.4 Rafts or boats alone may be allowed for inspection of the under-deck areas for
tanks or spaces, if the depth of the webs is 1.5 m or less.
5.5.5 If the depth of the webs is more than 1.5 m, rafts or boats alone may be allowed
only:
.I when the coating of the under-deck structure is in GOOD condition and
there is no evidence of wastage; or
.2 if a permanent means of access is provided in each bay to allow safe entry
and exit. This means of access should be direct from the deck via a
vertical ladder with a small platform fitted approximately 2 m below the
deck. Other effective means of escape to the deck may be considered.
If neither of the above conditions are met, then staging or other equivalent
means should be provided for the survey of the under-deck areas.
5.5.6 The use of rafts or boats alone in paragraphs 5.5.4 and 5.5.5 does not preclude the
use of boats or rafts to move about within a tank during a survey."

---CHUNK---

SOURCE: MSC.197(80).pdf
means should be provided for the survey of the under-deck areas.
5.5.6 The use of rafts or boats alone in paragraphs 5.5.4 and 5.5.5 does not preclude the
use of boats or rafts to move about within a tank during a survey."
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 14 -
28 The following new section 5.6 is added:
"5.6 Survey planning meeting
5.6.1 The establishment of proper preparation and the close co-operation between the
attending surveyor(s) and the owner's representatives onboard prior to and during the
survey are an essential part in the safe and efficient conduct of the survey. During the
survey on board safety meetings should be held regularly.
5.6.2 Prior to commencement of any part of the renewal and intermediate survey, a
survey planning meeting should be held between the attending surveyor(s), the owner's
representative in attendance, the thickness measurement company operator (as applicable)

and the master of the ship for the purpose to ascertain that all the arrangements envisaged

---CHUNK---

SOURCE: MSC.197(80).pdf
representative in attendance, the thickness measurement company operator (as applicable) and the master of the ship for the purpose to ascertain that all the arrangements envisaged in the survey programme are in place, so as to ensure the safe and efficient conduct of the survey work to be carried out.

5.6.3 The following is an indicative list of items that should be addressed 10 the meeting:

.1 schedule of the vessel (i.e. the voyage, docking and undocking manoeuvres, periods alongside, cargo and ballast operations, etc.);

.2 provisions and arrangements for thickness measurements (i.e. access, cleaning/de-scaling, illumination, ventilation, personal safety);

.3 extent of the thickness measurements ;

.4 acceptance criteria (refer to the list of minimum thicknesses);

.5 extent of close-up survey and thickness measurement considering the coating condition and suspect areas/areas of substantial corrosion;

.6 execution of thickness measurements;

.7 taking representative readings ill general and where uneven corrosion/pitting is found;

.8 mapping of areas of substantial corrosion; and