.9 communication between attending surveyor(s) the thickness measurement

---CHUNK---

SOURCE: MSC.197(80).pdf
.7 taking representative readings ill general and where uneven
corrosion/pitting is found;
.8 mapping of areas of substantial corrosion; and
.9 communication between attending surveyor(s) the thickness measurement
company operator(s) and owner representative(s) concerning findings."
29 The words "supply and maintain on-board" in paragraph 6.1.1 are replaced with "obtain,
supply and maintain on board the ship".
30 Paragraph 6.2.1.4 is deleted.
31 The word "inspection" in paragraph 6.4 is replaced with "survey".
32 The word "extend" in paragraph 7.1.3 is replaced with "extent".
33 The following new paragraph 8.2.2 is added after existing paragraph 8.2.1:
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 15 -
"8.2.2 When a survey is split between different survey stations, a report should be made
for each portion of the survey. A list of items examined andlor tested (pressure testing,
thickness measurements, etc.) and an indication of whether the item has been credited,

---CHUNK---

SOURCE: MSC.197(80).pdf
for each portion of the survey. A list of items examined andlor tested (pressure testing,
thickness measurements, etc.) and an indication of whether the item has been credited,
should be made available to the next attending surveyor(s), prior to continuing or
completing the survey."
34 The existing paragraph 8.2.2 is renumbered as 8.2.3.
35 The existing annex 4 is deleted.
36 The following new annex 4A is added after existing annex 3:
"ANNEX4A
SURVEY PROGRAMME
Basic information and particulars
Name of ship:
IMO number:
Flag State:
Port of registry :
Gross tonnage:
Deadweight (metric tonnes) :
Length between perpendiculars (m) :
Shipbuilder:
Hull number:
Recognized organization (RO) :
RO ship identity:
Date of delivery of the ship:
Owner:
Thickness measurement company:
1 Preamble
1.1 Scope

1.1.1 The present survey programme covers the minimum extent of overall surveys, close-up surveys, thickness measurements and pressure testing within the cargo length area, cargo holds, ballast tanks, including fore and aft peak tanks, required by the Guidelines.
1.1.2 The arrangements and safety aspects of the survey should be acceptable to the

---CHUNK---

SOURCE: MSC.197(80).pdf
area, cargo holds, ballast tanks, including fore and aft peak tanks, required by the Guidelines.
1.1.2 The arrangements and safety aspects of the survey should be acceptable to the attending surveyor(s).
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 16 -
1.2 Documentation
All documents used in the development of the survey programme should be available on board during the survey as required by section 6.
2 Arrangement of cargo holds, tanks and spaces
This section of the survey programme should provide information (either in the form of plans or text) on the arrangement of cargo holds, tanks and spaces that fall within the scope ofthe survey.
3 List of cargo holds, tanks and spaces with information on their use, extent of coatings and corrosion protection system
This section of the survey programme should indicate any changes relating to (and should update) the information on the use of the holds and tanks of the ship, the extent of coatings and the corrosion protective system provided in the Survey Planning

---CHUNK---

SOURCE: MSC.197(80).pdf
update) the information on the use of the holds and tanks of the ship, the extent of coatings and the corrosion protective system provided in the Survey Planning Questionnaire.
4 Conditions for survey
This section of the survey programme should provide information on the conditions for survey, e.g. information regarding cargo hold and tank cleaning, gas freeing, ventilation, lighting, etc.
5 Provisions and method of access to structures
This section of the survey programme should indicate any changes relating to (and should update) the information on the provisions and methods of access to structures provided in the Survey Planning Questionnaire.
6 List of equipment for survey
This section of the survey programme should identifY and list the equipment that will be made available for carrying out the survey and the required thickness measurements .
7 Survey requirements
7.1 Overall survey
This section of the survey programme should identifY and list the spaces that should undergo an overall survey for this ship in accordance with 2.4.1 and 2.5.1.
7.2 Close-up survey
This section of the survey programme should identify and list the hull structures that

---CHUNK---

SOURCE: MSC.197(80).pdf
undergo an overall survey for this ship in accordance with 2.4.1 and 2.5.1.
7.2 Close-up survey
This section of the survey programme should identify and list the hull structures that should undergo a close-up survey for this ship in accordance with 2.5.2.
8 Identification of tanks for tank testing
This section of the survey programme should identifY and list the cargo holds and tanks that should undergo tank testing for this ship in accordance with 2.7.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 17 -
9 Identification of areas and sections for thickness measurements
This section of the survey programme should identify and list the areas and sections where thickness measurements should be taken in accordance with 2.6.1.
10 Minimum thickness of hull structures
This section of the survey programme should specify the minimum thickness for hull structures of this ship that are subject to survey, according to (a) or (b):
(a) D Determined from the attached wastage allowance table and the original

---CHUNK---

SOURCE: MSC.197(80).pdf
This section of the survey programme should specify the minimum thickness for hull structures of this ship that are subject to survey, according to (a) or (b):
(a) D Determined from the attached wastage allowance table and the original thickness to the hull structure plans of the sbip ;
(b) D Given in the following table(s):

Area or location	Original as-built thickness (mm)	Minimum thickness (mm)	Substantial corrosion thickness (mm)
Deck			
Plating			
Longitudinals			
Longitudinal girders			
Cross deck olating			
Cross deck stiffeners			
Bottom			
Platin!!			
Lon"itudinals			
Longitudinal girders			
Inner bottom			
Plating			
Longitudinals			
Lon!!itudinal girders			
Floors			
Ship side in way of topside tanks			
Platin!!			

Lon!!itudinals
Ship side in way of hopper
side tanks
Platin!!
Longitudinals
Ship side in way of tanks
(if annJicable)
Platin!!
Longitudinals
Longitudinal stringers
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 18 -
Ship side in way of cargo
holds
Plating
Side frames webs
Side frames flanges
Upper brackets webs

---CHUNK---