SOURCE: MSC.197(80).pdf
required to be on board;
.4 information for planning of future surveys; and
.5 information which may be used as input for maintenance of classification rules and instructions.
1.3 When a survey is split between different survey stations, a report should be made for each portion of the survey. A list of items surveyed, relevant findings and an indication of whether the item has been credited, should be made available to the next attending surveyor, prior to continuing or completing the survey. Thickness measurement and tank testing carried out is also to be listed for the next surveyor.
2 Extent of the survey
2.1 Identification of compartments where an overall survey has been carried out.
2.2 Identification of locations, in each ballast tank and cargo hold including hatch covers and coamings, where a close-up survey has been carried out, together with information on the means of access used.
2.3 Identification of locations, in each ballast tank and cargo hold including hatch covers and coamings, where thickness measurement has been carried out.
Note: As a minimum, the identification of location of close-up survey and thickness

---CHUNK---

SOURCE: MSC.197(80).pdf
2.3 Identification of locations, in each ballast tank and cargo hold including hatch covers and coamings, where thickness measurement has been carried out.
Note: As a minimum, the identification of location of close-up survey and thickness measurement should include a confirmation with description of individual structural members corresponding to the extent of requirements stipulated in Annex A based on type of periodical survey and the ship's age.
Where only partial survey is required, i.e. 25% of shell frames, one transverse web, two selected cargo hold transverse bulkheads, the identification should include location within each ballast tank and cargo hold by reference to frame numbers.
2.4 For areas in ballast tanks and cargo holds where protective coating is found to be in good condition and the extent of close-up survey and/or thickness measurement has been specially considered, structures subject to special consideration should be identified.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 25 -

---CHUNK---

SOURCE: MSC.197(80).pdf
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 25 -
2.5 Identification of tanks subject to tank testing.
2.6 Identification of piping systems on deck and within cargo holds , ballast tanks , pipe tunnels, cofferdams and void spaces where:
.1 examination including internal examination of piping with valves and

fittings and thickness measurement , as relevant , has been carried out; and
.2 operational test to working pressure has been carried out.
3 Result of the survey
3.1 Type, extent and condition of protective coating in each tank , as relevant (rated GOOD , FAIR or POOR) including identification of tanks fitted with anodes.
3.2 Structural condition of each compartment with information on the following , as relevant:
.1 identification of findings , such as:
.1.1 corrosion with description of location, type and extent;
.1.2 areas with substantial corrosion;
.1.3 cracks /fractures with description oflocation and extent;
.1.4 buckling with description of location and extent; and

---CHUNK---

SOURCE: MSC.197(80).pdf
.1.1 corrosion with description of location, type and extent;
.1.2 areas with substantial corrosion;
.1.3 cracks /fractures with description oflocation and extent;
.1.4 buckling with description of location and extent; and
.1.5 indents with description of location and extent;
.2 identification of compartments where no structural damages /defects are found. The report may be supplemented by sketches/photos; and
.3 thickness measurement report should be verified and signed by the surveyor controlling the measurements on board.
4 Actions taken with respect to findings
4.1 Whenever the attending surveyor is of the opinion that repair s are required , each item to be repaired should be identified in a numbered list. Whenever repairs are carried out, details of the repairs effected should be reported by making specific reference to relevant items in the numbered list.
4.2 Repairs carried out should be reported with identification of:
.1 compartment;
.2 structural member;
.3 repair method (i.e. renewal or modification) , including:
.3.1 steel grades and scantlings (if different from the original);
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)

---CHUNK---

SOURCE: MSC.197(80).pdf
.1 compartment;
.2 structural member;
.3 repair method (i.e. renewal or modification) , including:
.3.1 steel grades and scantlings (if different from the original);
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 26-
.3.2 sketches/photos, as appropriate;
.4 repair extent; and
.5 non-destructive test (NDT)/tests.
4.3 For repairs not completed at the time of survey, condition of

class/recommendation should be imposed with a specific time limit for the repairs. In order to provide correct and proper information to the surveyor attending for survey of the repairs, condition of class/recommendation should be sufficiently detailed with identification of each item to be repaired. For identification of extensive repairs, reference may be made to the survey report."
39 Table 1 and table 2 in appendix 3 of Annex 8 are deleted and table 3 is renumbered as table I.
40 In paragraph I of annex 9, the words "the paragraph 5.1.6 of annex A" are replaced with "5.1.5".
41 The following new Annex 13 is added:
"ANNEX 13

---CHUNK---

SOURCE: MSC.197(80).pdf
table I.
40 In paragraph I of annex 9, the words "the paragraph 5.1.6 of annex A" are replaced with "5.1.5".
41 The following new Annex 13 is added:
"ANNEX 13
STRENGTH OF CARGO HATCH COVER SECURING ARRANGEMENTS FOR BULK CARRIERS
1 Securing devices
The strength of securing devices should comply with the following requirements:
.1 Panel hatch covers should be secured by appropriate devices (bolts, wedges or similar) suitably spaced alongside the coamings and between cover elements. Arrangement and spacing should be determined with due attention to the effectiveness for weathertightness, depending upon the type and the size of the hatch cover, as well as on the stiffness of the cover edges between the securing devices .
. 2 The net sectional area of each securing device is not to be less than:
where:
a - spacing between securing devices not to be taken less than 2 metres
f = (cry / 235)"
cry = specified minimum upper yield stress in N/mm2 of the steel used for fabrication, not to be taken greater than 70% of the ultimate tensile strength
e 0.75 for cry > 235
1.0 for cry :S 235
Rods or bolts should have a net diameter not less than 19 mm for

---CHUNK---

SOURCE: MSC.197(80).pdf
used for fabrication, not to be taken greater than 70% of the ultimate tensile strength
e 0.75 for cry > 235
1.0 for cry :S 235
Rods or bolts should have a net diameter not less than 19 mm for hatchways exceeding 5 m 2 in area.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED

.3 Between cover and coaming and at cross-joints, a packing line pressure sufficient to obtain weathertightness should be maintained by the securing devices. For packing line pressures exceeding 5 N/mm, the cross section area should be increased in direct proportion. The packing line pressure should be specified .
.4 The cover edge stiffness should be sufficient to maintain adequate sealing pressure between securing devices. The moment of inertia, I, of edge elements be less than:
where:
p packing line pressure in N/mm, minimum 5 N/mm
a = spacing in m of securing devices
.5 Securing devices should be of reliable construction and securely attached to the hatchway coarnings, decks or covers. Individual securing devices

---CHUNK---

SOURCE: MSC.197(80).pdf
where:
p packing line pressure in N/mm, minimum 5 N/mm
a = spacing in m of securing devices
.5 Securing devices should be of reliable construction and securely attached