the necessary assistance from the personnel on board. Necessary precautions and procedures for carrying out the survey should be in accordance with 5.1,5.2, 5.3 and 5.4.
5.5.2 A communication system should be arranged between the survey party in the tank and the responsible officer on deck. This system should also include the personnel in charge of ballast pump handling if boats or rafts are used.
5.5.3 Surveys of tanks by means of boats or rafts may only be undertaken with the agreement of the surveyor, who should take into account the safety arrangements provided, including weather forecasting and ship response in reasonable sea conditions.
5.5.4 When rafts or boats are used for close-up surveys, the following conditions should be observed:
.1 only rough duty, inflatable rafts or boats, having satisfactory residual buoyancy and stability even if one chamber is ruptured, should be used;
.2 the boat or raft should be tethered to the access ladder and an additional person should be stationed down the access ladder with a clear view of the

---CHUNK---

SOURCE: MSC.197(80).pdf
buoyancy and stability even if one chamber is ruptured, should be used;
.2 the boat or raft should be tethered to the access ladder and an additional person should be stationed down the access ladder with a clear view of the boat or raft;
.3 appropriate lifejackets should be available for all participants;
.4 the surface of water in the tank should be calm (under all foreseeable conditions the expected rise of water within the tank should not exceed 0.25 m) and the water level either stationary or falling. On no account should the level of the water be rising while the boat or raft is in use;
.5 the tank or space must contain clean ballast water only. Even a thin sheen of oil on the water is not acceptable;
.6 at no time should the water level be allowed to be within I m of the deepest under-deck web face flat so that the survey team is not isolated
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 40-
from a direct escape route to the tank hatch. Filling to levels above the

---CHUNK---

SOURCE: MSC.197(80).pdf
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 40-
from a direct escape route to the tank hatch. Filling to levels above the deck transverses should only be contemplated if a deck access manhole is fitted and open in the bay being examined, so that an escape route for the survey party is available at all times. Other effective means of escape to the deck may be considered;
.7 if the tanks (or spaces) are connected by a common venting system, or inert gas system, the tank in which the boat or raft should be used should be isolated to prevent a transfer of gas from other tanks (or spaces).
5.5.5 Rafts or boats alone may be allowed for inspection of the under-deck areas of

tanks or spaces if the depth of the webs is 1.5 m or less.
5.5.6 If the depth of the webs is more than 1.5 m, rafts or boats alone may be allowed only:
. I when the coating of the under-deck structure is in GOOD condition and there is no evidence of wastage; or
.2 if a permanent means of access is provided in each bay to allow safe entry

---CHUNK---

SOURCE: MSC.197(80).pdf
only:
. I when the coating of the under-deck structure is in GOOD condition and there is no evidence of wastage; or
.2 if a permanent means of access is provided in each bay to allow safe entry and exit. This means of access should be direct from the deck via a vertical ladder with a small platform fitted approximately 2 m below the deck. Other effective means of escape to the deck may be considered.
If neither of the above conditions are met, then staging or other equivalent means should be provided for the survey of the under-deck areas.
5.5.7 The use of rafts or boats alone in 5.5.5 and 5.5.6 does not preclude the use of boats or rafts to move about within a tank during a survey.
5.6 Survey planning meeting
5.6. I Proper preparation and close co-operation between the attending surveyor(s) and the owner's representatives on board prior to and during the survey are an essential part in the safe and efficient conduct of the survey. During the survey on board safety meetings should be held regularly.
5.6.2 Prior to commencement of any part of the renewal and intermediate survey, a

---CHUNK---

SOURCE: MSC.197(80).pdf
the safe and efficient conduct of the survey. During the survey on board safety meetings should be held regularly.
5.6.2 Prior to commencement of any part of the renewal and intermediate survey, a survey planning meeting should be held between the attending surveyor(s), the owner's representative in attendance, the thickness measurement company operator (as applicable) and the master of the ship for the purpose of ascertaining that all the arrangements envisaged in the survey programme are in place, so as to ensure the safe and efficient conduct of the survey work to be carried out.
5.6.3 The following is an indicative list of items that should be addressed III the meeting:
.I schedule of the vessel (i.e. the voyage, docking and undocking manoeuvres, periods alongside, cargo and ballast operations, etc.);
.2 provisions and arrangements for thickness measurements (i.e. access, cleaning/de-scaling, illumination, ventilation, personal safety);
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 41 -

---CHUNK---

SOURCE: MSC.197(80).pdf

RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 41 -
.3 extent of the thickness measurements;
.4 acceptance criteria (refer to the list of minimum thicknesses);
.5 extent of close-up survey and thickness measurement considering the
coating condition and suspect areas/areas of substantial corrosion;
.6 execution of thickness measurements;
.7 taking representative readings III general and where uneven
corrosion/pitting is found;
.8 mapping of areas of substantial corrosion; and
.9 communication between attending surveyor(s) the thickness measurement
company operator(s) and owner representative(s) concerning findings.
6 Documentation on board
6.1 General
6.1.1 The owner should obtain, supply and maintain on board the ship documentation
as specified in 6.2 and 6.3, which should be readily available for the surveyor. The
condition evaluation report referred to in 6.2 should include a translation into English.
6.1.2 The documentation should be kept on board for the lifetime of the ship.
6.2 Survey report file

---CHUNK---

SOURCE: MSC.197(80).pdf
condition evaluation report referred to in 6.2 should include a translation into English.
6.1.2 The documentation should be kept on board for the lifetime of the ship.
6.2 Survey report file
6.2.1 A survey report file should be a part of the documentation on board consisting of:
.1 reports of structural surveys (annex 8);
.2 condition evaluation report (annex 9); and
.3 thickness measurement reports (annex 10).
6.2.2 The survey report file should be available also III the owner's and the
Administration's offices.
6.3 Supporting documents
The following additional documentation should be available on board:
.1 all documents required by 5.1.2;
.2 survey programme as required by 5.1 until such time as the renewal
survey has been completed; and
.3 any other information that would help to identifY critical structural areas
and/or suspect areas requiring inspection.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 42-
6.4 Review of documentation on board

---CHUNK---

SOURCE: MSC.197(80).pdf
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)

AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 42-

6.4 Review of documentation on board

Prior to survey, the surveyor should examine the completeness of the documentation on board and its contents as a basis for the survey.

7 Procedures for thickness measurements

7.1 General

7.1.1 The required thickness m easurements, if not carried out by the recognized organization acting on behalf of the Administration, should be witnessed by a surveyor of the recognized organization. The surveyor should be on board to the extent necessary to control the process.

7.1.2 The thickness measurement company should be part of the survey planning meeting to be held prior to commencing the survey.

7. 1.3 In all cases the extent of the thickness measurements should be sufficient as to represent the actual average condition.

7.2 Certification of thickness measurement company

The thickness measurements should be carried out by a qualified company certified by an

---CHUNK---

SOURCE: MSC.197(80).pdf

represent the actual average condition.