7.2 Certification of thickness measurement company
The thickness measurements should be carried out by a qualified company certified by an organization recognized by the Administration according to principles stated in annex 7.
7.3 Reporting
7.3.1 A thickness measurement report should be prepared and submitted to the Administration. The report should give the location of measurements, the thickness measured as well as corresponding original thickness. Furthermore, the report should give the date when the measurements were carried out, type of measuring equipment, names of personnel and their qualifications and be signed by the operator. The thickness measurement report should follow the principles as specified in the recommended procedures for thickness measurements set out in annex 10.
7.3.2 The surveyor should verify and countersign the thickness measurement reports.
8 Reporting and evaluation of survey
8.1 Evaluation of survey report
8.1.1 The data and information on the structural condition of the ship collected during the survey should be evaluated for acceptability and continued structural integrity of the ship.

---CHUNK---

SOURCE: MSC.197(80).pdf
8.1 Evaluation of survey report
8.1.1 The data and information on the structural condition of the ship collected during the survey should be evaluated for acceptability and continued structural integrity of the ship.
8.1.2 In case of oil tankers of 130 m in length and upwards (as defined in the International Convention on Load Lines in force), the ship's longitudinal strength should be evaluated by using the thickness of structural members measured, renewed and reinforced, as appropriate, during the renewal survey of safety construction carried out after the ship reached 10 years of age, in accordance with the criteria for longitudinal strength ofthe ship's hull girder for oil tankers specified in annex 12.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 43 -
8.1.3 The analysis of data should be carried out and endorsed by the Administration and the conclusions of the analysis should form a part of the condition evaluation report.

---CHUNK---

SOURCE: MSC.197(80).pdf
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 43 -
8.1.3 The analysis of data should be carried out and endorsed by the Administration and the conclusions of the analysis should form a part of the condition evaluation report.
8.1.4 The final result of the evaluation of the ship's longitudinal strength required in 8.1.2, after renewal or reinforcement work of structural members, if carried out as a result of initial evaluation, should be reported as a part of the condition evaluation report.
8.2 Reporting
8.2.1 Principles for survey reporting are shown in annex 8.
8.2.2 When a survey is split between different survey stations, a report should be made for each portion of the survey. A list of items examined and/or tested (pressure testing, thickness measurements, etc.) and an indication of whether the item has been credited, should be made available to the next attending surveyor(s), prior to continuing or

completing the survey.
8.2.3 A condition evaluation report of the survey and results should be issued to the owner as shown in annex 9 and placed on board the ship for reference at future surveys.

---CHUNK---

SOURCE: MSC.197(80).pdf
completing the survey.
8.2.3 A condition evaluation report of the survey and results should be issued to the owner as shown in annex 9 and placed on board the ship for reference at future surveys. The condition evaluation report should be endorsed by the Administration.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 44-
ANNEX I
MINIMUM REQUIREMENTS FOR CLOSE -UP SURVEY AT RENEWAL SURVEY OF DOUBLE HULL OIL TANKERS
Age < 5 years 5<age < 10 years IO<age<15 years Age> 15 years
I 2 3 4
One web frame (I) , All web frames (I) , in All web frames (1), As for ships in a complete ballast a complet e ballast in all ballast tanks referred to in tank tank column 3
(see Note 1) (see Note I)
The knuckle area and the upper part (5 m approximately) of one transverse web frame in each Additional areas as deemed remaining ballast tank necessary by the
(6) Administration
One deck transverse, One deck transverse, All web frames (7), in a cargo oil tank (2) in two cargo oil tanks including deck
(2) transverse and cross

---CHUNK---

SOURCE: MSC.197(80).pdf
web frame in each as deemed remaining ballast tank necessary by the
(6) Administration
One deck transverse, One deck transverse, All web frames (7), in a cargo oil tank (2) in two cargo oil tanks including deck
(2) transverse and cross ties, if fitted , in a cargo oil tank
One web frame (7), including deck transverse and cross ties, if fitted, in each remaining cargo oil tank
One transverse One transverse All transverse bulkhead (4), in a bulkhead (4), in each bulkhead s, in all

complete ballast tank complete ballast tank cargo oil (3) and
(see Note 1) (see Note 1) ballast (4) tanks
One transverse One transverse
bulkhead (5) in a bulkhead (5), in two
cargo oil centre tank cargo oil centre tanks
One transverse One transverse
bulkhead (5), in a bulkhead (5), in a
cargo oil wing tank cargo oil wing tank
(see Note 2) (see Note 2)
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 45 -
NOTES:
(1), (2), (3), (4), (5), (6) and (7) are areas to be subjected to close-up surveys and thickness

---CHUNK---

SOURCE: MSC.197(80).pdf
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 45 -
NOTES:
(1), (2), (3), (4), (5), (6) and (7) are areas to be subjected to close-up surveys and thickness
measurements (see appendix 3 of annex 10).
(1) Web frame in a ballast tank means vertical web in side tank, hopper web in hopper tank, floor in double bottom tank and deck transverse in double deck tank (where fitted), including adjacent sttuctural members. In fore and aft peak tanks web frame means a complete transverse web frame ring including adjacent sttuctural members.
(2) Deck transverse, including adjacent deck structural members (or external sttucture on deck in way of the tank, where applicable).
(3) Transverse bulkhead complete in cargo tanks, including girder system, adjacent structural members (such as longitudinal bulkheads) and internal sttucture of lower and upper stools, where fitted.
(4) Transverse bulkhead complete in ballast tanks, including girder system and adjacent sttuctural members, such as longitudinal bulkheads, girders in double bottom tanks, inner bottom plating, hopper side, connecting brackets.

---CHUNK---

SOURCE: MSC.197(80).pdf
(4) Transverse bulkhead complete in ballast tanks, including girder system and adjacent sttuctural members, such as longitudinal bulkheads, girders in double bottom tanks, inner bottom plating, hopper side, connecting brackets.
(5) Transverse bulkhead lower part in cargo tank, including girder system, adjacent sttuctural members (such as longitudinal bulkheads) and internal sttucture of lower stool, where fitted.
(6) The knuckle area and the upper part (5 metres approximately), including adjacent structural members. Knuckle area is the area of the web frame around the connections of the slope hopper plating to the inner hull bulkhead and the inner bottom plating, up to 2 metres from the corners both on the bulkhead and the double bottom.
(7) Web frame in a cargo oil tank means deck transverse, longitudinal bulkhead vertical girder and cross ties, where fitted, including adjacent structural members.
Note 1 Complete ballast tank: means double bottom tank plus double side tank plus double

deck tank, as applicable, even if these tanks are separate.
Note 2 Where no centre cargo tanks are fitted (as in the case of centre longitudinal

---CHUNK---

SOURCE: MSC.197(80).pdf
Note 1 Complete ballast tank: means double bottom tank plus double side tank plus double deck tank, as applicable, even if these tanks are separate.
Note 2 Where no centre cargo tanks are fitted (as in the case of centre longitudinal bulkhead), transverse bulkheads in wing tanks should be surveyed.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 46-
ANNEX 2
MINIMUM REQUIREMENTS FOR THICKNESS MEASUREMENTS AT RENEWAL SURVEY OF DOUBLE HULL OIL TANKERS
Age<S years S<age< I 0 years IO<age< IS years Age> 15 years
I 2 3 4
One section of deck plating for the full beam of the ship Within the cargo area: each deck plate Within the cargo area: each deck plate Within the cargo area: each deck plate