A.P. Aftpeak
Under-deck
Side shell
~ ..., Bottom c
'" transverse -bll Longitudinal = ~ Transverse
Under-deck
.. Bottom ... ~
-..., transverse = = Ut! Transverse
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 61 -

---CHUNK---

SOURCE: MSC.197(80).pdf
-..., transverse = = Ut! Transverse
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 61 -
History of cargo with HzS content or heated cargo for the last 3 years together with indication as to whether cargo was heated and, where available, Marine Safety Data Sheets (MSDS)
Owner's inspections
Using a fonnat similar to th at of the table below (which is given as an example), the owner should provide details of the results of their inspections for the last 3 years on all cargo and ballast tanks and void spaces within the cargo area, including peak tanks.
Tank No. Corrosion Coating Coating Structural Tank damage
protection extent condition deterioration history
(1) (2) (3) (4) (5)
Cargo centre
tanks
Cargo wing
tanks
Slop
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 62-
Tank No. Corrosion Coating
protection extent
(1) (2)
Banast tanks
Aft peak
Fore peak

---CHUNK---

SOURCE: MSC.197(80).pdf
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS

AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 62-
Tank No. Corrosion Coating
protection extent
(1) (2)
Banast tanks
Aft peak
Fore peak
Miscellaneous
spaces
Note: Indicate tanks which are used for oillballast.
I) HC=hard coating; SC=soft coating;
A=anodes ; NP=no protection
2) U=upper part; M=middle part;
L=lower part; C=complete
3) G=good; F=fair; P=poor;
RC=recoated (during the last 3 years)
4) N=no findings recorded ; Y=findings
recorded , description of findings should
be attached to the questionnaire
5) DR=damage and repair ; L=leakage s;
CY= conversion (description should be
attached to this questionnaire)
Reports of Port State Control inspections
Coating Structural Tank damage
condition deterioration history
(3) (4) (5)
Name of owner's repre sentative :
Signature: ....
Date: ....
List the reports of Port State Control inspections containing hull structural-related
deficiencies and relevant information on rectification of the deficiencies:

---CHUNK---

SOURCE: MSC.197(80).pdf
Date: ....
List the reports of Port State Control inspections containing hull structural-related
deficiencies and relevant information on rectification of the deficiencies:
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 63 -
Safety Management System
List of non-conformities related to hull maintenance , including the associated corrective
actions:
Name and address of the approved thickness measurement company:
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 64-
ANNEX6C
OWNER'S INSPECTION REPORT

Structural condition
Ship's name: ....
For tank No.: ....
Grade of steel: deck: side: ....

---CHUNK---

SOURCE: MSC.197(80).pdf
Ship's name: ....
For tank No.: ....
Grade of steel: deck: side: ....
bottom: .... longitudinal bulkhead: ..... .
Coating Modifi-Elements Cracks Buckles Corrosion Pitting cation! Other condition repair
Deck
Bottom
Side
Longitudinal
bulkhead
Transverse
bulkhead
Repairs carried out due to:
Thickness measurements carried out (dates):
Results in general:
Overdue surveys:
Outstanding conditions of class:
Comments:
Date of inspection:
Inspected by:
Signature:
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 65 -
ANNEX 7
PROCEDURES FOR CERTIFICATION OF A COMPANY ENGAGED IN
THICKNESS MEASUREMENT OF HULL STRUCTURES
1 Application
This guidance applies for certification of the company which intends to engage in the thickness measurement of hull structures of ships.

---CHUNK---

SOURCE: MSC.197(80).pdf
PROCEDURES FOR CERTIFICATION OF A COMPANY ENGAGED IN
THICKNESS MEASUREMENT OF HULL STRUCTURES
1 Application
This guidance applies for certification of the company which intends to engage in the thickness measurement of hull structures of ships.
2 Procedures for certification
Submission of documents
2.1 The following documents should be submitted to an organization recognized by the Administration for approval:
.1 outline of the company, e.g. organization and management structure;

.2 experience of the company in thickness measurement of hull structures of ships;
.3 technicians' careers, i.e. experience of technicians as thickness measurement operators, technical knowledge and experience of hull structure, etc. Operators should be qualified according to a recognized industrial non-destructive test (NDT) standard;
.4 equipment used for thickness measurement such as ultrasonic testing machines and their maintenance/calibration procedures;
.5 a guide for thickness measurement operators;
.6 training programmes for technicians for thickness measurement; and
.7 measurement record format in accordance with recommended procedures

---CHUNK---

SOURCE: MSC.197(80).pdf
machines and their maintenance/calibration procedures;
.5 a guide for thickness measurement operators;
.6 training programmes for technicians for thickness measurement; and
.7 measurement record format in accordance with recommended procedures
for thickness measurements (see annex 10). Recommended procedures for thickness measurements of double hull oil tankers are contained in annex 2.
Auditing of the company
2.2 Upon satisfactory review of the documents submitted, the company should be