6. Keel plate 16. Horizontal girders in 26. Inner bottom 36. Cross ties
wing ballast tanks plating
17. Bottom girders 27. Inner bottom
longitudinals
18. Longitudinal 28. Topside tank
bulkhead top strake plating
19. Longitudinal 29. Topside tank
bulkhead bottom longitudinals
strake
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 93 -
Thickness measurement - Double hull oil tankers
Transverse section outline.
(The diagram may be used for those ships where typical sections are not applicable.)
Report on TM2-DHT Report on TM3-DHT Report on TM4-DHT
(i) and (ii)

---CHUNK---

SOURCE: MSC.197(80).pdf
Thickness measurement - Double hull oil tankers
Transverse section outline.
(The diagram may be used for those ships where typical sections are not applicable.)
Report on TM2-DHT Report on TM3-DHT Report on TM4-DHT
(i) and (ii)
O. Strength deck plating 10. Deck longitudinals 20. Longitudinal 30. Deck transverse -
bulkhead plating centre tank
(remainder)
1. Stringer plate II. Sheerstrake 21. Longitudinal 31. Deck transverse -
longitudinals bulkhead wing tank
longitudinals
2. Sheerstrake 12. Side shell 22. Inner side plating 32. Vertical web in
longitudinals wing ballast tank
3. Side shell plating 13. Bilge longitudinal s 23. Inner side 33. Double bottom
longitudinals floor - wing tank
4. Bilge plating 14. Bottom 24. Hopper plating 34. Double bottom
longitudinals floor - centre tank
5. Bottom shell plating 15. Deck girders 25. Hopper 35. Longitudinal
longitudinals bulkhead vertical
web
6. Keel plate 16. Horizontal girders 26. Inner bottom 36. Cross ties
in wing ballast plating
tanks
17. Bottom girders 27. Inner bottom
longitudinal s
18. Longitudinal 28. Topside tank
bulkhead top strake plating
19. Longitudinal 29. Topside tank
bulkhead bottom longitudinals

---CHUNK---

SOURCE: MSC.197(80).pdf
in wing ballast plating
tanks
17. Bottom girders 27. Inner bottom
longitudinal s
18. Longitudinal 28. Topside tank
bulkhead top strake plating
19. Longitudinal 29. Topside tank
bulkhead bottom longitudinals
strake
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 94-
Thickness measurement - double hull oil tankers
Areas subject to close-up survey and thickness measurements - areas (1) to (5) as
defined in annex 1- thickness to be reported on TM3-DHT, TM4-DHT and
TM5-DHT, as appropriate
r-- -,
: Close-up survey:
area 1.. __ _ _____ .J
~===- -=- -T-~~~~~~~ i'=:-- --, II (2)
, " , " , " 1 I (2) II----
: ,I I I L _ ____ _____ _ ____ .J
, , , , , , , , , , : , , , , , , , , , , , , , , , ,
: : , ,
: : , , , , , , , ,
:1---'", , : , : (1) ,
! , _____ ...I
\, .---------- - - - --- - - - - --- - - ---- ----- - -- ----- ----- ~
-------- iii
fr
,
"
,
"
,
"
, ,
"
, ,
"
, ,
"
, ,
"
, ,
"
, ,
"

---CHUNK---

SOURCE: MSC.197(80).pdf
: : , ,
: : , , , , , , , , ,
:1---'", , : , : (1) ,
! , _____ ...I
\, .---------- - - - --- - - - - --- - - ---- ----- - -- ----- ----- ~
-------- iii
fr

,
"

,
"

,
"

, ,
"

, ,
"

, ,
"

, ,
"

, ,
"

, ,
"
, , " , " , , II III , , , , , , : , , " , " , " , (3) " (3) , " , " , " , " , " , " , " -- - -- -, , iii' , ill : , III , Itl , , III (5) , , III , , ,
" III , , 1,\" ,,' , Id , , ',;,'.. __ -.-_-_____ ___) l;;::--:-:-:-:-:-;::-:-:-:-:::;:: . . = , , (4) , ,
:'\
, , , : '._----------
~
1= 1= 1= 1=
1== , 1= , ,
1= , , ,
~ , , , I--, - - - - -!ill
i ~ III III 11= III
1n1 (5) 11= III It--III , !lll 'J L --- - - ~ - - - - -
n ~
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 95 -
Areas subject to close-up survey and thickness measurements - areas (6) to (7) as
defined in annex 1 - thickness to be reported on TM3-DHT and TM4-DHT, as
appropriate
r- - --- -------.,
: Close-up survey:
area
L _____ .J

---CHUNK---

SOURCE: MSC.197(80).pdf
Areas subject to close-up survey and thickness measurements - areas (6) to (7) as defined in annex 1 - thickness to be reported on TM3-DHT and TM4-DHT, as appropriate
r- - --- -------.,
: Close-up survey:
area
L _____ .J
,- - - - - - - - - - - - - -- - - - - - - - - - - :;'Tn-T1T1l--q- TrrT"TIT"TT"rnrr-r" 1----' :
'®' , : 6: ® : " , ~ __ ------- _____ 1
, ,
--'~ , , , , , , ,
~
~. ' 6 , ' !.. _ _ .! _____ '"TTTT~rrrTTr+TT1""TT_,_,_TT1""TT-,A
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 96-
ANNEX 11
GUIDELINES FOR TECHNICAL ASSESSMENT IN CONJUNCTION WITH THE PLANNING OF ENHANCED SURVEYS FOR OIL TANKERS
Renewal survey