in paragraph 5.4.2 are numbered from ".1" to ".5".
74 New paragraphs 5.4.3 to 5.4.5 are added as follows:
"5.4.3 Explosimeter, oxygen-meter, breathing apparatus, lifelines, riding belts with rope and hook and whistles together with instructions and guidance on their use should be made available during the survey. A safety checklist should be provided.
5.4.4 Adequate and safe lighting should be provided for the safe and efficient conduct of the survey.

---CHUNK---

SOURCE: MSC.197(80).pdf
made available during the survey. A safety checklist should be provided.
5.4.4 Adequate and safe lighting should be provided for the safe and efficient conduct of the survey.
5.4.5 Adequate protective clothing should be made available and used (e.g., safety helmet, gloves, safety shoes, etc.) during the survey."
75 The existing paragraph 5.5.3 is deleted and the existing paragraph 5.5.4 is renumbered as 5.5.3.
76 The following new paragraphs 5.5.4 to 5.5.7 are added:
"5.5.4 When rafts or boats will be used for close-up survey, the following conditions should be observed:
.1 only rough duty, inflatable rafts or boats, having satisfactory residual buoyancy and stability even if one chamber is ruptured, should be used;
.2 the boat or raft should be tethered to the access ladder and an additional person should be stationed down the access ladder with a clear view of the boat or raft;
.3 appropriate lifejackets should be available for all participants;
.4 the surface of water in the tank should be calm (under all foreseeable conditions the expected rise of water within the tank should not exceed 0.25 m) and the water level either stationary or falling. On no

---CHUNK---

SOURCE: MSC.197(80).pdf
.4 the surface of water in the tank should be calm (under all foreseeable conditions the expected rise of water within the tank should not exceed 0.25 m) and the water level either stationary or falling. On no account should the level of the water be rising while the boat or raft is in use;
.5 the tank or space must contain clean ballast water only. Even a thin sheen of oil on the water is not acceptable;
.6 at no time should the water level be allowed to be within I m of the deepest under-deck web face flat so that the survey team is not isolated from a direct escape route to the tank hatch. Filling to levels above the deck transverses should only be contemplated if a deck access manhole is fitted and open in the bay being examined, so that an escape route for the

survey party is available at all times. Other effective means of escape to the deck may be considered;
.7 if the tanks (or spaces) are connected by a common venting system , or

---CHUNK---

SOURCE: MSC.197(80).pdf
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 112-
survey party is available at all times. Other effective means of escape to
the deck may be considered;
.7 if the tanks (or spaces) are connected by a common venting system , or
Inert Gas system, the tank in which the boat or raft should be used should
be isolated to prevent a transfer of gas from other tanks (or spaces).
5.5.5 Rafts or boats alone may be allowed for inspection of the under-deck areas for
tanks or spaces if the depth of the webs is 1.5 m or less.
5.5.6 If the depth of the webs is more than 1.5 m, rafts or boats alone may be allowed
only:
.1 when the coating of the under-deck structure is in GOOD condition and
there is no evidence of wastage; or
.2 if a permanent means of access is provided in each bay to allow safe entry
and exit. This means of access should be direct from the deck via a
vertical ladder with a small platform fitted approximately 2 m below the
deck. Other effective means of escape to the deck may be considered.
If neither of the above conditions are met, then staging or other equivalent means should
be provided for the survey ofthe under-deck areas.

---CHUNK---

SOURCE: MSC.197(80).pdf
deck. Other effective means of escape to the deck may be considered.
If neither of the above conditions are met, then staging or other equivalent means should
be provided for the survey ofthe under-deck areas.
5.5.7 The use of rafts or boats alone in 5.5.5 and 5.5.6 does not preclude the use of
boats or rafts to move about within a tank during a survey."
77 The following new section 5.6 is added:
"5.6 Survey planning meeting
5.6. I Proper preparation and close co-operation between the attending surveyor(s) and
the owner's representatives on board prior to and during the survey are an essential part in
the safe and efficient conduct of the survey. During the survey, on board safety meetings
should be held regularly.
5.6.2 Prior to commencement of any part of the renewal and intermediate survey, a
survey planning meeting should be held between the attending surveyor(s), the owner's
representative in attendance , the thickness measurement company operator (as applicable)
and the master of the ship for the purpose to ascertain that all the arrangements envisaged
in the survey programme are in place, so as to ensure the safe and efficient conduct of the

---CHUNK---

SOURCE: MSC.197(80).pdf
and the master of the ship for the purpose to ascertain that all the arrangements envisaged
in the survey programme are in place, so as to ensure the safe and efficient conduct of the
survey work to be carried out.
5.6.3 The following is an indicative list of items that should be addressed III the
meeting:
.I schedule of the vessel (i.e. the voyage , docking and undocking
manoeuvres, periods alongside , cargo and ballast operations, etc.);
.2 provisions and arrangements for thicknes s measurements (i.e. access,

cleaning /de-scaling , illumination, ventilation , personal safety);
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED
PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS
AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 113 -
.3 extent of the thickness measurements;
.4 acceptance criteria (refer to the list of minimum thicknesses);
.5 extent of close-up survey and thickness measurement considering the
coating condition and suspect areas/areas of substantial corrosion;
.6 execution of thickness measurements;
.7 taking representative readings III general and where uneven
corrosion/pitting is found;

---CHUNK---

SOURCE: MSC.197(80).pdf
coating condition and suspect areas/areas of substantial corrosion;
.6 execution of thickness measurements;
.7 taking representative readings III general and where uneven
corrosion/pitting is found;
.8 mapping of areas of substantial corrosion;
.9 communication between attending surveyor(s) the thickness measurement
company operator(s) and owner representative(s) concerning findings."
78 The words "supply and maintain on-board" in paragraph 6.1.1 are replaced with "obtain,
supply and maintain on board the ship".
79 Paragraph 6.2.1.4 is deleted.
80 The word "inspection" in paragraph 6.4 is replaced with "survey".
81 The word "extend" in paragraph 7.1.3 is replaced with "extent".
82 The following new paragraph 8.2.2 is added after existing paragraph 8.2.1:
"8.2.2 When a survey is split between different survey stations, a report should be made
for each portion of the survey. A list of items examined and/or tested (pressure testing,
thickness measurements, etc.) and an indication of whether the item has been credited,
should be made available to the next attending surveyor(s), prior to continuing or
completing the survey."

---CHUNK---

SOURCE: MSC.197(80).pdf
thickness measurements, etc.) and an indication of whether the item has been credited,
should be made available to the next attending surveyor(s), prior to continuing or
completing the survey."
83 The existing paragraph 8.2.2 is renumbered as 8.2.3.
84 In the third column of annex I, the words "One web frame rings in each remaining cargo
wing tank" are replaced with "A minimum of 30% of all web frame rings in each remaining
cargo wing tank (see Note 1)" and the words "One deck and bottom transverse in each cargo
centre tank" are replaced with "A minimum of 30% of deck and bottom transverses, including
adjacent structural members in each cargo centre tank (see Note 1)". A Note 1 is added at the
bottom of that annex as:
"Note I: The 30% should be rounded up to the next whole integer."
85 A new annex 6A "Survey programme" is added after existing annex 5. The text of the
annex is identical to annex 6A of Part A (see amendment no.43).
86 A new annex 6B is added after the new annex 6A. The text of the annex is identical to
annex 6B of Part A (see amendment no.43).

87 The existing annex 6 is deleted.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)

---CHUNK---

SOURCE: MSC.197(80).pdf
86 A new annex 6B is added after the new annex 6A. The text of the annex is identical to annex 6B of Part A (see amendment no.43).
87 The existing annex 6 is deleted.
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)
AMENDMENTS TO THE GUIDELINES ON THE ENHANCED PROGRAMME OF INSPECTIONS DURING SURVEYS OF BULK CARRIERS AND OIL TANKERS (RESOLUTION A.744(18), AS AMENDED)- 114-
88 The existing text of annex 8 is replaced by new text with the heading "Survey reporting principles". The new text is identical to the text of annex 8 of Part A (see amendment no.43).
89 Table I and table 2 in appendix 3 of annex 10 are deleted and table 3 is renumbered as table 1.
90 In paragraph I of annex 11, the words "paragraph 5.1.6 of annex B" are replaced by "5.1.5".
RESOLUTION MSC.197(80)
(adopted on 20 May 2005)