"the Inventory Guidelines").

The SRFP should describe how PCHMs will be treated; either:

they will be removed, stored and treated as Hazardous Materials in accordance with the requirements of the Convention; or

sampling and analysis will be conducted and PCHMs will be treated accordingly, based on the findings of sampling and analysis.

The basis of such a decision on how to treat PCHMs should be transparent and consistent as far as practicable. This information will need to be fully described in the Ship Recycling Plan.

3.4.2.2 Additional sampling and analysis

If, during the recycling process or in preparation for it, the Ship Recycling Facility deems it

---CHUNK---

SOURCE: MEPC.210(63).pdf
as far as practicable. This information will need to be fully described in the Ship Recycling Plan.

3.4.2.2 Additional sampling and analysis

If, during the recycling process or in preparation for it, the Ship Recycling Facility deems it necessary, sampling, analysis and/or visual inspection should be conducted, possibly with the cooperation of the shipowner, to enable the identification of Hazardous Materials.
A sampling plan should be developed describing the sampling locations, number of samples to be taken, the name of the sampler (including subcontractors) and the type of analysis to be performed.

When conducting the sampling of any possible Hazardous Materials, the samplers should be protected from exposure by the worker-safety measures required for the Hazardous Materials in question. Analysis of the samples should be performed by an accredited laboratory.

It is recommended that, in conducting additional sampling, the Ship Recycling Facility should follow the relevant part on sampling and analysis of the Inventory Guidelines.

After the sampling and analysis results are known, the Ship Recycling Facility should

---CHUNK---

SOURCE: MEPC.210(63).pdf
follow the relevant part on sampling and analysis of the Inventory Guidelines.

After the sampling and analysis results are known, the Ship Recycling Facility should manage the materials appropriately according to whether they have been found to be hazardous.

3.4.2.3 Identification, marking and labelling and potential onboard locations

The Ship Recycling Facility should utilize the information in the IHM for the purposes of

identifying the type, location and quantity of any Hazardous Materials and for marking and/or labelling. Asbestos, PCBs, other Hazardous Materials and ship tanks such as crude oil tank (COT), fuel oil tank (FOT), lubricating oil tank (LOT), fresh water tank (FWT) and water ballast tank (WBT) should be clearly marked in an easily identifiable manner.

It is recommended that the Ship Recycling Facility should ensure that it is fully aware of all the potential locations of Hazardous Materials on board ships. Examples of typical locations

---CHUNK---

SOURCE: MEPC.210(63).pdf

It is recommended that the Ship Recycling Facility should ensure that it is fully aware of all the potential locations of Hazardous Materials on board ships. Examples of typical locations for many of the Hazardous Materials are provided in section 2.2 ("Indicative List") of appendix 5 ("Example of the Development Process for Part I of the Inventory for Existing Ships") of the Inventory Guidelines.

3.4.2.4 Removal, handling and remediation

The SRFP should describe how to safely remove, handle and/or clean the Hazardous Materials that have been identified on the ship, taking account of their potential adverse effects on human health and/or the environment.

Removal of Hazardous Materials should only be conducted by appropriately trained personnel following the worker-safety measures required for the Hazardous Materials in question.

Whenever in use, the space where the removal work is occurring should be isolated from other work spaces and should be clearly marked to inform all persons of the hazards in the area.

After the removal of highly toxic, explosive or reactive Hazardous Materials, decontamination

---CHUNK---

SOURCE: MEPC.210(63).pdf
other work spaces and should be clearly marked to inform all persons of the hazards in the area.

After the removal of highly toxic, explosive or reactive Hazardous Materials, decontamination or remediation of the space should be performed by trained personnel.

Methods and procedures for the removal, handling and remediation of Hazardous Materials should be established to ensure safe and environmentally sound operations in accordance

with the applicable national requirements.

Pursuant to section 2.2 of the Supplement to the Document of Authorization to conduct Ship Recycling (DASR) (appendix 5 of the Convention), the SRFP should indicate the responsible personnel authorized to carry out removal of Hazardous Materials, with the certificate number or other relevant information, for each of the Hazardous Materials identified.

In the normal handling of all hazardous materials due attention should be paid to relevant occupational exposure limits.

3.4.2.5 Storage and labelling after removal

The SRFP should describe how all wastes generat ed from recycling activity will be kept

---CHUNK---

SOURCE: MEPC.210(63).pdf
occupational exposure limits.

3.4.2.5 Storage and labelling after removal

The SRFP should describe how all wastes generat ed from recycling activity will be kept separate from recyclable materials and equipment, labelled for clear identification and stored in appropriate conditions either temporarily or for a longer term. The SRFP should describe how the Ship Recycling Facility will avoid waste being mixed or contaminated in a way that interferes with subsequent handling, storage, treatment, recycling or disposal.

3.4.2.6 Treatment, transportation and disposal

The SRFP should demonstrate how the Ship Recycling Facility will ensure environmentally sound management of all Hazardous Materials and wastes removed from a ship at the Ship Recycling Facility. If treatment or disposal is taking place at the Ship Recycling Facility, the SRFP should describe how the materials will be managed in an environmentally sound manner and in compliance with applicable national requirements.

In situations where the Hazardous Materials and wastes are sent off site, the SRFP should describe procedures to ensure that they are transferred only to a facility authorized to deal

---CHUNK---

SOURCE: MEPC.210(63).pdf
In situations where the Hazardous Materials and wastes are sent off site, the SRFP should describe procedures to ensure that they are transferred only to a facility authorized to deal with their safe and environmentally sound treatment and disposal.

The SRFP should identify all off-site management and disposal facilities, describe how the materials will be managed at those facilities and identify all authorizations, permits, certificates,

approvals and licences required by national and other agencies authorizing the facilities to manage the wastes. The SRFP should include procedures for tracking Hazardous Materials and wastes as they are transported from the Ship Recycling Facility to their ultimate destination, and for managing and storing documentation, including that of subcontractors.

The final waste-management facilities should adhere to national standards and requirements which should take into account applicable international standards and requirements.

---CHUNK---

SOURCE: MEPC.210(63).pdf
The final waste-management facilities should adhere to national standards and requirements which should take into account applicable international standards and requirements.

3.4.3 Environmentally sound management of Hazardous Materials

3.4.3.1 Asbestos and materials containing asbestos

The Ship Recycling Facility should identify the location and quantity of asbestos and materials containing asbestos by actively utilizing the IHM. Identification, marking and labelling should be conducted by the Ship Recycling Facility before asbestos and materials containing asbestos are removed.