containers,
etc.
Minor easy to
feed into hopper
High Over 95% Powder ash Possibly smoky
and not
hazardous based
on incinerator
design
Minimum
Plastics
sheeting,
netting,
rope and
bulk
material.
Moderate
manual labour
time to size
reduction
High Over 95% Powder ash Possibly smoky
and not
hazardous based
on incinerator
design
Minimum
Rubber
hoses and
bulk pieces
Major manual
labour time to
size reduction
High Over 95% Powder ash Possibly smoky
and not
hazardous based
on incinerator
design
Minimum
Metal food
and
beverage
containers,
etc.
Minor easy to
feed into hopper
Low Less 10% Slag Possibly smoky
and not
hazardous
Moderate

6 Each operator of the onboard garbage incinerator should be trained and familiar in the use of the

---CHUNK---

SOURCE: MEPC.219(63).pdf
Minor easy to
feed into hopper
Low Less 10% Slag Possibly smoky
and not
hazardous
Moderate

6 Each operator of the onboard garbage incinerator should be trained and familiar in the use of the equipment and the types of garbage that can be destroyed in the incinerator.

Examples
of garbage
Special handling
by vessel
personnel6
before
incineration
Incineration characteristics
Onboard
storage
space Combustibility Reduction of volume Residual Exhaust
Metal
cargo, bulky
containers,
thick metal
items
Major manual
labour time to
size reduction(not
easily
incinerated)
Very low Less 5% Large metal
Fragments
and slag
Possibly smoky
and not
hazardous
Maximum
Glass food
and
beverage
containers,
etc.
Minor easy to
feed into hopper
Low Less 10% Slag Possibly smoky
and not
hazardous

Moderate
Wood,
cargo
containers
and large
wood
scrapes
Moderate
manual labour
time to size
reduction

---CHUNK---

SOURCE: MEPC.219(63).pdf
Glass food
and
beverage
containers,
etc.
Minor easy to
feed into hopper
Low Less 10% Slag Possibly smoky
and not
hazardous
Moderate
Wood,
cargo
containers
and large
wood
scrapes
Moderate
manual labour
time to size
reduction
High Over 95% Powder ash Possibly smoky
and not
hazardous
Minimum

2.11.5 Some of the disadvantages of incinerators may include the possible hazardous nature of the ash or vapour, dirty operation, excessive labour required for charging, stoking and ash removal. Some incinerators may not be able to meet air pollution regulations imposed in some ports and harbours or by flag and coastal States when such matters are subject to their jurisdiction . Some of these disadvantages can be remedied by automatic equipment for charging and stoking, however, the additional equipment to perform automatic functions will require more installation space.

2.11.6 The incineration of garbage that contains a large amount of plastic involves very specific incinerator settings such as higher oxygen injection and higher temperatures (850 to 1,200°C). If these special conditions are not met, depending on the type of plastic

---CHUNK---

SOURCE: MEPC.219(63).pdf
specific incinerator settings such as higher oxygen injection and higher temperatures (850 to 1,200°C). If these special conditions are not met, depending on the type of plastic and conditions of combustion, some toxic gases can be generated in the exhaust stream, including vaporized hydrochloric (HCl) and hydrocyanic (HCN) acids. These and other intermediary products of combustion of waste containing plastics are toxic to humans and marine life.

2.11.7 Onboard incineration of garbage may reduce the volume of garbage subject to quarantine requirements in some countries. However, incinerator ash may still be subject to local quarantine, sanitary or health requirements. Advice should be sought from local authorities regarding requirements that are in addition to MARPOL. For example, higher temperatures and more complete combustion may be required to effectively destroy organisms that present a risk.

2.11.8 Information on the development and advantages on the use of shipboard incinerator systems should be forwarded to the Organization for sharing between interested parties.
RESOLUTION MEPC.219(63)
Adopted on 2 March 2012

---CHUNK---