prevent accumulation of biofouling in relevant niche areas;

.2 regular polishing (with capture of debris) of uncoated propellers to maintain operational efficiency and minimize macrofouling accumulation;
RESOLUTION MEPC.378(80) (adopted on 7 July 2023)

---CHUNK---

SOURCE: MEPC.378(80).pdf
.2 regular polishing (with capture of debris) of uncoated propellers to maintain operational efficiency and minimize macrofouling accumulation;
RESOLUTION MEPC.378(80) (adopted on 7 July 2023)

.3 appropriate treatment of internal seawater cooling systems and discharge of any treated water in accordance with applicable regulations; and

.4 minimizing the use of any soap, cleaner or detergent used on surfaces and ensuring they are toxic - and phosphate -free, biodegradable and non-hazardous to the marine environment.

9.11 Operators undertaking in-water reactive cleaning should be aware of any regulations or requirements. Regulations regarding the discharge of biofouling and waste substances into the marine environment and the location of sensitive areas (such as Marine Protected Areas) may be relevant.

9.12 Captured biological waste and waste substances should be disposed of and treated

---CHUNK---

SOURCE: MEPC.378(80).pdf
the marine environment and the location of sensitive areas (such as Marine Protected Areas) may be relevant.

9.12 Captured biological waste and waste substances should be disposed of and treated in a safe and environmentally sound manner, in accordance with local requirements.

9.13 A report on the cleaning should be prepared by the operators undertaking reactive cleaning. The report should have the content as described in appendix 2 and describe the cleaning outcome.

9.14 A copy of the cleaning report or similar outcome in a digital tool should be available on board and the activity entered in the BFRB.

Procedures for recycling facilities

9.15 Ship recycling facilities should adopt measures (consistent with applicable national and local laws and regulations) to ensure that biofouling organisms or waste substances are not released into the local aquatic environment.

9.16 Ship recycling facilities should develop a plan to minimize release of biofouling organisms and/or waste substances. If relevant, it is recommended that hull and niche areas be cleaned prior to recycling to avoid release of viable biofouling organisms or waste substances.

---CHUNK---

SOURCE: MEPC.378(80).pdf
organisms and/or waste substances. If relevant, it is recommended that hull and niche areas be cleaned prior to recycling to avoid release of viable biofouling organisms or waste substances.

10 BIOFOULING MANAGEMENT PLAN

10.1 It is recommended that every ship have a ship-specific BFMP under the responsibility of shipowners, ship operators and shipmasters. A BFMP may require information from ship designers, shipbuilders, shipowners, AFC and MGPS manufacturers, recognized organizations and suppliers.

10.2 An effective BFMP should contribute to the aim of maintaining a recommended fouling rating 1, as described in chapter 8.

10.3 The ship-specific BFMP should include, but not necessarily be limited to, the following:

.1 identification of the officer, or the position (e.g. chief engineer), responsible for the BFMP, ensuring that the plan is properly implemented;

.2 details of the AFS installed and where it is installed;

.3 details of the recommended operating conditions which are suitable for the selected AFS to avoid deterioration of AFC, including recommended conditions such as temperature, salinity, speed;

---CHUNK---

SOURCE: MEPC.378(80).pdf
.3 details of the recommended operating conditions which are suitable for the selected AFS to avoid deterioration of AFC, including recommended conditions such as temperature, salinity, speed;

.4 details of expected AFC efficacy throughout AFC lifetime including the need for inspection or maintenance, if relevant;

.5 description of monitoring on biofouling risk parameters;

.6 regime for cleaning, if any;

.7 details of hull and niche areas where biofouling may accumulate;

.8 schedule for fixed inspections of areas;

.9 procedures for reactive cleaning actions that should be performed if triggered by inspection results;

.10 contingency action plan based on specific triggers from monitoring of biofouling risk parameters;

.11 regime for repairs, maintenance and renewal of AFS, when relevant, in accordance with the manufacturer's instructions;

---CHUNK---

SOURCE: MEPC.378(80).pdf
.10 contingency action plan based on specific triggers from monitoring of biofouling risk parameters;

.11 regime for repairs, maintenance and renewal of AFS, when relevant, in accordance with the manufacturer's instructions;

.12 process for monitoring and maintenance of MGPS as per the manufacturer's instructions to ensure their effectiveness in minimizing biofouling; and

.13 details of the documentation/reports required to document biofouling activities.

Continuous improvements

10.4 Information should be gathered to plan and facilitate efficient and sustainable biofouling management, allowing the evaluation and comparison of the cost-effectiveness of alternative strategies. The optimal solution is case -specific and should be considered in the light of several aspects.

10.5 Monitoring of the hull and the biofouling risk parameters may determine a risk of biofouling to be higher than predicted in the BFMP and therefore trigger more frequent inspections.

10.6 Inspection results may be shared in agreement with stakeholders involved if they are relevant for improvement purposes. To increase the efficiency of biofouling management and

---CHUNK---

SOURCE: MEPC.378(80).pdf
inspections.

10.6 Inspection results may be shared in agreement with stakeholders involved if they are relevant for improvement purposes. To increase the efficiency of biofouling management and inspections, inspection organizations are encouraged to share inspection re sults with AFS manufacturers.

10.7 The effectiveness of the management actions in place should be reviewed following inspections and cleaning. The BFMP should be updated if the management actions in place

are ineffective or deficient. Efficacy of the following items should be evaluated:

.1 ability to minimize biofouling by use of proactive cleaning methods;
.2 biofouling inspections schedule;
.3 ability to minimize biofouling by MGPS;
.4 AFS performance; and
.5 outcome of reactive biofouling management procedures:

.1 efficacy of the biofouling removal (i.e. no areas are missed); and
.2 accessibility for reactive cleaning in niche areas.

---CHUNK---

SOURCE: MEPC.378(80).pdf
RESOLUTION MEPC.378(80) (adopted on 7 July 2023)
2023 GUIDELINES FOR THE CONTROL AND MANAGEMENT OF SHIPS' BIOFOULING TO