s for INMARSAT Standard-C
ship earth stations capable of transmitting and rece~v~ng
direct-printing communications and resolution A.570(14): Type
approval of ship earth stations .
. 11 Resolution A.664(16): Performance standards for enhanced group call
equipment .
. 12 Resolution A.661(16): Performance standards for float-free satellite
emergency position-indicating radio beacons operating through the
geostationary INMARSAT satellite system on 1.6 GHz •
. 13 Resolution A.662(16): Performance standards for float-free release
and activation arrangements for emergency radio equipment .
. 14 Resolution A.699(17): System performance standard for the
---CHUNK---
SOURCE: MSC.36(63).pdf
. 13 Resolution A.662(16): Performance standards for float-free release
and activation arrangements for emergency radio equipment .
. 14 Resolution A.699(17): System performance standard for the
promulgation and co-ordination of maritime safety information using
high-frequency narrow-band direct-printing .
. 15 Resolution A.700(17): Performance standards for narrow-band
direct-printing telegraph equipment for the reception of
navigational and meteorological warnings and urgent information to
ships (MSI) by HF.
W/1687n/pp/EWP
RESOLUTION MSC.36(63)
(adopted on 20 May 1994)
ADOPTION OF THE INTERNATIONAL CODE OF SAFETY
FOR HIGH SPEED CRAFT MSC 62/23/Add.2
ANNEX 18
Page 144
14.14
14.14.1
14.14.2
14.14.3
14.14.4
14.14.5
14 .14.6
14.14.1
14.14.8
Maint e nance requ irements
Equipment should be so designed that the main units can be replaced
readily without elaborate recalibration or readjustment.
Where applicable, equipment should be so constructed and installed
that it is readily accessible for inspection and on-board
maintenance purposes.
Adequate information should be provided to enable the equipment
---CHUNK---
SOURCE: MSC.36(63).pdf
Where applicable, equipment should be so constructed and installed
that it is readily accessible for inspection and on-board
maintenance purposes.
Adequate information should be provided to enable the equipment
to be properly operated and maintained, taking into account the
recommendations of the Organization*.
Adequate tools and spares should be provided to enable equipment to
be maintained .
The Administration should ensure that radio equipment required by
this chapter is maintained to provide the availability of the
functional requirements specified in 14.4 and to meet the
recommended performance standards of such equipment.
On crafts engaged on voyages in sea areas Al and A2, the
availability should be ensured by using such methods as duplication
of equipment, shore-based maintenance or at-sea electronic
maintenance capability, or a combinat5 .on of these, as may be
approved by the Administration.
On crafts engaged on voyages in sea areas A3 and A4, the
availability should be ensured by using a combination of at
least two methods such as duplication of equipment, shore-based
maintenance or at-sea electronic maintenance capability, as may
---CHUNK---
SOURCE: MSC.36(63).pdf
On crafts engaged on voyages in sea areas A3 and A4, the
availability should be ensured by using a combination of at
least two methods such as duplication of equipment, shore-based
maintenance or at-sea electronic maintenance capability, as may
be approved by the Administration, taking into account the
I'ecommendations of the Organization"""".

However, crafts operating solely between ports where adequate facilities for shore-based maintenance of the radio installations are available and provided no journey between two such ports exceeds six hours, then the Administration may exempt such crafts from the requirement to use at least two maintenance methods. For such crafts at least one maintenance method should be used.

* Refer to the Recommendation on general requirements for shipborne radio equipment forming part of the global maritime distress and safety system and for ele