d which are controlling the MODU while stationary at the site including its drilling operations (i.e. normally the control room)■.
5 Refer to the World-Wide Navigational Warning Service (resolution A.706(17), as amended).
RESOLUTION MSC.506(105) (adopted on 28 April 2022)
AMENDMENTS TO THE CODE FOR THE CONSTRUCTION AND EQUIPMENT
OF MOBILE OFFSHORE DRILLING UNITS, 2009 (2009 MODU CODE)
MSC 105/20/Add.1
Annex 13, page 4
I:\MSC\105\MSC 105-20-Add.1.docx

SOURCE: MSC.506(105).pdf
URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.506(105).pdf
OF MOBILE OFFSHORE DRILLING UNITS, 2009 (2009 MODU CODE)
MSC 105/20/Add.1
Annex 13, page 4
I:\MSC\105\MSC 105-20-Add.1.docx
11.6 Radio life-saving appliances
Two-way VHF radiotelephone apparatus
11.6.1 All lifeboats should carry a two-way VHF radiotelephone apparatus.
11.6.2 At least two two -way VHF radiotelephone apparatuses should be available on the MODU, so stowed that they can be rapidly placed in any liferaft. 6 All two -way VHF radiotelephone apparatuses should conform to performance standards not inferior to those adopted by the Organization.

_____
6 The two -way VHF radiotelephone apparatus required by 11.6.2 may fulfil or partially fulfil the requirements of SOLAS regulations IV/7.2, 7.3 or 7.4, as applicable.
Search and rescue locating device
11.6.3 All lifeboats should carry one radar SART or AIS-SART.
11.6.4 At least two radar SARTs or AIS-SARTs should be available on the MODU, so stowed
---
SOURCE: MSC.506(105).pdf
URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.506(105).pdf
11.6.4 At least two radar SARTs or AIS-SARTs should be available on the MODU, so stowed that they can be rapidly placed in any liferaft. 7 All SARTs or AIS -SARTs should conform to performance standards not inferior to those adopted by the Organization.

_____
7 The radar SARTs or AIS-SARTs required by 11.6.4 may fulfil the requirements of SOLAS regulations IV/7.1.3, 7.2, 7.3 or 7. 5, as applicable.
11.7 Helicopter communications
In order to ensure communication with helicopters, MODUs should carry an aeromobile VHF radiotelephone station complying with the relevant requirements of ICAO 8 and suitable for communication with helicopters in its area of operation.

_____
8 Refer to Volume 3, Part II of annex 10, and Part III, section II of annex 6 to the ICAO Convention.
11.8 Internal communications
All types of MODUs should be fitted with efficient means of communication between the control
---
SOURCE: MSC.506(105).pdf
URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.506(105).pdf
11.8 Internal communications
All types of MODUs should be fitted with efficient means of communication between the control room, the bridge (if provided) and position or positions fitted with facilities for operation of radio
equipment.
11.9 Performance standards
All radio equipment should be of a type approved by the Administration issuing the licence. Such equipment should conform to appropriate performance standards not inferior to those adopted by the Organization.9

_____
9 Refer to the following performance standards adopted by the Organization:
General requirements
.1 General requirements for shipborne radio equipment forming part of the Global Maritime Distress and Safety System (GMDSS) and for electronic navigational aids (resolution A.694(17));
.2 Performance standards for the presentation of navigation-related information on shipborne navigational displays (resolution MSC.191(79), as amended);

SOURCE: MSC.506(105).pdf
URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.506(105).pdf
navigational displays (resolution MSC.191(79), as amended);
.3 Performance standards