arrangements for emergency
radio equipment (resolution A.662(16));
.15 Performance standards for float -free emergency position -indicating radio beacons
(EPIRBs) operating on 406 MHz (resolution MSC.471(101));
Search and rescue transmitters and transponders
.16 Performance standards for search and rescue radar transponders
(resolution MSC.510(105)); and

SOURCE: MSC.506(105).pdf
URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResoluti
ons/MSC.506(105).pdf
Search and rescue transmitters and transponders
.16 Performance standards for search and rescue radar transponders
(resolution MSC.510(105)); and
.17 Performance standards for survival craft AIS search and rescue transmitters (AIS -SART)
for use in search and rescue operations (resolution MSC.246(83)).
11.10 Survey of the radio station
11.10.1 The radio station of a unit should be subject to survey as specified below:
.1 by the Administration which issues the licence or its authorized
representative before the radio station is put into service;
RESOLUTION MSC.506(105) (adopted on 28 April 2022)
AMENDMENTS TO THE CODE FOR THE CONSTRUCTION AND EQUIPMENT
OF MOBILE OFFSHORE DRILLING UNITS, 2009 (2009 MODU CODE)
MSC 105/20/Add.1
Annex 13, page 6
I:\MSC\105\MSC 105-20-Add.1.docx
.2 when the unit is moved and comes under the administrative control of
another coastal State a survey may be carried out by that State or its
authorized representative; and

SOURCE: MSC.506(105).pdf
URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResoluti
ons/MSC.506(105).pdf
another coastal State a survey may be carried out by that State or its
authorized representative; and
.3 within three months before or after the anniversary date of the MODU Code
certificate, a periodical survey carried out by an officer of the Administration
and/or the coastal State or their respective authorized representative.
11.10.2 EPIRBs should be serviced at intervals not exceeding five years, to be performed by
an approved shore-based maintenance facility.
11.10.3 The Administration may recognize the coastal State as its authorized representative.
11.10.4 In every case when an authorized representative of the coastal State carries out an
inspection, a report should be issued and kept with the radio documents, and a copy, if
requested, should be forwarded to the Administration.
11.11 Navigation equipment
11.11.1 All units should comply with SOLAS chapter V.
11.11.2 Administrations may exempt units from navigation equipment carriage requirements,
---
SOURCE: MSC.506(105).pdf
URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResoluti
ons/MSC.506(105).pdf
11.11.1 All units should comply with SOLAS chapter V.
11.11.2 Administrations may exempt units from navigation equipment carriage requirements,
in accordance with SOLAS regulation V/3.■
***
RESOLUTION MSC.506(105) (adopted on 28 April 2022)
AMENDMENTS TO THE CODE FOR THE CONSTRUCTION AND EQUIPMENT
OF MOBILE OFFSHORE DRILLING UNITS, 2009 (2009 MODU CODE)
RESOLUTION MSC.506(105) (adopted on 28 April 2022)
AMENDMENTS TO THE CODE FOR THE CONSTRUCTION AND EQUIPMENT
OF MOBILE OFFSHORE DRILLING UNITS, 2009 (2009 MODU CODE)

SOURCE: MSC.524(106).pdf
URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResoluti
ons/MSC.524(106).pdf
RESOLUTION MSC.524(106) (adopted on 10 November 2022)
AMENDMENTS TO THE INTERNATIONAL CODE OF SAFETY FOR SHIPS USING
GASES OR OTHER LOW-FLASHPOINT FUELS (IGF CODE)
RESOLUTION MSC.524(106)
(adopted on 10 November 2022)
AMENDMENTS TO THE INTERNATIONAL CODE OF SAFETY
FOR SHIPS USING GASES OR OTHER LOW-FLASHPOINT FUELS (IGF CODE)
THE MARITIME SAFETY COMMITTEE,
RECALLING Article 28(b) of the Convention on the International Maritime Organization
concerning the functions of the Committee,
NOTING resolu