ipborne VHF Radio Installations

-

out in Annexes 1 to 4 to the present resolution:

(a) Resolution A. 803(19) - Performance Standards for Shipborne VHF Radio Installations

Capable of Voice Communication and Digital Selective Calling (Annex 1);

(b) Resolution A.804(19) - Performance Standards for Ship borne MF Radio Installations

Capable of Voice Communication and Digital Selective Calling (Annex 2);

(c) Resolution A. 806(1 9) - Performance Standards for Shipborne MFIHF Radio Installations

Capable of Voice Communication, Narrow-Band Direct-Printing and Digital Selective

Calling (Annex 3); and

(d) Resolution A. 807(19) - Performance Standards for Inmarsat-C Ship Earth Stations

Capable of Transmitting and Receiving Direct-Printing Communications (Annex 4);

2. RECOMMENDS Governments to ensure that equipment and systems listed in the present

resolution and installed on or after 1 January 2000 conform to the amended performance standards

specified in the attached Annexes .

I:\MSC\68\23 -Add.l

-

resolution and installed on or after 1 January 2000 conform to the amended performance standards

specified in the attached Annexes .

I:\MSC\68\23 -Add.l

RESOLUTION MSC.68(68)

(adopted on 6 June 1997)

ADOPTION OF

FOR SHIPBORNE RADIOCOMMUNICATION EQUIPMENT MSC 68/23/ Add. 1

ANNEX 10

Page 2

ANNEX 1

FOR VHF RADIO INSTALLATIONS CAPABLE OF VOICE COMMUNICATION

AND DIGITAL SELECTIVE CALLING

Modify paragraphs 11.2.5 and 11.2.6 of the Annex, as follows:

".5 facilities to automatically update the ship's position and the time at which the position was

determined from a suitable electronic position-fixing aid which may be an integral part

of the equipment. For equipment which does not have an integral position-fixing aid,

such facilities should include a suitable interface conforming to the appropriate

international standard; 1

-

of the equipment. For equipment which does not have an integral position-fixing aid,

such facilities should include a suitable interface conforming to the appropriate

international standard; 1

.6 means for manual entry of position information and the time at which the position was

determined; and"

Add new paragraph 11.2.7 :

".7 means to activate an alarm when no position data is received from the electronic position-fixing aid or, in the case of manual input, the position information is over 4 hours old. Any position information not updated for more than 23 Y2 hours should be erased."

Modify paragraph 11.3.2, as follows:

".3.2 These messages should be stored until readout and should be erased 48 hours after their reception. II

Modify the second sentence of paragraph 11.4, as follows:

"11. 4 ..... The means for initiating a distress alert should be as prescribed in 2.6 to 2.8. II

IEC 1162

J:\MSC\68\23-Add .l

RESOLUTION MSC.68(68)

(adopted on 6 June 1997)

-

"11. 4 ..... The means for initiating a distress alert should be as prescribed in 2.6 to 2.8. II

IEC 1162

J:\MSC\68\23-Add .l

RESOLUTION MSC.68(68)

(adopted on 6 June 1997)

ADOPTION OF

FOR SHIPBORNE RADIOCOMMUNICATION EQUIPMENT ANNEX 2

MSC 68/23/ Add . 1

ANNEX 10

Page 3

FOR MF RADIO INSTALLATIONS CAPABLE OF VOICE COMMUNICATION

AND DIGITAL SELECTIVE CALLING

Modify paragraphs 2.4,2 .5 and 2.6 of Part D of the Annex, as follows :

".4 means to display, in plain language with a minimum of 160 characters in two or more lines, the information contained in a received call;

.5 facilities to automatically update the ship's position and the time at which the position was determined from a suitable electronic position-fixing aid which may be an integral part of the equipment. For equipment which does not have an integral position-fixing aid,

-

determined from a suitable electronic position-fixing aid which may be an integral part of the equipment. For equipment which does not have an integral position-fixing aid, such facilities should include a suitable interface conforming to the appropriate international standard; 1

.6 means for manual entry of position information and the time at which the position was determined ; and"

Add new paragraph 2.7 of Part D, the Annex, as follows :

".7 means to activate an alarm when no position data is received from the electronic

position-fixing aid or, in the case of manual input , the position information is over 4 hours old . Any position information not updated for more than 23 Yz