aft, and coast stations, ships and supporting aircraft.

11.2 Training

Training in the use of IMO Standard Marine Communication Phrases should be provided to personnel responsible for radio communications.1

_____

1 Refer to IMO Standard Marine Communication Phrases (resolution A.918(22)).

11.3 Self-propelled units

Each unit should comply with the applicable provisions concerning radio stations for cargo ships in SOLAS chapter IV.2

_____

2 All requirements of SOLAS chapter IV referring to ■from the position from which the ship is normally navigated■ should be appl ied as meaning ■from the position the MODU is normally navigated■.

11.4 Non-self-propelled units under tow

11.4.1 The provisions for non-self-propelled units under tow when manned depend upon the radio installations fitted in the towing ship, as set out in paragraphs 11.4.2 and 11.4.3.

RESOLUTION MSC.506(105) (adopted on 28 April 2022)

URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.506(105).pdf

radio installations fitted in the towing ship, as set out in paragraphs 11.4.2 and 11.4.3.

RESOLUTION MSC.506(105) (adopted on 28 April 2022)

OF MOBILE OFFSHORE DRILLING UNITS, 2009 (2009 MODU CODE)

MSC 105/20/Add.1

I:\MSC\105\MSC 105-20-Add.1.docx

11.4.2 In cases where the towing ship complies fully with all applicable requirements concerning radiocommunications for ships prescribed in SOLAS chapter IV, the unit under tow when manned should:

.1 be fitted with VHF facilities as required by SOLAS regulations IV/7.1.1 3 and 7.1.2 and with MF facilities as required by regulations IV/9.1.1 and 9.1.2;

.2 be fitted with an EPIRB as required by SOLAS regulation IV/7.1.5; and

.3 be fitted with receiver(s) capable of re ceiving MSI and SAR related information throughout the entire voyage in which the unit is engaged in accordance with SOLAS regulation IV/7.1.4.

URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.506(105).pdf

information throughout the entire voyage in which the unit is engaged in accordance with SOLAS regulation IV/7.1.4.

11.4.3 In cases where the towing ship does not comply fully with the applicable requirements concerning radiocommunications for ships prescribed in SOLAS chapter IV, the unit under tow when manned should comply with all the applicable provisions concerning radiocommunications prescribed in SOLAS chapter IV.3

3 All requirements of SOLAS chapter IV referring to ■from the position from which the ship is

normally navigated■ should be applied as meaning ■from a position which is continuously manned

and which is controlling the MODU while under tow■.

11.5 Units stationary at the site or engaged in drilling operations

11.5.1 Each unit, while stationary at the site, including when engaged in drilling operations,

should comply with all requirements prescribed in SOLAS chapter IV that are applicable to a

---

URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.506(105).pdf

should comply with all requirements prescribed in SOLAS chapter IV that are applicable to a

ship sailing through the same area.4 Each unit should also report its position to the relevant

World-Wide Navigational Warning Service (WWNWS) NAVAREA Coordinator when arriving

on-site, in order for a Navigational Warning to be broadcast.5 Additionally, units should inform the

NAVAREA Coordinator when departing from that site, in order for the broadcast to be

cancelled.

11.5.2 On units which do not have a navigation bridge, it should be possible to initiate

transmission of the distress alerts by the radio installation specified in SOLAS

regulations IV/10.1.1, 10.1.2 and 10.1.4, as applicable, from a position in an accessible and

protected area which is acceptable to the Administration.

11.5.3 If the acoustic noise level in a room fitted with operating controls for radio equipment

is so high or could be so high, during particular operating conditions, that it may disturb or

---

URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.506(105).pdf

is so high or could be so high, during particular operating conditions, that it may disturb or

prevent proper use of the radio equipment, then adequate noise protection should be provided

by mechanical or other means, in association with the op erating controls for the radio

equipment.

---

4 All requirements o