UTION MSC.68(68)

(adopted on 6 June 1997)

ADOPTION OF

FOR SHIPBORNE RADIOCOMMUNICATION EQUIPMENT RESOLUTION MSC.68(68)

(adopted on 6 June 1997)

ADOPTION OF

FOR SHIPBORNE RADIOCOMMUNICATION EQUIPMENT

-

RESOLUTION MSC.133(76)

(adopted on 12 December 2002)

ADOPTION OF TECHNICAL PROVISIONS FOR MEANS OF

ACCESS FOR INSPECTIONSMSC 76/23/Add.1

I:\MSC\76\23-ADD.1.DOC

ANNEX 2

RESOLUTION MSC.133(76)

(adopted on 12 December 2002)

ADOPTION OF TECHNICAL PROVISIONS FOR MEANS OF

ACCESS FOR INSPECTIONS

THE MARITIME SAFETY COMMITTEE,

RECALLING Article 28(b) of the Convention on the International Maritime Organization

concerning the functions of the Committee,

NOTING the new regulation II-1/3-6 of the In ternational Convention for the Safety of

Life at Sea (SOLAS), 1974, as amended (hereinaft er referred to as ■the Convention■) adopted by

resolution MSC.134(76), concerning access to and with in spaces in the cargo area of oil tankers

and bulk carriers,

NOTING ALSO that the aforementioned regulation provides that the means of access

referred to therein shall comply with the requirements of Technical provisions for means of

access for inspections (hereinafter referred to as ■the Technical provisions■) to be made

mandatory under the Convention;

RECOGNIZING that the Technical provisions referred to above are not intended to

-

access for inspections (hereinafter referred to as ■the Technical provisions■) to be made

mandatory under the Convention;

RECOGNIZING that the Technical provisions referred to above are not intended to

inhibit the development of new or novel technol ogies which provide for an improved means to

carry out ship surveys and inspections,

HAVING CONSIDERED, at its seventy-sixth session, the text of the proposed Technical

provisions,

1. ADOPTS the Technical provisions for means of access for inspections, the text of which

is set out in the Annex to the present resolution;

2. INVITES Contracting Governments to th e Convention to note that the Technical

provisions will take effect on 1 January 2005 upon en try into force of the new regulation II-1/3-6

of the Convention;

3. REQUESTS the Secretary-General to transmit certified copies of this resolution and the text of the Technical provisions contained in th e Annex to all Contracting Governments to the

Convention;

4. FURTHER REQUESTS the Secretary-General to transmit copies of this resolution and the Annex to all Members of the Organization, which are not Contracting Governments to the Convention;

-

Convention;

4. FURTHER REQUESTS the Secretary-General to transmit copies of this resolution and the Annex to all Members of the Organization, which are not Contracting Governments to the Convention;

5. INVITES Governments to encourage the de velopment of novel technologies aimed at facilitating the survey and inspection of ships and to keep the Organization advised of any positive results.

RESOLUTION MSC.133(76)

(adopted on 12 December 2002)

ADOPTION OF TECHNICAL PROVISIONS FOR MEANS OF

ACCESS FOR INSPECTIONSMSC 76/23/Add.1

ANNEX 2

Page 2

I:\MSC\76\23-ADD.1.DOC

ANNEX

TECHNICAL PROVISIONS FOR MEANS OF ACCESS FOR INSPECTIONS

Preamble

It has long been recognised that the only way of ensuring that the condition of a ship■s structure

is maintained to conform with the applicable requirements is for all its components to be surveyed on a regular basis throughout their operationa l life so as to ensure that they are free

from damage such as cracks, buckling or defo rmation due to corrosion, overloading or contact

damage and that thickness diminution is within established limits. The provision of suitable

-

from damage such as cracks, buckling or defo rmation due to corrosion, overloading or contact

damage and that thickness diminution is within established limits. The provision of suitable

means of access to the hull structure for the pur pose of carrying out overall and close-up surveys

and inspections is essential and such means shoul d be considered and provided for at the ship

design stage.

Ships should be designed and built with due consid eration as to how they will be surveyed

by

flag State inspectors and classification society surveyors during their in-service life and how the

crew will be able to monitor the condition of th e ship. Without adequate access, the structural

condition of the ship can deteriorate undetected and major structural failure can arise. A

comprehensive approach to design and maintenan ce is required to cove