y position-indicating radio beacons

.14 Performance standards for float-free release and activation arrangements for emergency radio equipment (resolution A.662(16));

.15 Performance standards for float -free emergency position -indicating radio beacons (EPIRBs) operating on 406 MHz (resolution MSC.471(101));

Search and rescue transmitters and transponders

.16 Performance standards for search and rescue radar transponders (resolution MSC.510(105)); and

---

URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.506(105).pdf

Search and rescue transmitters and transponders

.16 Performance standards for search and rescue radar transponders (resolution MSC.510(105)); and

.17 Performance standards for survival craft AIS search and rescue transmitters (AIS -SART) for use in search and rescue operations (resolution MSC.246(83)).

11.10 Survey of the radio station

11.10.1 The radio station of a unit should be subject to survey as specified below:

.1 by the Administration which issues the licence or its authorized representative before the radio station is put into service;

RESOLUTION MSC.506(105) (adopted on 28 April 2022)

OF MOBILE OFFSHORE DRILLING UNITS, 2009 (2009 MODU CODE)

MSC 105/20/Add.1

I:\MSC\105\MSC 105-20-Add.1.docx

.2 when the unit is moved and comes under the administrative control of another coastal State a survey may be carried out by that State or its authorized representative; and

---

URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.506(105).pdf

another coastal State a survey may be carried out by that State or its authorized representative; and

.3 within three months before or after the anniversary date of the MODU Code certificate, a periodical survey carried out by an officer of the Administration and/or the coastal State or their respective authorized representative.

11.10.2 EPIRBs should be serviced at intervals not exceeding five years, to be performed by an approved shore-based maintenance facility.

11.10.3 The Administration may recognize the coastal State as its authorized representative.

11.10.4 In every case when an authorized representative of the coastal State carries out an inspection, a report should be issued and kept with the radio documents, and a copy, if requested, should be forwarded to the Administration.

11.11 Navigation equipment

11.11.1 All units should comply with SOLAS chapter V.

11.11.2 Administrations may exempt units from navigation equipment carriage requirements,

---

URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.506(105).pdf

11.11.1 All units should comply with SOLAS chapter V.

11.11.2 Administrations may exempt units from navigation equipment carriage requirements,

in accordance with SOLAS regulation V/3.■

***

RESOLUTION MSC.506(105) (adopted on 28 April 2022)

OF MOBILE OFFSHORE DRILLING UNITS, 2009 (2009 MODU CODE)

RESOLUTION MSC.506(105) (adopted on 28 April 2022)

OF MOBILE OFFSHORE DRILLING UNITS, 2009 (2009 MODU CODE)

URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.524(106).pdf

RESOLUTION MSC.524(106) (adopted on 10 November 2022)

GASES OR OTHER LOW-FLASHPOINT FUELS (IGF CODE)

RESOLUTION MSC.524(106)

(adopted on 10 November 2022)

FOR SHIPS USING GASES OR OTHER LOW-FLASHPOINT FUELS (IGF CODE)

THE MARITIME SAFETY COMMITTEE,

RECALLING Article 28(b) of the Convention on the International Maritime Organization

concerning the functions of the Committee,

NOTING resolution MSC.391(95), by which it adopted the International Code of Safety for

Ships using Gases or other Low -flashpoint Fuels (IGF Code), which has become mandatory

under chapters II-1 and II-2 of the International Convention for the Safety of Life at Sea,
1974

("the Convention"),

NOTING ALSO article VIII(b) and regulation II -1/2.29 of the Convention concerning the

procedure for amending the IGF Code,

URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.524(106).pdf

NOTING ALSO article VIII(b) and regulation II -1/2.29 of the Convention concerning the

procedure for amending the IGF Code,

HAVING CONSIDE