IMO Doc: IMO_DOC_611

SOURCE: MSC.198%2880%29.pdf■3. STRONGLY URGES Contracting Governments to the Convention to meet their ■obligations under SOLAS regulation XI-1/5 and resolution A.959(23) and, in particular, when a ■ship entitled to fly their flag is transferred to the flag of another Contracting Government to the ■Convention, to forward to it the Continuous Synopsis Record of the ship as soon as possible and ■within the time frame prescribed in resolution A.959(23), as amended, so as to enable the latter ■Government to promptly issue to the ship the required Continuous Synopsis Record; ■ ■4. INVITES Contracting Governments to the Convention to bring to its attention any ■difficulties encountered with the implementation of the provisions of SOLAS regulation XI-1/5 ■or of resolution A.959(23) as amended for consideration of the issues involved and decision on ■the actions to be taken. ■ ■ ■RESOLUTION MSC.198(80) ■(adopted on 20 May 2005) ■ADOPTION OF AMENDMENTS TO THE FORMAT AND■■---CHUNK---■■SOURCE: MSC.198%2880%29.pdf■the actions to be taken. ■ ■ ■RESOLUTION MSC.198(80) ■(adopted on 20 May 2005) ■ADOPTION OF AMENDMENTS TO THE FORMAT AND ■GUIDELINES FOR THE MAINTENANCE OF THE CONTINUOUS ■SYNOPSIS RECORD (CSR)MSC 80/24/Add.1 ■ANNEX 8 ■Page 3 ■ ■I:\MSC\80\24-Add-1.doc ■ANNEX 1 ■ ■ ■AMENDMENTS TO THE FORMAT AND GUIDELINES FOR THE MAINTENANCE ■OF THE CONTINUOUS SYNOPSIS RECORD (CSR) (RESOLUTION A.959(23)) ■ ■Issue of revised and updated CSR documents by the Administration ■ ■ ■1 The existing paragraph 8 is replaced by the following text: ■ ■■In the case of a change of flag, the previ ous flag State has to issue a new CSR document ■to the ship showing the date the ship ceased to be registered with that flag State. That ■flag State is required to se nd a copy of the ship■s CSR file, as soon as possible and ■preferably not later than one m onth from the date the ship ceas ed to be registered, to the ■new flag State. The new flag State is requ ired to issue a new CSR document as soon as■■---CHUNK---■■SOURCE: MSC.198%2880%29.pdf■preferably not later than one m onth from the date the ship ceas ed to be registered, to the ■new flag State. The new flag State is requ ired to issue a new CSR document as soon as ■possible and not later than three months after the date of change of flag.■ ■ ■2 At the end of paragraph 9, the following new paragraph 9.1 is inserted: ■ ■■9.1 In instances where the previous flag State has not forwarded, within three months ■from the date of change of flag, the CSR file of the ship covering the period during which ■the ship was entitled to fly its flag, to the new w flag State, then the new flag State should ■issue to the ship a CSR based on the CSR information received from onboard the ship. ■The sequential number to be allocated to the CSR document to be so issued should be the ■second sequential number after the last sequentially number shown on the CSR document ■found (i.e. leaving first sequential number unused). The new flag State should explain, in■■---CHUNK---■■SOURCE: MSC.198%2880%29.pdf■second sequential number after the last sequentially number shown on the CSR document ■found (i.e. leaving first sequential number unused). The new flag State should explain, in ■entry box 14, the reason for issuing the CSR document in such a manner.■ ■ ■Possibility of inconsistencies ■ ■3 At the end of paragraph 13, the fo llowing new paragraph 13.1 is inserted: ■ ■■13.1 When inspecting the CSR file of ship s that have changed flag, those exercisi