On crafts engaged on voyages in sea areas A3 and A4, the availability should be ensured by using a combination of at least two methods such as duplication of equipment, shore-b ased maintenance or at-sea electronic maintenance capability, as may be approved by the Administration, taking into account the I'ecommendations of the Organization"""".

However, crafts operating solely between ports where adequate facilities for shore-based maintenance of the radio installations are available and provided no journey between two such ports exceeds six hours, then the Administration may exempt such crafts from the re quirement to use at least two maintenance methods.

For such crafts at least one maintenance method should be used.

* Refer to the Recommendation on general requirements for shipborne radio equipment form ing part of the global maritime distress and safety system and for electronic navigation al aids , adopted by the Organization by resolution A.694(11).

** Administrations should take account of the Recommendations on radio maintenance guide lines for the Global Maritime Distress and Safety System - and for electronic navigation al aids , adopted by the Organization by resolution A.694(11).

** Administrations should take account of the Recommendations on radio maintenance guide lines for the Global Maritime Distress and Safety System (GMDSS) related to sea areas A3 and A4 , a.dopted by the Organization by resolution A.102(11) W/1681n/pp/EWP RESOLUTION MSC.36(63) (adopted on 20 May 1994) ADOPTION OF THE INTERNATIONAL CODE OF SAFETY FOR HIG H SPEED CRAFT 14.14.9 14.15 14.16 MSC 62/23/Add.2 ANNEX 18 Page 145 While all reasonable steps should be taken to maintain the equipment in efficient working order to ensure com pliance with all the functional requirements specified in 14.4, malfunction of the equip ment for providing the general radiocommunications, required by 14.4.8, should not be co nsidered as making a craft unseaworthy or as a reason for delaying the craft in ports wh ere repair facilities are not readily available, provided the craft is capable of perfor ming all distress and safety functions.

Radio pers~ Every craft should carry personnel qualified for distress and safety radioco mmunication purposes to the satisfaction of the - not readily available, provided the cr aft is capable of performing all distress and safety functions.

Radio pers~ Every craft should carry personnel qualified for distress and safety radioco mmunication purposes to the satisfaction of the Administration.

The personnel should be holders of certificates specified in the Radio Regulations as ap propriate, anyone of whom should be designated to have primary responsibility for radioc ommunications during distress incidents.

Radio records A record should be kept, to the satisfaction of the Administration and as required by the Radio Regulations, of all incidents connected with the radiocommunicatio n service which appear to be of importance to safety of life at sea.

W/l687n/pp/EWP RESOLUTION MSC.36(63) (adopted on 20 May 1994) ADOPTION OF THE INTERNATIO NAL CODE OF SAFETY FOR HIGH SPEED CRAFT