.

13 Resolution A.662(16): Performance standards for float-free release and activation arr angements for emergency radio equipment .

.

14 Resolution A.699(17): System performance standard for the promulgation and co-ordinat ion of maritime safety information using high-frequency narrow-band direct-printing .

.

15 Resolution A.700(17): Performance standards for narrow-band direct-printing telegraph equipment for the reception of navigational and meteorological warnings and urgent infor mation to ships (MSI) by HF.

W/1687n/pp/EWP RESOLUTION MSC.36(63) (adopted on 20 May 1994) ADOPTION OF THE INTERNATIO NAL CODE OF SAFETY FOR HIGH SPEED CRAFT MSC 62/23/Add.2 ANNEX 18 Page 144 14.14 14.14.1 14.14.2 14.14.3 14.14.4 14.14.5 14 .14.6 14.14.1 14.14.8 Maint e nance requ irements Equ ipment should be so designed that the main units can be replaced readily without elabora te recalibration or readjustment.

Where applicable, equipment should be so constructed and installed that it is readily ac cessible for inspection and on-board maintenance purposes.

Adequate information should be provided to enable the equipment - Where applicable, equi pment should be so constructed and installed that it is readily accessible for inspectio n and on-board maintenance purposes.

Adequate information should be provided to enable the equipment to be properly operated and maintained, taking into account the recommendations of the Organization*.

Adequate tools and spares should be provided to enable equipment to be maintained .

The Administration should ensure that radio equipment required by this chapter is mainta ined to provide the availability of the functional requirements specified in 14.4 and to meet the recommended performance standards of such equipment.

On crafts engaged on voyages in sea areas Al and A2, the availability should be ensured by using such methods as duplication of equipment, shore-based maintenance or at-sea ele ctronic maintenance capability, or a combinat5 .on of these, as may be approved by the A dministration.

On crafts engaged on voyages in sea areas A3 and A4, the availability should be ensured by using a combination of at least two methods such as duplication of equipment, shore-b ased maintenance or at-sea electronic maintenance capability, as may - On crafts engaged on voyages in sea areas A3 and A4, the availability should be ensured by using a combina tion of at least two methods such as duplication of equipment, shore-based maintenance o r at-sea electronic maintenance capability, as may be approved by the Administration, ta king into account the l'ecommendations of the Organization"""".

However, crafts operating solely between ports where adequate facilities for shore-based maintenance of the radio installations are available and provided no journey between two such ports exceeds six hours, then the Administration may exempt such crafts from the re quirement to use at least two maintenance methods.

For such crafts at least one maintenance method should be used.

* Refer to the Recommendation on general requirements for shipborne radio equipment form ing part of the global maritime d