"3.2 These messages should be stored until readout and should be erased 48 hours after t
heir reception .

" Modify the second sentence of paragraph 4 of Part D, the Annex, as follows : "4 .....

The means for initiating a distress alert should be as prescribed in 2.5 to 2.7 of Part
A." IEC 1162 I:\MSC \68\23-Add .l RESOLUTION MSC.68(68) (adopted on 6 June 1997) ADOPTIO
N OF AMENDMENTS TO PERFORMANCE STANDARDS FOR SHIPBORNE RADIOCOMMUNICATION EQUIPMENT MSC
68/231 Add.

1 ANNEX 10 Page 4 ANNEX 3 AMENDMENTS TO RESOLUTION A.806(19) - PERFORMANCE STANDARDS FOR
MF/HF RADIO INSTALLATIONS CAPABLE OF VOICE COMMUNICATION NARROW-BAND DIQECT-PRINTING AND
DIGITAL SELECTIVE CALLING Modify paragraphs 2.4, 2.5 and 2.6 of Part D, the Annex, as fo
llows : ".4 means to display, in plain language with a minimum of 160 characters in two
or more lines, the information contained in a received call; - ".4 means to display, in
plain language with a minimum of 160 characters in two or more lines, the information co
ntained in a received call; .5 facilities to automatically update the ship's position an
d the time at which the position was determined from a suitable electronic position-fixi
ng aid which may be an integral part of the equipment.

For equipment which does not have an integral position-fixing aid, such facilities shoul
d include a suitable interface conforming to the appropriate international standard; 1 .
6 means for manual entry of position information and the time at which the position was
determined; and" Add new paragraph 2.7 of Part D, the Annex : ".7 means to activate an a
larm when no position data is received from the electronic position-fixing aid or, in th
e case of manual input, the position information is over 4 hours old.

Any position information not updated for more than 2312 hours should be erased.

II - position-fixing aid or, in the case of manual input, the position information is ov
er 4 hours old.

Any position information not updated for more than 2312 hours should be erased.

II Modify paragraph 3.2 of Part D, the Annex, as follows: ".3.2 These messages should be
stored until readout and should be erased 48 hours after their reception .

II Modify the second sentence of paragraph 4 of Part D, the Annex, as follows: "4 .....
.

The means for initiating a distress alert should be as prescribed in 2.5 to 2.7 of Part
A" IEC 1162 I:\MSC\68\23-Add.l RESOLUTION MSC.68(68) (adopted on 6 June 1997) ADOPTION O
F AMENDMENTS TO PERFORMANCE STANDARDS FOR SHIPBORNE RADIOCOMMUNICATION EQUIPMENT ANNEX 4
MSC 68/23/ Add .

1 ANNEX 10 Page 5 AMENDMENTS TO RESOLUTION A.807(19) - PERFORMANCE STANDARDS FOR INMARSA
T-C SHIP EARTH STATIONS CAPABLE OF T