RECALLING Article 28(b) of the Convention on the International Maritime Organization con
cerning the functions of the Committee, RECALLING ALSO resolution A.534(13), by which th
e Assembly, at its thirteenth session, adopted the Code of Safety for Special Purpose Sh
ips, 1983 (1983 SPS Code), RECALLING FURTHER that the Assembly authorized the Committee
to amend the Code as may be necessary, NOTING the amendments to the International Conven
tion for the Safety of Life at Sea, 1974 ("the Convention") adopted by resolution MSC.49
6(105), --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOReso
lutions/MSCResolutions/MSC.502(105).pdf NOTING the amendments to the International Conve
ntion for the Safety of Life at Sea, 1974 ("the Convention") adopted by resolution MSC.4
96(105), HAVING CONSIDERED, at its 105th session, consequential amendments to the Specia
l Purpose Ship Safety Certificate and the Record of Equipment for the Special Purpose Sh
ip Safety Certificate (Form SPS) of the 1983 SPS Code, 1 ADOPTS amendments to the 1983 S
PS Code, the text of which is set out in the annex to the present resolution; 2 DETERMIN
ES that the said consequential amendments to the 1983 SPS Code should become effective o
n 1 January 2024, in conjunction with the entry into force of the amendments to the Conv
ention adopted by resolution MSC.496(105).

RESOLUTION MSC.502(105) (adopted on 28 April 2022) AMENDMENTS TO THE CODE OF SAFETY FOR
SPECIAL PURPOSE SHIPS, 1983 (1983 SPS CODE) MSC 105/20/Add.1 Annex 9, page 2 I:\MSC\105\
MSC 105-20-Add.1.docx ANNEX --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeC
entre/IndexofIMOResolutions/MSCResolutions/MSC.502(105).pdf (1983 SPS CODE) MSC 105/20/A
dd.1 Annex 9, page 2 I:\MSC\105\MSC 105-20-Add.1.docx ANNEX AMENDMENTS TO THE CODE OF SA
FETY FOR SPECIAL PURPOSE SHIPS, 1983 (1983 SPS CODE) APPENDIX FORM OF SAFETY CERTIFICATE
FOR SPECIAL PURPOSE SHIPS Special Purpose Ship Safety Certificate The existing form of S
afety Certificate for Special Purpose Ships , including the associated record of equipme
nt for Special Purpose Ship Safety Certificate (Form SPS), contained in the appendix to
the annex is replaced by the following: RESOLUTION MSC.502(105) (adopted on 28 April 202
2) AMENDMENTS TO THE CODE OF SAFETY FOR SPECIAL PURPOSE SHIPS, 1983 (1983 SPS CODE) MSC
105/20/Add.1 Annex 9, page 3 I:\MSC\105\MSC 105-20-Add.1.docx "FORM OF SAFETY CERTIFICAT
E FOR SPECIAL PURPOSE SHIPS SPECIAL PURPOSE SHIP SAFETY CERTIFICATE This Certificate sho
uld be supplemented by a Record of Equipment (Form SPS) (Official seal) (State) --- URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolu
tions/MSC.502(105).pdf This Certificate should be supplemented by a Record of Equipment
(Form SPS) (Official seal) (State) Issued in compliance with the provisions of the CODE
OF SAFETY FOR SPECIAL PURPOSE SHIPS under the authority of the Government of (name of th
e State) by (person or organization authorized) Particulars of ship1 Name of ship Distin
ctive number or letters Port of registry Gross tonnage Sea areas in which ship is certif
icated to operate (SOLAS regulation IV/2)2 IMO number3 Ship's special purpose Date on wh
ich keel was laid or ship was of a similar stage of construction or, where applicable, d
ate on which work for a conversion or an alteration or modification of a major character
was commenced 1 Alternatively, the particulars of the ship may be placed horizontally in
boxes.

2 For a ship certified to operate in sea area A3, indicate the recognized mobile satelli
te service in brackets.

--- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/
MSCResolutions/MSC.502(105).pdf 2 For a ship certified to operate in sea area A3, indica
te the recognized mobile satellite service in brackets.

3 Refer to the IMO Ship Identification Number Scheme, adopted by the Organization by res
olution A.1117(30).

RESOLUTION MSC.502(105) (adopted on 28 April 2022) AMENDMENTS TO THE CODE OF SAFETY FOR
SPECIAL PURPOSE SHIPS, 1983 (1983 SPS CODE) MSC 105/20/Add.1 Annex 9, page 4 I:\MSC\105\
MSC 105-20-Add.1.docx THIS IS TO CERTIFY: 1 That the ship has been surveyed in accordanc
e with the requirements of regulation 1.6 of the Code.

2 That the survey showed that: 2.1 the ship complied with the provisions of the Code as
regards: .1 the structure, main and auxiliary machinery, boilers and other pressure vess
els; and .2 the watertight subdivision arrangements and details; 2.2 the ship complied w
ith the provisions of the Code as regards structural fire protection, fire safety system
s and appliances, and fire-control plans; --- URL: https://wwwcdn.imo.org/localresources
/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.502(105).pdf fire safety sy
stems and appliances, and fire-control plans; 2.3 the life-saving appliances and the equ
ipment of the lifeboats, liferafts and rescue boats were provided in accordance with the

provisions of the Code; 2.4 the shi p was provided with a line -throwing appliance in ac cordance with the provisions of the Code; 2.5 the ship complied with the provisions of t he Code as regards radio installations; 2.6 the provision and functioning of the radio i nstallations used in life-saving appliances complied with the provisions of the Code; 2. 7 the ship complied with the provisions of the Code as regards shipborne navigational eq uipment, means of embarkation for pilots and nautical publications; 2.8 the ship was pro vided with lights , shapes and means of making sound signals and distress signals, in ac cordance with the provisions of the Code and the International Regulations for Preventin g Collisions at Sea in force; and --- URL: https://wwwcdn.imo.org/localresources/en/Know ledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.502(105).pdf distress signals, in a ccordance with the provisions of the Code and the International Regulations for Preventi ng Collisions at Sea in force; and 2.9 in all other respects the ship complied with the relevant provisions of the Code.

3 That an Exemption Certificate has/has not4 been issued.

4 That the ship has/has not4 been provided with Certificates issued under the 1974 SOLAS Convention, as amended.

This certificate is valid until Completion date of the survey on which this certificate is based: (dd/mm/yyyy) Issued at .....
.....

(Place of issue of certificate) …… ……..

(Date of issue) (Signature of authorized official issuing the certificate) (Seal or stam p of the issuing authority, as appropriate) 4 Delete as appropriate.

RESOLUTION MSC.502(105) (adopted on 28 April 2022) --- URL: https://wwwcdn.imo.org/local resources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.502(105).pdf (Seal or stamp of the issuing authority, as appropriate) 4 Delete as appropriate.

RESOLUTION MSC.502(105) (adopted on 28 April 2022) AMENDMENTS TO THE CODE OF SAFETY FOR SPECIAL PURPOSE SHIPS, 1983 (1983 SPS CODE) MSC 105/20/Add.1 Annex 9, page 5 I:\MSC\105\ MSC 105-20-Add.1.docx ENDORSEMENT FOR ANNUAL SURVEYS RELATING TO HULL, MACHINERY AND EQU IPMENT REFERRED TO IN SECTION 2.1 OF THIS CERTIFICATE THIS IS TO CERTIFY that, at a surv ey required by 1.6 of the Code, the ship was found to comply with the relevant provision s of the Code.

Annual survey: Signed .....

(Signature of authorized official) Place .....
.....

Date .....

(Seal or stamp of the Authority, as appropriate) Annual survey: Signed .....
.....

--- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/ MSCResolutions/MSC.502(105).pdf (Seal or stamp of the Authority, as appropriate) Annual survey: Signed .....

(Signature of authorized official) Place .....
.....

Date .....

(Seal or stamp of the Authority, as appropriate) Annual survey: Signed .....
.....

(Signature of authorized official) Place .....
.....

Date .....

(Seal or stamp of the Authority, as appropriate) Annual survey: Signed .....
.....

(Signature of authorized official) Place .....
.....

Date .....

--- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/ MSCResolutions/MSC.502(105).pdf Date .....
.....

(Seal or stamp of the Authority, as appropriate) RESOLUTION MSC.502(105) (adopted on 28

April 2022) AMENDMENTS TO THE CODE OF SAFETY FOR SPECIAL PURPOSE SHIPS, 1983 (1983 SPS C
ODE) MSC 105/20/Add.1 Annex 9, page 6 I:\MSC\105\MSC 105-20-Add.1.docx ENDORSEMENT FOR A
NNUAL AND PERIODICAL SURVEYS RELATING TO LIFE-SAVING APPLIANCES AND OTHER EQUIPMENT REFE
RRED TO IN SECTIONS 2.2, 2.3, 2.4, 2.6, 2.7, 2.8 AND 2.9 OF THIS CERTIFICATE THIS IS TO
CERTIFY that, at a survey required by 1.6 of the Code, the ship was found to comply with
the relevant provisions of the Code.

Annual survey: Signed (Signature of authorized official) Place Date (Seal or stamp of th
e Authority, as appropriate) Annual/periodical4 survey: Signed (Signature of authorized
official) Place Date (Seal or stamp of the Authority, as appropriate) Annual/periodical4
survey: Signed --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/Indexof
IMOResolutions/MSCResolutions/MSC.502(105).pdf Place Date (Seal or stamp of the Authorit
y, as appropriate) Annual/periodical4 survey: Signed (Signature of authorized official)
Place Date (Seal or stamp of the Authority, as appropriate) Annual survey: Signed (Signa
ture of authorized official) Place Date (Seal or stamp of the Authority, as appropriate)
4 Delete as appropriate.

RESOLUTION MSC.502(105) (adopted on 28 April 2022) AMENDMENTS TO THE CODE OF SAFETY FOR
SPECIAL PURPOSE SHIPS, 1983 (1983 SPS CODE) MSC 105/20/Add.1 Annex 9, page 7 I:\MSC\105\
MSC 105-20-Add.1.docx ENDORSEMENT FOR PERIODICAL SURVEYS RELATING TO RADIO INSTALLATIONS
REFERRED TO IN SECTION 2.5 OF THIS CERTIFICATE THIS IS TO CERTIFY that, at a survey requ
ired by 1.6 of the Code, the ship was found to comply with the relevant provisions of th
e Code: Periodical survey: Signed (Signature of authorized official) Place Date --- URL:
https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolu
tions/MSC.502(105).pdf comply with the relevant provisions of the Code: Periodical surve
y: Signed (Signature of authorized official) Place Date (Seal or stamp of the Authority,
as appropriate) Periodical survey: Signed (Signature of authorized official) Place Date
(Seal or stamp of the Authority, as appropriate) Periodical survey: Signed (Signature of
authorized official) Place Date (Seal or stamp of the Authority, as appropriate) Annual
survey: Signed (Signature of authorized official) Place Date (Seal or stamp of the Autho
rity, as appropriate) RESOLUTION MSC.502(105) (adopted on 28 April 2022) AMENDMENTS TO T
HE CODE OF SAFETY FOR SPECIAL PURPOSE SHIPS, 1983 (1983 SPS CODE) MSC 105/20/Add.1 Annex
9, page 8 I:\MSC\105\MSC 105-20-Add.1.docx ENDORSEMENT FOR THE EXTENSION OF THE CERTIFIC
ATE The ship complies with the relevant provisions of the Code and this Certificate shou
ld, in accordance --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/Inde
xofIMOResolutions/MSCResolutions/MSC.502(105).pdf The ship complies with the relevant pr
ovisions of the Code and this Certificate should, in accordance with 1.7.3, be accepted
as valid until Signed (Signature of authorized official) Place Date (Seal or stamp of th
e Authority, as appropriate) RESOLUTION MSC.502(105) (adopted on 28 April 2022) AMENDMEN
TS TO THE CODE OF SAFETY FOR SPECIAL PURPOSE SHIPS, 1983 (1983 SPS CODE) MSC 105/20/Add.
1 Annex 9, page 9 I:\MSC\105\MSC 105-20-Add.1.docx ANNEX RECORD OF EQUIPMENT FOR THE SPE
CIAL PURPOSE SHIP SAFETY CERTIFICATE (FORM SPS) This Record should be permanently attach
ed to the Special Purpose Ship Safety Certificate.

RECORD OF EQUIPMENT FOR COMPLIANCE WITH THE CODE OF SAFETY FOR SPECIAL PURPOSE SHIPS 1 P
articulars of ship Name of ship .....
.....

--- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/
MSCResolutions/MSC.502(105).pdf Name of ship .....
.....

Distinctive number or letters .....
.....

Number of special personnel on board (including passengers) for which certified .....
.....
.....

Minimum number of persons on board with required qualifications to operate the radio ins
tallations .....
.....

2 Details of life-saving appliances 1 Total number of persons for which life-saving appl
iances are provided .

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

Port side Starboard side 2 Total number of lifeboats 2.1 Total number of persons accommodated by them --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.502(105).pdf Port side Starboard side 2 Total number of lifeboats 2.1 Total number of persons accommodated by them 2.2 Number of partially enclosed lifeboats (SOLAS regulation III/425) 2.3 Number of self-righting partially enclosed lifeboats (SOLAS regulation III/435) 2.4 Number of totally enclosed lifeboats (SOLAS regulation III/445) 2.5 Other lifeboats 2.5.1 Number 2.5.2 Type .

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

5 Refer to the 1983 amendments to SOLAS (MSC.6(48)), applicable for ships constructed on or after 1 July 1986, but before 1 July 1998.

RESOLUTION MSC.502(105) (adopted on 28 April 2022) --- URL: https://wwwcdn.imo.org/local resources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.502(105).pdf 1 Jul y 1986, but before 1 July 1998.

RESOLUTION MSC.502(105) (adopted on 28 April 2022) AMENDMENTS TO THE CODE OF SAFETY FOR SPECIAL PURPOSE SHIPS, 1983 (1983 SPS CODE) MSC 105/20/Add.1 Annex 9, page 10 I:\MSC\105 \MSC 105-20-Add.1.docx 2 Details of life-saving appliances (continued) 3 Number of motor lifeboats (included in the total lifeboats shown above) 3.1 Number of lifeboats fitted w ith searchlights .

.

.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.

4 Number of rescue boats 4.1 Number of boats which are included in the total lifeboats shown above .

.
.
.
.
.
.
.
.
.
.
.
.
.
.
.

.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
5 Liferafts 5.1 Those for which approved launching appliances are required 5.1.1 Number of liferafts 5.1.2 Number of persons accommodated by them 5.2 Those for which approved launching appliances are not required 5.2.1 Number of liferafts 5.2.2 Number of persons accommodated by them --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.502(105).pdf 5.2 Those for which approved launching appliances are not required 5.2.1 Number of liferafts 5.2.2 Number of persons accommodated by them .
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.

.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.

6 Buoyant apparatus 6.1 Number of apparatus 6.2 Number of persons capable of being suppo rted .

.

.

7 Number of lifebuoys .

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

8 Number of lifejackets .

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

9 Immersion suits 9.1 Total number 9.2 Number of suits complying with the requirements f
or lifejackets .

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
--- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.502(105).pdf .
.
.
.
.
.
.
.
.
.
.

.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
10 Number of thermal protective aids6 .
.
.
.
.
.
.
.

.
.
.
.
.
.
.
.
.
6 Excluding those required by SOLAS regulations III/38.5.1.24, III/41.8.31 and III/47.2.
2.13 of the 1983 amendments to SOLAS (MSC.6(48)) that are applicable to ships constructe
d on or after 1 July 1986, but before 1 July 1998.

RESOLUTION MSC.502(105) (adopted on 28 April 2022) AMENDMENTS TO THE CODE OF SAFETY FOR SPECIAL PURPOSE SHIPS, 1983 (1983 SPS CODE) MSC 105/20/Add.1 Annex 9, page 11 I:\MSC\105 \MSC 105-20-Add.1.docx 3 Details of radio facilities Item Actual provision 1 Primary sys
tems 1.1 VHF radio installation 1.1.1 DSC encoder 1.1.2 DSC watch receiver 1.1.3 Radiote
lephony .
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.

.

.

.

--- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.502(105).pdf .

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
1.2 MF radio installation 1.2.1 DSC encoder 1.2.2 DSC watch receiver 1.2.3 Radiotelephon
y .
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.

.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
1.3 MF/HF radio installation 1.3.1 DSC encoder 1.3.2 DSC watch receiver 1.3.3 Radiotelep
hony .
.
.
.
.

.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
1.4 Recognized mobile satellite service ship earth station .
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
2 Secondary means of initiating the transmission of ship -to-shore distress alerts .
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.

.
3 Facilities for reception of MSI and search and rescue related information .
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
4 EPIRB --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.502(105).pdf 3 Facilities for reception of MSI and search and rescue related information .
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
4 EPIRB .
.
.
.
.
.
.
.
.
.
.
.
.
.

5 Two-way VHF radiotelephone apparatus 5.1 Portable two-way VHF radiotelephone apparatus
5.2 Two-way VHF radiotelephone apparatus fitted in survival craft .

.

.

.

.

.

.

.

.

6 Search and rescue locating devices 6.1 Radar search and r escue transponders (radar SA RT) stowed for rapid placement in survival craft 6.2 Radar search and rescue transponder s (radar SART) stowed in survival craft 6.3 AIS search and rescue transmitters (AIS -SAR T) stowed for rapid placement in survival craft 6.4 AIS search and rescue transmitters (AIS-SART) stowed in survival craft .

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
--- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.502(105).pdf .
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.

.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
RESOLUTION MSC.502(105) (adopted on 28 April 2022) AMENDMENTS TO THE CODE OF SAFETY FOR SPECIAL PURPOSE SHIPS, 1983 (1983 SPS CODE) MSC 105/20/Add.1 Annex 9, page 12 I:\MSC\105 \MSC 105-20-Add.1.docx 4 Methods used to ensure availability of radio facilities (SOLAS regulations IV/15.6 and 15.7) 4.1 Duplication of equipment .....
.....

4.2 Shore-based maintenance .....
.....

4.3 At-sea maintenance capability .....
.....

--- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.502(105).pdf 4.3 At-sea maintenance capability .....
.....

5 Special Purpose Ships constructed before 1 February 1995 which do not comply with all the applicable requirements of chapter IV of the SOLAS Convention, as amended 7 Requirements of regulations Actual provision Hours of listening by operator Number of operators Whether auto alarm fitted Whether main installation fitted Whether reserve installation fitted Whether main and reserve transmitters electrically separated or combined .

.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.

.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
--- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.502(105).pdf .
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.
.

6 Special Purpose Ships constructed before 1 February 1992 which do not comply with the applicable requirements of chapter III of the SOLAS Convention, as amended 8 Actual prov ision Radiotelegraph installation for lifeboat Portable radio apparatus for survival cra ft Survival craft EPIRB (121.5 MHz and 243.0 MHz) Two-way radiotelephone apparatus .

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

.

THIS IS TO CERTIFY that this Record is correct in all respects.

Issued at ....

....

(Place of issue of the Record) ……………………………………… ……………………………………...

--- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.502(105).pdf (Place of issue of the Record) ……………………………………… ……………………… ……………...

(Date of issue) (Signature of authorized official issuing the Record) (Seal or stamp of the issuing authority, as appropriate)" *** 7 This section need not be reproduced on the record attached to certificates issued after 1 February 1999.

8 This section need not be reproduced on the record attached to certificates issued afte

r 1 February 1995.

RESOLUTION MSC.502(105) (adopted on 28 April 2022) AMENDMENTS TO THE CODE OF SAFETY FOR SPECIAL PURPOSE SHIPS, 1983 (1983 SPS CODE) RESOLUTION MSC.502(105) (adopted on 28 April 2022) AMENDMENTS TO THE CODE OF SAFETY FOR SPECIAL PURPOSE SHIPS, 1983 (1983 SPS CODE) -- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.472(101).pdf RESOLUTION MSC.472(101) (adopted on 14 June 2019) AMENDMENTS TO THE REVISED RECOMMENDATION ON TESTING OF LIFE-SAVING APPLIANCES (RESOLUTION MSC.81(70), AS AMENDED) MSC 101/24/Add.1 Annex 26, page 1 I:\MSC\101\MSC 101-24-Add.1.docx ANNEX 26 RESOLUTION MSC.472(101) (adopted on 14 June 2019) AMENDMENTS TO THE REVISED RECOMMENDATION ON TESTING OF LIFE-SAVING APPLIANCES (RESOLUTION MSC.81(70), AS AMENDED) THE MARITIME SAFETY COMMITTEE, RECALLING Article 28(b) of the Convention on the International Maritime Organization concerning the functions of the Committee, RECALLING ALSO that the Assembly, when adopting resolution A.689(17) on Testing of life-saving appliances, authorized the Committee to keep the annexed Recommendati