RECALLING Article 28(b) of the Convention on the International Maritime Organization con cerning the functions of the Committee, RECALLING ALSO resolution MSC.268(85) by which i t adopted the International Maritime Solid Bulk Cargoes Code (hereinafter referred to as "the IMSBC Code"), which has become mandatory under chapter VI of the International Conv ention for the Safety of Life at Sea, 1974, as amended ("the Convention"), RECALLING FUR THER article VIII(b) and regulation VI/1 -1.1 of the Convention concerning amendment pro cedure for amending the IMSBC Code, HAVING CONSIDERED, at its 110th session, amendments to the IMSBC Code, proposed and --- URL: https://wwwcdn.imo.org/localresources/en/Knowle dgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf amendment procedure for amending the IMSBC Code, HAVING CONSIDERED, at its 110th session, amendments to the IMSB C Code, proposed and circulated in accordance with article VIII(b)(i) of the Convention, 1 ADOPTS, in accordance with article VIII(b)(iv) of the Convention, amendments to the IM SBC Code, the text of which is set out in the annex to the present resolution; 2 DETERMI NES, in accordance with article VIII(b)(vi)(2)(bb) of the Convention, that the said amen dments shall be deemed to have been accepted on 1 July 2026, unless prior to that date, more than one third of the Contracting Governments to the Convention or Contracting Gove rnments the combined merchant fleets of which constitute not less than 50% of the gross tonnage of the world's merchant fleet have notified the Secretary -General of their obje ctions to the amendments; 3 INVITES Contracting Governments to the Convention to note th at, in accordance with --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre /IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf to the amendments; 3 INVITES Cont racting Governments to the Convention to note that, in accordance with article VIII(b)(v ii)(2) of the Convention, the amendments shall enter into force on 1 January 2027 upon t heir acceptance in accordance with paragraph 2 above; 4 AGREES that Contracting Governme nts to the Convention may apply the aforementioned amendments in whole or in part on a v oluntary basis as from 1 January 2026; 5 REQUESTS the Secretary -General, for the purpos e of article VIII(b)(v) of the Convention, to transmit certified copies of the present r esolution and the text of the amendments contained in the annex to all Contracting Gover nments to the Convention; 6 ALSO REQUESTS the Secretary -General to transmit copies of t his resolution and its annex to Members of the Organization which are not Contracting Go vernments to the Convention.

RESOLUTION MSC.575(110) (adopted on 26 June 2025) AMENDMENTS TO THE INTERNATIONAL MARITI ME SOLID BULK CARGOES CODE (IMSBC CODE) --- URL: https://wwwcdn.imo.org/localresources/e n/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf the Convention.

RESOLUTION MSC.575(110) (adopted on 26 June 2025) AMENDMENTS TO THE INTERNATIONAL MARITI ME SOLID BULK CARGOES CODE (IMSBC CODE) - 2 - ANNEX AMENDMENTS TO THE INTERNATIONAL MARI TIME SOLID BULK CARGOES CODE (IMSBC CODE) AMENDMENT 08-25 Section 9 – Materials possessi ng chemical hazards 9.3 Stowage and segregation requirements 9.3.3 Segregation between b ulk materials possessing chemical hazards and dangerous goods in packaged form Table in 9.3.3 is amended as follows: The oblique line in the first cell on the left is deleted; the cell is separated into two, and the right cell is merged to the next cell after the separation.

The heading of the first column on the left is replaced to read "Bulk materials (classif ied as dangerous goods)".

In the heading of the fourth column, the term "1.6" is added after the term "1.3".

In the first column on the left, the words "Radioactive materials" are replaced by the w ords "Radioactive material".

--- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/ MSCResolutions/MSC.575(110).pdf In the first column on the left, the words "Radioactive materials" are replaced by the words "Radioactive material".

In the second column on the left, the word "MHB" is deleted.

In paragraph 3 ( "Separated by a complete compartment or hold from"), replace the words "Means either" by the word "Either".

Section 13 – References to related information and recommendations 13.2 Reference list I n paragraph 13.2.3, "MSC.1/Circ.1395/Rev.6" is replaced by "MSC.1/Circ.1395/Rev.7".

In paragraphs 13.2.6 and 13.2.9, the words "Recommendations on the safe use of pesticide s in ships applicable to the fumigation of cargo holds (MSC.1/Circ.1264, as amended by M SC.1/Circ.1396)" are replaced by the words "Revised recommendations on the safe use of p esticides in ships applicable to the fumigation of cargo holds (MSC.1/Circ.1264/Rev.1)".

RESOLUTION MSC.575(110) (adopted on 26 June 2025) AMENDMENTS TO THE INTERNATIONAL MARITI
ME SOLID BULK CARGOES CODE (IMSBC CODE) - 3 - APPENDIX 1 --- URL: https://wwwcdn.imo.org
/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf
RESOLUTION MSC.575(110) (adopted on 26 June 2025) AMENDMENTS TO THE INTERNATIONAL MARITI
ME SOLID BULK CARGOES CODE (IMSBC CODE) - 3 - APPENDIX 1 INDIVIDUAL SCHEDULES OF SOLID B
ULK CARGOES Amendments to existing individual schedules The following individual schedul
es are amended as indicated below: ALUMINIUM FERROSILICON POWDER UN 1395 In the individu
al schedule for "ALUMINIUM FERROSILICON POWDER UN 1395", in the section for "Precautions
", the last sentence is deleted.

ALUMINIUM SILICON POWDER, UNCOATED UN 1398 In the individual schedule for "ALUMINIUM SIL
ICON POWDER, UNCOATED UN 1398", in the section for "Precautions", the last sentence is d
eleted.

ALUMINIUM SMELTING BY -PRODUCTS or ALUMINIUM REMELTING BY -PRODUCTS UN 3170 In the indiv
idual schedule for "ALUMINIUM SMELTING BY -PRODUCTS or ALUMINIUM REMELTING BY -PRODUCTS
UN 3170", in the section for "Precautions", the sentence "At least two sets of self -con
tained breathing apparatus, in addition to those required by --- URL: https://wwwcdn.imo
.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110)
.pdf "At least two sets of self -contained breathing apparatus, in addition to those req
uired by SOLAS regulation II-2/10.10, shall be provided on board" is deleted.

CASTOR BEANS or CASTOR MEAL or CASTOR POMACE or CASTOR FLAKE UN 2969 In the individual s
chedule for "CASTOR BEANS or CASTOR MEAL or CASTOR POMACE or CASTOR FLAKE UN 2969", BCSN
is replaced to read "CASTOR BEANS UN 2969".

In the table for "Characteristics", in the box for "MHB", the words "TX and/or CR" are i
nserted.

In the section for "Hazard", the sentence "This cargo is non -combustible or has a low f
ire risk." is inserted at the end of the section.

DIRECT REDUCED IRON (A), Briquettes, hot-moulded The text in the section for "Descriptio
n" is replaced to read as follows: "Direct reduced iron (DRI) (A) is a metallic grey mat
erial, emanating from a densification process, whereby the DRI feed material is hot-moul
ded into a briquette --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/I
ndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf densification process, whereby the
DRI feed material is hot-moulded into a briquette form with total iron (Fe) content of a
t least 88% by weight at a temperature greater than 650°C." The first and second paragra
phs in the section for "Loading" are replaced, as follows : "Prior to loading this cargo
, the shipper shall provide the master with a certificate issued by a competent person r
ecognized by the competent authority of the port of loading stating that the cargo, at t
he time of loading, is suitable for shipment and that it conforms with the requirements
of this Code: that the apparent density is greater than 5,000 kg/m3; the quantity of fin
es and small particles (under 6.35 mm in size) does not exceed 5% by weight; the moistur
e content does not exceed 1.0%; and the temperature does not exceed 65°C.

This cargo shall not be loaded and shipped under the provisions of this schedule if the
temperature is in excess of 65°C, if its moisture content is in excess of 1.0%, if --- U
RL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCRe
solutions/MSC.575(110).pdf the temperature is in excess of 65°C, if its moisture content
is in excess of 1.0%, if RESOLUTION MSC.575(110) (adopted on 26 June 2025) AMENDMENTS TO
THE INTERNATIONAL MARITIME SOLID BULK CARGOES CODE (IMSBC CODE) - 4 - the quantity of fi
nes and small particles (under 6.35 mm in size) exceeds 5% by weight or if the apparent
density is equal to or less than 5,000 kg/m3." The third paragraph in the section for "L
oading" is replaced, as follows: "Appropriate precautions shall be taken prior to and du
ring loading in order that the cargo be substantially composed of essentially whole and
intact briquettes with minimal presence of exposed or loose uncompacted pellets .

The cargo shall be loaded in such a way so as to minimize breakage of briquettes and the
additional generation of fines and small particles (under 6.35 mm in size) and concentra
tion of fines in any area of the cargo and to minimize the presence of exposed or loose
--- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/
MSCResolutions/MSC.575(110).pdf fines in any area of the cargo and to minimize the prese
nce of exposed or loose uncompacted pellets and concentration thereof in any area of the
cargo.

The addition of fines and small particles (under 6.35 mm in size) or dust or loose pelle
ts in homogeneous cargoes of DRI (A) shall be prohibited." DIRECT REDUCED IRON (B), Lump
s, pellets, cold-moulded briquettes The text in the section for "Description" is replace

d, as follows : "Direct reduced iron (DRI) (B) is a highly porous, black/grey metallic m
aterial formed by the reduction (removal of oxygen) of iron oxide at temperatures below
the fusion point of iron.

Cargoes in briquette form are defined as those with total iron (Fe) content of at least
88% by weight which have been moulded at a temperature not greater than 650°C or which h
ave an apparent density of not greater than 5,000 kg/m3." FERROSILICON UN 1408 with 30%
or more but less than 90% silicon (including briquettes) --- URL: https://wwwcdn.imo.org
/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf
FERROSILICON UN 1408 with 30% or more but less than 90% silicon (including briquettes) I
n the individual schedule for "FERROSILICON UN 1408 with 30% or more but less than 90% s
ilicon (including briquettes)", in the "Appendix", in the section for "General requireme
nts for carriage of ferrosilicon", the first paragraph is deleted and the follo wing par
agraphs are renumbered, accordingly.

FERROSILICON with at least 25% but less than 30% silicon, or 90% or more silicon In the
individual schedule for "FERROSILICON with at least 25% but less than 30% silicon, or 90
% or more silicon", in the "Appendix", in the section for "General requirements for carr
iage of ferrosilicon", the text in paragraph 1 is replaced to read: "1 Two sets of self-
contained breathing apparatus shall be carried in the ship in addition to those required
by SOLAS regulation II -2/10.10.

Self-contained breathing apparatus sets carried in accordance with --- URL: https://wwwc
dn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.57
5(110).pdf addition to those required by SOLAS regulation II -2/10.10.

Self-contained breathing apparatus sets carried in accordance with SOLAS regulation II-2
/19.3.6.2 may be used to comply with this requirement." FERROUS METAL BORINGS, SHAVINGS,
TURNINGS or CUTTINGS UN 2793 in a form liable to self-heating In the individual schedule
for "FERROUS METAL BORINGS, SHAVINGS, TURNINGS or CUTTINGS UN 2793 in a form liable to s
elf-heating", in the section for "Carriage", in the second sentence, the words "or, alte
rnatively, entry is required for this purpose, at least two sets of self-contained breat
hing apparatus, additional to those required by SOLAS regulation II-2/10.10 shall be pro
vided" are deleted.

FISH MEAL (FISH SCRAP), STABILIZED Anti-oxidant treated In the individual schedule for "
FISH MEAL (FISH SCRAP), STABILIZED Anti-oxidant treated" (as adopted by resolution MSC.5
39(107)), BCSN is replaced to read "FISH MEAL (FISH RESOLUTION MSC.575(110) (adopted on
26 June 2025) --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofI
MOResolutions/MSCResolutions/MSC.575(110).pdf (as adopted by resolution MSC.539(107)), B
CSN is replaced to read "FISH MEAL (FISH RESOLUTION MSC.575(110) (adopted on 26 June 202
5) AMENDMENTS TO THE INTERNATIONAL MARITIME SOLID BULK CARGOES CODE (IMSBC CODE) - 5 - S
CRAP), STABILIZED UN 2216 Anti -oxidant treated.

Moisture content greater than 5% but not exceeding 12%, by mass.

Fat content not more than 15%"; in the section for "Description", the words "Moisture co
ntent: greater than 5% but not exceeding 12%, by mass." and the words "Fat content: not
more than 15%, by mass." are deleted; and in the table for "Characteristics", in the box
for "Class", the words "Not applicable" are replaced by the number "9"; and in the box f
or "MHB", the word "SH" is replaced by the wo rd "Not applicable".

In the section for "Precautions", the text in paragraph 1 is replaced to read as follows
: "1 Stabilization of fish meal shall be achieved to prevent spontaneous combustion by t
he effective application of ethoxyquin or BHT (butylated --- URL: https://wwwcdn.imo.org
/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf
"1 Stabilization of fish meal shall be achieved to prevent spontaneous combustion by the
effective application of ethoxyquin or BHT (butylated hydroxytoluene) or tocopherols at
the time of production.

The said application shall occur within 12 months prior to shipment.

Fish scrap or fish meal shall contain remnant measurable anti -oxidant levels of at leas
t 100 ppm (mg/kg) of ethoxyquin, or 100 ppm (mg/kg) of BHT or 250 ppm (mg/kg) of tocophe
rol at the time of shipment." IRON ORE PELLETS In the individual schedule for "IRON ORE
PELLETS", in the section for "Description", the second and third sentences are replaced
to read "This iron oxide is formed into pellets by using binders, such as clay, and then
hardening by firing at 1,200°C to 1,31 5°C.

Moisture content: up to 6%."; and in the table for "Characteristics", in the box for "Bu
lk density", "1,900" is replaced by "1,800"; and in the box for "Stowage factor", the te
rms "0.45" and "0.52" are --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCen

tre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf replaced by "1,800"; and in th
e box for "Stowage factor", the terms "0.45" and "0.52" are replaced by the terms "0.42■
and ■0.56", respectively.

New individual schedules The following new individual schedules are inserted in alphabet
ical order: "ALUMINIUM SULPHATE GRANULAR Description Aluminium sulphate granular consist
s of inorganic white granules.

Hygroscopic in nature.

Soluble in water.

Used as a coagulant for drinking and wastewater treatment.

Characteristics Physical properties Size Angle of repose Bulk density (kg/m3) Stowage fa
ctor (m3 /t) less than 3 mm 40° to 45° 900 to 1,100 0.91 to 1.11 Hazard classification C
lass Subsidiary hazard(s) MHB Group Not applicable Not applicable CR B Hazard Causes ser
ious eye damage.

This cargo is hygroscopic and will cake if wet.

This cargo is highly soluble and will be acidic when wet.

This cargo is non-combustible or has a low fire risk.

Stowage and segregation --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentr
e/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf This cargo is highly soluble and
will be acidic when wet.

This cargo is non-combustible or has a low fire risk.

Stowage and segregation Contact with certain metals, e.g.

aluminium and zinc, may form hydrogen gas.

"Separated from" most other cargoes since it is a drinking water product.

Hold cleanliness Clean and dry as relevant to the quality and hazards of the cargo.

RESOLUTION MSC.575(110) (adopted on 26 June 2025) AMENDMENTS TO THE INTERNATIONAL MARITI
ME SOLID BULK CARGOES CODE (IMSBC CODE) - 6 - Weather precautions This cargo shall be ke
pt as dry as practicable.

It shall not be handled during precipitation.

During handling of this cargo, all non-working hatches of the cargo spaces into which th
is cargo is loaded, or to be loaded, shall be closed.

Loading Trim in accordance with the relevant provisions required under sections 4 and 5
of this Code.

Precautions Persons who may be exposed to the dust of the cargo shall wear protective gl
oves and goggles --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/Index
ofIMOResolutions/MSCResolutions/MSC.575(110).pdf Precautions Persons who may be exposed
to the dust of the cargo shall wear protective gloves and goggles or other equivalent du
st eye -protection, face protection and dust filter masks, as necessary.

Minimize dust generation when loading.

Ventilation The cargo spaces carrying this cargo shall not be ventilated during the voya
ge.

Carriage Hatches of the cargo spaces shall be weathertight to prevent water ingress.

Discharge This cargo is hygroscopic and may cake in overhangs, impairing safety during d
ischarge.

If this cargo has hardened, it shall be trimmed to avoid the formation of overhangs, as
necessary.

Clean-up After discharge of this cargo, the cargo spaces and the bilge wells shall be sw
ept clean and then thoroughly washed out.

Emergency procedures Special emergency equipment to be carried Protective clothing (glov
es, boots, face protection and coveralls).

Self-contained breathing apparatus.

Emergency procedures --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/I
ndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf Protective clothing (gloves, boots,
face protection and coveralls).

Self-contained breathing apparatus.

Emergency procedures Wear protective clothing and self-contained breathing apparatus.

Emergency action in the event of fire Use extinguishers appropriate for surrounding mate rials.

The cargo itself is not combustible.

Medical first aid Refer to the Medical First Aid Guide (MFAG), as amended.

" RESOLUTION MSC.575(110) (adopted on 26 June 2025) AMENDMENTS TO THE INTERNATIONAL MARI TIME SOLID BULK CARGOES CODE (IMSBC CODE) - 7 - "APATITE CONCENTRATE Description Crystal line fine powder of grey colour.

Characteristics Physical properties Size Angle of repose Bulk density (kg/m3) Stowage fa ctor (m3/t) Less than 0.5 mm Not applicable 1,429 to 2,000 0.5 to 0.7 Hazard classificat ion Class Subsidiary hazard(s) MHB Group Not applicable Not applicable Not applicable A Hazard This cargo may liquefy if shipped at a moisture content in excess of its transpor table moisture --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/Indexof IMOResolutions/MSCResolutions/MSC.575(110).pdf Hazard This cargo may liquefy if shipped at a moisture content in excess of its transportable moisture limit (TML).

See sections 7 and 8 of this Code.

This cargo is non-combustible or has a low fire risk.

Stowage and segregation No special requirements.

Hold cleanliness No special requirements.

Weather precautions When a cargo is carried in a ship other than a ship complying with t he requirements in 7.3.2 of this Code, the following provisions shall be complied with: .1 the moisture content of the cargo shall be kept less than its TML during loading oper ations and the voyage; .2 unless expressly provided otherwise in this individual schedul e, the cargo shall not be handled during precipitation; .3 unless expressly provided oth erwise in this individual schedule, during handling of the cargo, all non-working hatche s of the cargo spaces into which the cargo is loaded, or to be loaded, shall be closed; --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/ MSCResolutions/MSC.575(110).pdf handling of the cargo, all non-working hatches of the ca rgo spaces into which the cargo is loaded, or to be loaded, shall be closed; .4 the carg o may be handled during precipitation under the conditions stated in the procedures requ ired in 4.3.3 of this Code; and .5 the cargo in a cargo space may be discharged during p recipitation provided that the total amount of the cargo in the cargo space is to be dis charged in the port.

Loading Hatch covers, manholes and vent openings shall be checked for weather-tightness.

Prior to loading, the holds shall be surveyed carefully to ensure a proper condition of ballast, bilge, fire- extinguishing and other systems.

Additionally, manholes of the ballast tanks shall be checked for water leakage into the cargo spaces.

This cargo shall be trimmed to ensure that the height difference between peaks and troug hs does not exceed 5% of the ship's breadth and that the cargo slopes uniformly from the hatch --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolu tions/MSCResolutions/MSC.575(110).pdf does not exceed 5% of the ship's breadth and that the cargo slopes uniformly from the hatch boundaries to the bulkheads and to avoid steep surfaces of cargo that collapse during the voyage.

When the stowage factor of this cargo is equal to or less than 0.56 m 3/t, the tank top RESOLUTION MSC.575(110) (adopted on 26 June 2025) AMENDMENTS TO THE INTERNATIONAL MARITI ME SOLID BULK CARGOES CODE (IMSBC CODE) - 8 - may be overstressed unless the cargo is ev enly spread across the tank top to equalize the weight distribution.

Due consideration shall be given to ensure that the tank top is not overstressed during the voyage and during loading by a pile of the cargo forming.

Precautions Appropriate precautions shall be taken to protect machinery and accommodatio n spaces from the dust of the cargo.

Bilge wells of the cargo spaces shall be protected from ingress of the cargo.

Due consideration shall be given to protect equipment from the du st of the cargo.

--- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/ MSCResolutions/MSC.575(110).pdf cargo.

Due consideration shall be given to protect equipment from the du st of the cargo.

Persons who may be exposed to the dust of the cargo shall wear protective clothing, gogg
les or other equivalent dust eye -protection and dust filter masks, as necessary.

Bilge wells shall be clean, dry and covered, as appropriate, to prevent ingress of the c
argo.

Ventilation The cargo spaces carrying this cargo shall not be ventilated during the voya
ge Carriage The appearance of the surface of this cargo shall be checked regularly durin
g the voyage.

If free water above the cargo or fluid state of the cargo is observed during the voyage,
the master shall take appropriate action to prevent cargo shifting and potential capsize
of the ship and give consideration to seeking emergency entry into a place of refuge.

Discharge No special requirements.

Clean-up After discharge of this cargo, the bilge wells and the scuppers of the cargo sp
aces shall be --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofI
MOResolutions/MSCResolutions/MSC.575(110).pdf Discharge No special requirements.

Clean-up After discharge of this cargo, the bilge wells and the scuppers of the cargo sp
aces shall be checked and any blockage in the bilge wells and the scuppers shall be remo
ved." RESOLUTION MSC.575(110) (adopted on 26 June 2025) AMENDMENTS TO THE INTERNATIONAL
MARITIME SOLID BULK CARGOES CODE (IMSBC CODE) - 9 - "ASPHALT GRANULATES Description Gran
ulates from the demolition of asphalt roads.

The granulates are re -used for the foundation/sub-base for new roads.

The cargo has a dark grey/black colour and contains no more than 10% asphalt.

The material has, in principle, no odour, but a light bitumen odour may be possible.

The cargo is stored outside (open air).

Characteristics Physical properties Size Angle of repose Bulk density (kg/m3) Stowage fa
ctor (m3/t) Up to 60 mm 30° to 45° 1,700 to 1,800 0.55 to 0.59 Hazard classification Cla
ss Subsidiary hazard(s) MHB Group Not applicable Not applicable Not applicable C Hazard
--- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/
MSCResolutions/MSC.575(110).pdf Hazard classification Class Subsidiary hazard(s) MHB Gro
up Not applicable Not applicable Not applicable C Hazard No special hazards.

This cargo is non-combustible or has a low fire risk.

Stowage and segregation "Away from" alkalis, oxidizing substances, acids, food, drink an
d animal feeding stuffs.

Hold cleanliness No special requirements.

Weather precautions No special requirements.

Loading Trim in accordance with the relevant provisions required under sections 4 and 5
of this Code.

When the stowage factor of this cargo is equal to or less than 0.56 m 3/t, the tank top
may be overstressed unless the cargo is evenly spread across the tank top to equalize th
e weight distribution.

Due consideration shall be given to ensure that the tank top is not overstressed during
the voyage and during loading by a pile of the cargo.

Precautions Bilge wells shall be clean, dry and covered as appropriate, to prevent ingre
ss of the cargo.

--- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/
MSCResolutions/MSC.575(110).pdf Precautions Bilge wells shall be clean, dry and covered
as appropriate, to prevent ingress of the cargo.

Bilge wells of the cargo spaces shall be protected from ingress of the cargo.

Persons who may be exposed to cargo shall wear eye/face protection and applicable filter
masks (in case of inadequate ventilation).

Ventilation No special requirements.

Carriage No special requirements.

Discharge No special requirements.

Clean-up Contaminated washing water shall be retained and disposed of in an appropriate
manner/facility." RESOLUTION MSC.575(110) (adopted on 26 June 2025) AMENDMENTS TO THE IN
TERNATIONAL MARITIME SOLID BULK CARGOES CODE (IMSBC CODE) - 10 - "CRUSHED GRANODIORITE,
COARSE The provisions of this schedule shall apply only to cargoes containing less than

0.1% respirable quartz and less than 7% of particles under 2 mm.

Description Crushed granodiorite is made by blasting, crushing and sieving the common ro ck species --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOR esolutions/MSCResolutions/MSC.575(110).pdf Description Crushed granodiorite is made by b lasting, crushing and sieving the common rock species granodiorite, a grey, very hard an d compact mineral stone.

The aggregate is used as a component in asphalt, concrete and hydraulically unbound mate rials.

Characteristics Physical properties Size Angle of repose Bulk density (kg/m3) Stowage fa ctor (m3/t) Up to 200 mm and less than 7% of particles less than 2 mm 34° to 40° 1,340 t o 1,900 0.53 to 0.75 Hazard classification Class Subsidiary hazard(s) MHB Group Not appl icable Not applicable Not applicable C Hazard No special hazards.

This cargo is non-combustible or has a low fire risk.

Stowage and segregation No special requirements.

Hold cleanliness No special requirements.

Weather precautions No special requirements.

Loading During loading, due consideration shall be given to minimize dust generation.

Trim in accordance with the relevant provisions required under sections 4 and 5 of this Code.

--- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/ MSCResolutions/MSC.575(110).pdf accordance with the relevant provisions required under s ections 4 and 5 of this Code.

When the stowage factor of this cargo is equal to or less than 0.56 m 3/t, the tank top may be overstressed unless the cargo is evenly spread across the tank top to equalize th e weight distribution.

Due consideration shall be given to ensure that the tank top is not overstressed during the voyage and during loading by a pile of the cargo.

Precautions Appropriate precautions shall be taken to protect machinery and accommodatio n spaces from the dust of the cargo.

Bilge wells of the cargo spaces shall be protected from ingress of the cargo.

Due consideration shall be given to protect equipment from the du st of the cargo.

Persons who may be exposed to the dust of the cargo shall wear goggles or other equivale nt dust eye -protection and dust filter masks.

Those persons shall wear protective clothing, as necessary.

Ventilation No special requirements.

Carriage No special requirements.

--- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/ MSCResolutions/MSC.575(110).pdf as necessary.

Ventilation No special requirements.

Carriage No special requirements.

RESOLUTION MSC.575(110) (adopted on 26 June 2025) AMENDMENTS TO THE INTERNATIONAL MARITI ME SOLID BULK CARGOES CODE (IMSBC CODE) - 11 - Discharge No special requirements.

Clean-up No special requirements." "FERRIC SULPHATE GRANULAR Description Ferric sulphate consists of inorganic granules, usually yellow, brown or grey in colour.

Hygroscopic in nature.

Soluble in water.

Used as a coagulant for water treatment.

No special odour.

Moisture normally around 10% (measured at 105°C); no oil in the car go.

Stored under cover.

Characteristics Physical properties Size Angle of repose Bulk density (kg/m3) Stowage fa ctor (m3/t) less than 5 mm 38° to 42° 1,000 to 1,300 0.77 to 1.00 Hazard classification Class Subsidiary hazard(s) MHB Group Not applicable Not applicable CR B Hazard Harmful i f swallowed.

Causes skin irritation.

May cause an allergic skin reaction due to sensitization.

--- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf Hazard Harmful if swallowed.

Causes skin irritation.

May cause an allergic skin reaction due to sensitization.

Causes serious eye damage.

This cargo is highly soluble and will be acidic when wet.

This cargo is hygroscopic and will cake if wet.

This cargo may be subject to decomposition if heated strongly.

Decomposition may produce gases that are toxic (sulphur oxides).

However, this cargo is not subject to an explosion hazard.

Corrodes metals under the influence of moisture.

This cargo is non-combustible or has a low fire risk.

Stowage and segregation "Away from" certain metals, e.g.

aluminium and zinc, that may form hydrogen gas in case of contact with the cargo.

Avoid contact with unalloyed steel or galvanized surfaces; materials not resistant to ac id, copper, aluminium and iron.

"Away" from sources of heat.

Hold cleanliness Clean and dry as relevant to the hazards of the cargo.

Weather precautions --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/In dexofIMOResolutions/MSCResolutions/MSC.575(110).pdf "Away" from sources of heat.

Hold cleanliness Clean and dry as relevant to the hazards of the cargo.

Weather precautions This cargo shall be kept as dry as practicable.

It shall not be handled during precipitation.

During handling of this cargo, all non-working hatches of the cargo spaces into which th is cargo is loaded, or to be loaded, shall be closed.

Loading Trim in accordance with the relevant provisions required under sections 4 and 5 of this Code.

RESOLUTION MSC.575(110) (adopted on 26 June 2025) AMENDMENTS TO THE INTERNATIONAL MARITI ME SOLID BULK CARGOES CODE (IMSBC CODE) - 12 - Precautions Avoid contact with eyes and s kin.

Persons who may be exposed to the dust of the cargo shall wear protective clothing, glov es and eye -protection, as necessary.

Minimize dust generation when loading.

Bilge wells shall be clean, dry and covered, as appropriate, to prevent ingress of the c argo.

Ventilation --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMO Resolutions/MSCResolutions/MSC.575(110).pdf when loading.

Bilge wells shall be clean, dry and covered, as appropriate, to prevent ingress of the c argo.

Ventilation The cargo spaces carrying this cargo shall not be ventilated during the voya ge.

Carriage Hatches of the cargo spaces shall be weathertight to prevent water ingress.

Discharge The product is hygroscopic and may cake in overhangs, impairing safety during discharge.

If this cargo has hardened, it shall be trimmed to avoid the formation of overhangs, as necessary.

No discharge operations during precipitation.

Clean-up After discharge of this cargo, the cargo spaces and the bilge wells shall be sw ept clean and then thoroughly washed out.

Emergency procedures Special emergency equipment to be carried Protective clothing (glov

es, boots and coveralls).

Self-contained breathing apparatus.

Emergency procedures Wear protective clothing and self-contained breathing apparatus.

Emergency action in the event of fire --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf Emergency procedures Wear protective clothing and self-contained breathing apparatus.

Emergency action in the event of fire Use extinguishers appropriate for surrounding materials.

The cargo itself is not combustible.

Medical first aid Refer to the Medical First Aid Guide (MFAG), as amended.

" "FISH MEAL (FISH SCRAP), STABILIZED This schedule shall only apply to fish meal that does not meet any of the criteria on dangerous goods or materials hazardous only in bulk specified in sections 9.2.2 or 9.2.3, respectively.

Description Fresh whole pelagic fish or trimmings for food grade fillet factories that are cooked, dried, with added anti-oxidants and milled before storage.

The product is light brown to brown in colour.

Water content between 5% to 10%, Fat content below 12%.

Most particles between 0.08 mm to 1.2 mm.

Smells of fish.

Characteristics Physical properties Size Angle of repose Bulk density (kg/m3) Stowage factor (m3/t) --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf to 1.2 mm.

Smells of fish.

Characteristics Physical properties Size Angle of repose Bulk density (kg/m3) Stowage factor (m3/t) Not applicable Not applicable 300 to 700 1.43 to 3.33 Hazard classification Class Subsidiary hazard(s) MHB Group Not applicable Not applicable Not applicable C Hazard Liable to cause oxygen depletion in cargo space.

RESOLUTION MSC.575(110) (adopted on 26 June 2025) AMENDMENTS TO THE INTERNATIONAL MARITIME SOLID BULK CARGOES CODE (IMSBC CODE) - 13 - This cargo is non-combustible or has a low fire risk.

Stowage and segregation No special requirements.

Hold cleanliness Clean and dry as relevant to the hazards of the cargo.

Weather precautions This cargo shall be kept as dry as practicable.

This cargo shall not be handled during precipitation.

During handling of this cargo, all non -working hatches of the cargo spaces into which this cargo is loaded, or to be loaded, shall be closed.

Loading --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf which this cargo is loaded, or to be loaded, shall be closed.

Loading Trim in accordance with the relevant provisions required under sections 4 and 5 of this Code.

The cargo shall not be accepted for loading when the temperature of the cargo exceeds 35 °C or 5°C above the ambient temperature, whichever is higher.

The cargo may be loaded without weathering/curing prior to loading.

A certificate from an entity recognized by the competent authority of the port of loading shall be provided by the shipper prior to loading, stating that the material does not meet the MHB (SH) criteria specified in 9.2.3.3 of this Code.

Precautions The shipper shall further provide the master with a certificate issued by an entity recognized by the competent authority of the port of loading specifying: .1 moisture content; .2 fat content; and .3 details of anti-oxidant treatment.

A suitable equipment for quantitative measurement of the concentration of oxygen in the cargo --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolutions/MSC.575(110).pdf .3 details of anti-oxidant treatment.

A suitable equipment for quantitative measurement of the concentration of oxygen in the cargo space shall be provided on board the ship.

Entry of personnel into cargo spaces for this cargo shall not be permitted until tests h
ave been carried out and it has been established that the oxygen content has been restor
ed to a normal level.

Ventilation No special requirements.

Carriage No special requirements.

Discharge No special requirements.

Clean-up No special requirements." "IRON ORE BRIQUETTES Description This cargo is compos
ed of hard briquettes generated in the process of cold agglomeration of iron ore and bin
ders, such as sodium silicate.

Iron ore briquettes are odourless and vary in RESOLUTION MSC.575(110) (adopted on 26 Jun
e 2025) AMENDMENTS TO THE INTERNATIONAL MARITIME SOLID BULK CARGOES CODE (IMSBC CODE) -
14 - colour, from beige to dark grey, always granular in form, pillow -shaped, not solub
le in water --- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMO
Resolutions/MSCResolutions/MSC.575(110).pdf BULK CARGOES CODE (IMSBC CODE) - 14 - colour
, from beige to dark grey, always granular in form, pillow -shaped, not soluble in water
and resistant to ageing.

Characteristics Physical properties Size Angle of repose Bulk density (kg/m3) Stowage fa
ctor (m3/t) 10 mm to 40 mm Not applicable 1,800 to 2,400 0.42 to 0.56 Hazard classificat
ion Class Subsidiary hazard(s) MHB Group Not applicable Not applicable Not applicable C
Hazard This cargo may affect magnetic compasses.

This cargo is non-combustible or has a low fire risk.

Stowage and segregation No special requirements.

Hold cleanliness No special requirements.

Weather precautions No special requirements.

Loading Trim in accordance with the relevant provisions required under sections 4 and 5
of this Code.

As the density of the cargo is extremely high, the tank top may be overstressed unless t
he cargo is evenly spread across the tank top to equalize the weight distribution.

--- URL: https://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/
MSCResolutions/MSC.575(110).pdf cargo is evenly spread across the tank top to equalize t
he weight distribution.

Due consideration shall be given to ensure that the tank top is not overstressed duri ng
the voyage and during loading by a pile of the cargo.

Precautions Loading rates of this cargo are normally very high.

Due consideration shall be given to the ballasting operation in developing the loading p
lan required by SOLAS regulation VI/7.3.

Bilge wells shall be clean, dry and protected as appropriate to prevent ingress of the c
argo.

Ventilation No special requirements.

Carriage No special requirements.

Discharge No special requirements.

Clean-up No special requirements." RESOLUTION MSC.575(110) (adopted on 26 June 2025) AME
NDMENTS TO THE INTERNATIONAL MARITIME SOLID BULK CARGOES CODE (IMSBC CODE) --- URL: http
s://wwwcdn.imo.org/localresources/en/KnowledgeCentre/IndexofIMOResolutions/MSCResolution
s/MSC.579(110).pdf RESOLUTION MSC.579(110) (adopted on 20 June 2025) ACCESSIBILITY OF IN
FORMATION ON SEAFARER MEDICAL CERTIFICATES AND MEDICAL PRACTITIONERS RECOGNIZED FOR THE
PURPOSE OF CONDUCTING SEAFARER MEDICAL EXAMINATIONS MSC 110/21/Add.3 Annex 15, page 1 I:
\MSC\110\MSC 110-21-Add.3.docx ANNEX 15 RESOLUTION MSC.579(110) (adopted on 20 June 2025
) ACCESSIBILITY OF INFORMATION ON SEAFARER MEDICAL CERTIFICATES AND MEDICAL PRACTITIONER
S RECOGNIZED FOR THE PURPOSE OF CONDUCTING SEAFARER MEDICAL EXAMINATIONS THE MARITIME SA
FETY COMMITTEE, RECALLING Articles 28(a) and 28(b) of the Convention on the Internationa
l Maritime Organization with respect to the functions of the Maritime Safety Committee,
RECOGNIZING that regulation I/9 of the International Con