Ex.No.-1.2-Design and draft the given 2D sketches in modelling software.

AIM:

To sketch the given drawing with dimensions using fusion 360 tool.


REQUIREMENTS:

1. Autodesk fusion 360
2. Windows 10
3. 16 GB of RAM (integrated graphics recommend 1GB or more)
4. 2.5 Mbps or faster download; 500 Kbps or faster upload

PROCEDURE:


1. Open new file and then select sketch icon.
2. Select front view.
3. Draw four circles with centre at origin each with diameter 32mm, 42mm, 64mm and 80mm respectively.
4. Draw two circles with same centre at a horizontal distance of 70mm to the left from the origin. Their diameters are 30mm and 40mm.

5. On the top-left, at a horizontal distance of 50mm and vertical distance of 60mm, draw two circles of diameters 30mm and 42mm having same centre point.




6. Create a partition in the ring formed by the middle circles having centre at origin.


7. Use the circular pattern tool to create 6 of such partitions.



8. Trim the excess.
9. Create a circle of diameter 40mm tangent to the top-left and centre circles.
10. Draw a tangent line and connect the top-left and left circles.
11. Use the mirror tool to project the image about the x and y axis.




12. Trim the excess.



13. After finishing the sketch use finish sketch option to finalize the sketch.
14. Extrude the sketch for a distance of 20mm.
15. Switch to drawing mode to plot the sketch in ISO standard.

OUTPUT:



RESULT:

Thus the given sketch is drawn and drafted using fusion 360 tool.