# Ex.No.-1.1-Design and Draft the given 2D Sketches in modelling software.

## AIM:

To sketch the given drawing with dimensions using fusion 360 tool.


## REQUIREMENTS:

1. Autodesk fusion 360
2. Windows 10
3. 16 GB of RAM (integrated graphics recommended 2GB or more)
4. 2.5 Mbps or faster download; 500 Kbps or faster upload

## PROCEDURE:


1. Open new file and then select sketch icon.
2. Select front view.
3. Draw two circles of diameter 40mm and 66mm with same centre at origin.
4. Below it, at a distance of 50mm from the centre, draw another pair of circles with diameters 10mm and 20mm.
5. On the bottom-left, at a distance of 47 mm horizontally and 26 mm vertically from the centre, draw a pair of circle with same centre point of diameters 14mm and 20mm.

6. On the top, at a distance of 65mm from the centre, draw two circles with diameters 20mm and 32mm.





7. Create a circle with diameter 128mm and tangent it to the top and centre circles.
8. Create a circle with diameter 40mm and tangent it to the bottom-left and centre circles, above the circle.
9. Create a circle with diameter 20mm and tangent it to the bottom-left and centre circles, below the circle.

10. Create a circle with diameter 40mm and tangent it to the bottom and centre circles.





11. Trim the excess.
12. Use the mirror tool to copy the left side to the right side.





13. Draw a circle with diameter 12mm on the centre circle.
14. Use the circular pattern to create 6 circles on the surface of that centre circle.

15. Trim off the excess.




16. After finishing the sketch use finish sketch option to finalize the sketch.
17. Extrude the sketch for a distance of 20mm.
18. After finishing the sketch switch to drawing mode to plot the sketch in ISO standard.

## OUTPUT:




## RESULT:

Thus the given sketch is drawn and drafted using fusion 360 tool.