

MANUFACTURING QUALITY ASSURANCE REPORT

Session Identifier: Multiple Clips

EXECUTIVE SUMMARY

INSPECTION DATE	2026-02-13 08:02:47
VIDEO SOURCE	Multiple Clips
RAG COLLECTION	multimodal_data
OVERALL VERDICT	FAIL

SOP AUDIT CONTEXT

Inspect all individuals in the scene for Personal Protective Equipment (PPE) compliance. Specifically describe: 1) Presence of high-visibility safety vests (e.g. orange/yellow vests). 2) Presence of safety helmets. 3) Proximity to the moving forklift.

DETAILED FINDINGS & VISUAL EVIDENCE

Finding 1: Inspection Finding

TIMESTAMP 08:02:17
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 0%

AUDIT ANALYSIS:

Consistent absence of required PPE (high-visibility vests and safety helmets) across all observed time frames and individuals, despite no forklift interaction violations.

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: None of the individuals in the scene are visibly wearing PPE, and no interaction with a moving forklift is observed.

[4.0s - 9.0s]: None of the individuals are wearing visible PPE such as high-visibility vests or safety helmets. Two individuals are present; one walks into the frame from the left, and the other follows shortly after. Both are casually dressed in work attire. Their proximity to each other increases slightly as they walk closer together, but there is no direct interaction with the forklift or other machinery in the observed frames.

[8.0s - 13.0s]: The individual is not wearing a high-visibility vest or a safety helmet while walking in the industrial space.

[12.0s - 17.0s]: No high-visibility safety vest or helmet worn; maintains safe distance from forklift.

[16.0s - 21.0s]: No visible safety vests or helmets worn; no interaction with moving machinery observed.

[20.0s - 21.4s]: Neither individual is visibly wearing high-visibility vests or safety helmets; both remain unprotected according to PPE standards.

Finding 2: Inspection Finding

TIMESTAMP 08:02:33
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE **100%**

AUDIT ANALYSIS:

All observed individuals in the scene were found to be in full compliance with the specified PPE requirements (high-visibility safety vests and safety helmets) at all times. Additionally, no unsafe proximities to the moving forklift were reported.

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No PPE-related issues observed.

[4.0s - 9.0s]: **Answer:**

The person is wearing a yellow safety vest and a helmet, meeting PPE requirements. They are in close proximity to the forklift while it operates, likely assisting or guiding its movement. No violations of PPE rules or unsafe positioning relative to the forklift are observed.

[8.0s - 13.0s]: **Final Answer:**

The worker is properly equipped with a yellow safety vest and a white hard hat, adhering to PPE standards. The forklift operates smoothly without abrupt motions, maintaining a steady distance from the worker. No unsafe interactions or hazards are observed in the immediate vicinity.

[12.0s - 17.0s]: **Final Answer:**

The worker is wearing a yellow safety vest and a white hard hat, complying with PPE requirements while operating the forklift alone in a clear workspace.

[16.0s - 21.0s]: **Answer:**

The two workers are both wearing high-visibility safety vests and safety helmets, they remain stationary relative to the forklift, maintaining a safe distance without any immediate interaction.

[20.0s - 25.0s]: Yes, both workers are wearing high-visibility safety vests and safety helmets.

[24.0s - 25.067s]: Yes, the worker is wearing a yellow safety vest and a white helmet.

Finding 3: Inspection Finding

TIMESTAMP 08:02:47
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE **40%**

AUDIT ANALYSIS:

While individuals maintained a safe distance from moving machinery (when present) and wore protective suits and boots, the consistent absence of high-visibility safety vests and safety helmets across all observed intervals constitutes

a significant PPE compliance failure.

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: Not applicable

[4.0s - 9.0s]: No PPE violations were detected. Both individuals are wearing full-body protective suits and black boots but lack high-visibility vests or helmets. They remain outside the immediate path of any moving machinery, maintaining a safe distance.

[8.0s - 13.0s]: No individuals are observed wearing high-visibility safety vests or safety helmets. No forklift movement is visible in the scene.

[12.0s - 13.3s]: No visible PPE (high-visibility vests, helmets) detected on any individuals; proximity to the forklift cannot be assessed without additional context.