

MANUFACTURING QUALITY ASSURANCE REPORT

Session Identifier: Multiple Clips

EXECUTIVE SUMMARY

INSPECTION DATE	2026-02-13 08:27:16
VIDEO SOURCE	Multiple Clips
RAG COLLECTION	multimodal_data
OVERALL VERDICT	FAIL


SOP AUDIT CONTEXT

Inspect all individuals in the scene for Personal Protective Equipment (PPE) compliance. Specifically describe: 1) Presence of high-visibility safety vests (e.g. orange/yellow vests). 2) Presence of safety helmets. 3) Proximity to the moving forklift.

DETAILED FINDINGS & VISUAL EVIDENCE

Finding 1: Inspection Finding

TIMESTAMP 08:26:39
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 0%



AUDIT ANALYSIS:

Consistent absence of required PPE (high-visibility vests and safety helmets) across all observable periods where individuals were present, with no mitigating factors or exceptions noted.

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No PPE observed, no forklift present

[4.0s - 9.0s]: The worker is not wearing a high-visibility vest or a safety helmet. The worker is not near the forklift in these frames.

[8.0s - 13.0s]: Not present

- [12.0s - 17.0s]: **Personal Protective Equipment (PPE) Compliance:**
- **High-visibility safety vests:** Not applicable; no one is wearing a vest.
 - **Safety helmets:** Not applicable; neither individual is wearing a helmet.
 - **Proximity to the moving forklift:** Not applicable; no forklift is visible in the scene.

[16.0s - 21.0s]: Not wearing PPE

[20.0s - 21.4s]: The video does not show any specific instances related to PPE compliance or proximity to the forklift. Therefore, it is not possible to assess whether the observed conditions meet safety standards based solely on the provided information.

Finding 2: Inspection Finding

TIMESTAMP 08:26:58
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE **66%**



AUDIT ANALYSIS:

The worker operating the forklift was not wearing a safety helmet, violating the INSPECTION RULES. However, the high-visibility safety vest requirement was met, and no unsafe proximity to the forklift was observed for the operator themselves, though the environment required cautious navigation.

CHRONOLOGICAL AUDIT TIMELINE:

- [0.0s - 5.0s]: No PPE-related violations observed.
- [4.0s - 9.0s]: Yes
- [8.0s - 13.0s]: Yes, the worker is wearing a high-visibility safety vest. No interaction with moving machinery/vehicles observed.
- [12.0s - 17.0s]: **Final Answer:**
The worker is wearing a yellow safety vest and a white hard hat, both of which are PPE items. Their proximity to the forklift increases as they walk toward it, but no interaction occurs during the observed frames.
- [16.0s - 21.0s]: Yes; the worker is wearing a high-visibility safety vest and a safety helmet.
- [20.0s - 25.0s]: **Industrial Description:**
A worker in a yellow safety vest operates a forklift near scattered cardboard boxes and industrial equipment. Yellow floor markings guide safe pathways. Background elements include metal doors, shelving units, and another person observing nearby. Bright, even lighting ensures visibility.

PPE Compliance:

- **High-Visibility Vest:** Yes (worker wears a yellow safety vest).

- **Safety Helmet:** Not observed on the forklift operator.

Proximity to Forklift:

- Boxes and equipment are closely positioned near the forklift, requiring cautious navigation.

[24.0s - 25.067s]: **Answer:**

The individual is wearing a **high-visibility safety vest** (yellow/orange) and a **safety helmet**, which are correctly worn and comply with PPE standards. No unsafe behavior or improper equipment use is observed. The person

Finding 3: Inspection Finding

TIMESTAMP 08:27:16
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE **0%**



AUDIT ANALYSIS:

Consistent absence of mandatory Personal Protective Equipment (PPE) across all observed time frames, specifically high-visibility safety vests and safety helmets, in the presence of potential hazards (with proximity to moving forklift unable to be assessed but not ruled out entirely).

CHRONOLOGICAL AUDIT TIMELINE:

- [0.0s - 5.0s]: None of the individuals are visibly wearing PPE such as high-visibility vests or safety helmets.
- [4.0s - 9.0s]: No visible PPE violations detected; both individuals wear full-body protective suits but no high-visibility vests or helmets are present. No interaction with a forklift is observed in the static frame.
- [8.0s - 13.0s]: None of the individuals are wearing high-visibility safety vests or safety helmets. Both individuals are dressed in casual clothing. No forklift is visible in the frames provided, so proximity to a moving forklift cannot be assessed.
- [12.0s - 13.3s]: No PPE observed; no interaction with moving machinery noted.