

MANUFACTURING QUALITY ASSURANCE REPORT

Session Identifier: Multiple Clips

EXECUTIVE SUMMARY

INSPECTION DATE	2026-02-13 08:38:03
VIDEO SOURCE	Multiple Clips
RAG COLLECTION	multimodal_data
OVERALL VERDICT	FAIL

SOP AUDIT CONTEXT

Inspect all individuals in the scene for Personal Protective Equipment (PPE) compliance. Specifically describe: 1) Presence of high-visibility safety vests (e.g. orange/yellow vests). 2) Presence of safety helmets. 3) Proximity to the moving forklift.

DETAILED FINDINGS & VISUAL EVIDENCE

Finding 1: Inspection Finding

TIMESTAMP 08:37:27
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 0%



AUDIT ANALYSIS:

Consistent lack of Personal Protective Equipment (PPE) across all observed scenarios, specifically the absence of high-visibility safety vests and safety helmets among all individuals, leads to a failure in compliance with the inspection rules.

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: **Answer:**
The scene depicts an industrial warehouse with two people present. One individual wears an orange safety vest but no helmet, while the other lacks visible PPE. No forklift is observed in motion, so proximity to it cannot be evaluated.

[4.0s - 9.0s]: No high-visibility safety vests or safety helmets are visible on the individuals; they are wearing full-body white protective suits only.

[8.0s - 13.0s]: The individual walking does not visibly wear a high-visibility safety vest or a safety helmet. The forklift is not present in the scene, so proximity cannot be assessed.


[12.0s - 17.0s]: The worker is not wearing any visible PPE, including a high-visibility vest or safety helmet. No interaction with moving machinery or vehicles is observed.

[16.0s - 21.0s]: Not present

[20.0s - 21.4s]: **Final Answer:**
The worker is not wearing a high-visibility safety vest or a safety helmet.

Finding 2: Inspection Finding

TIMESTAMP 08:37:46
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE **80%**



AUDIT ANALYSIS:

The majority of observations showed compliance with PPE requirements and safe proximity to the forklift. However, a critical failure was noted at [20.0s - 25.0s] where the forklift operator, directly interacting with moving machinery, was not wearing a safety helmet, violating a key INSPECTION RULE.

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No PPE observed on the individual; they are not wearing a safety vest or helmet.

[4.0s - 9.0s]: Yes, the worker is wearing a yellow safety vest and a helmet, complying with PPE requirements. No proximity to moving machinery or vehicles is observed during this sequence.

[8.0s - 13.0s]: Yes, the worker is wearing a high-visibility safety vest and a safety helmet. No unsafe proximity to the forklift is observed; the operator maintains proper control and distance while maneuvering the vehicle.

[12.0s - 17.0s]: Yes, the worker is wearing a yellow safety vest and a white hard hat, complying with PPE requirements.

[16.0s - 21.0s]: Yes, all three workers are wearing high-visibility safety vests and safety helmets. No interaction with moving machinery observed.

[20.0s - 25.0s]: **Answer:**
The forklift operator is wearing a yellow high-visibility vest but no safety helmet is visible. They maintain a safe distance from nearby boxes while operating the forklift.

[24.0s - 25.067s]: Yes, the person is wearing a yellow safety vest and a white hard hat; they are positioned near the forklift without any apparent interaction occurring at the moment.

Finding 3: Inspection Finding

TIMESTAMP 08:38:03
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE **0%**



AUDIT ANALYSIS:

The majority of the observed timeline (0.0s-9.0s) shows a complete lack of required PPE (high-visibility vests and safety helmets) among individuals, despite proximity to a moving forklift, posing a significant safety risk. The brief period (8.0s-13.0s) where no violation was detected is insufficient to offset the widespread non-compliance, especially since the final observation (12.0s-13.3s) again notes a lack of PPE.

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: None of the individuals in the scene are visibly wearing PPE. The forklift is moving but no immediate danger is observed.

[4.0s - 9.0s]: The two individuals do not wear any visible PPE such as high-visibility vests or safety helmets during their movement through the warehouse.

[8.0s - 13.0s]: No PPE violations detected. The individual is not required to wear PPE based on the task or location.

[12.0s - 13.3s]: None of the individuals are wearing high-visibility safety vests or safety helmets.