

MANUFACTURING QUALITY ASSURANCE REPORT

EXECUTIVE SUMMARY

INSPECTION DATE	2026-02-13 10:09:50
VIDEO SOURCE	stream_1936375f_2026-02-13T10-06-42.060740Z_st_1.267_end_22.633_clip_1.mp4, stream_1936375f_2026-02-13T10-06-42.060740Z_st_33.367_end_58.400_clip_2.mp4, stream_1936375f_2026-02-13T10-06-42.060740Z_st_89.167_end_102.433_clip_3.mp4
OVERALL VERDICT	FAIL

SUMMARY: The inspection revealed significant non-compliance with PPE standards across multiple events, with consistent failures in wearing high-visibility vests and safety helmets. Only one event partially met the criteria, but overall, the site failed to meet the required safety protocols. Critical violations were observed in two out of three inspected events.

PROJECTED IMPROVEMENTS

- Mandatory enforcement of high-visibility safety vests for all individuals in the scene at all times.
- Strict adherence to safety helmet policy for all personnel, with immediate corrective action for non-compliance.
- Comprehensive retraining on PPE protocols for all site workers to address the systemic lack of compliance.

POSITIVE HIGHLIGHTS

- Event 2 demonstrated partial compliance with safe proximity to the forklift when present, indicating some awareness of spatial safety protocols.
- The absence of forklifts in Event 3 prevented potential proximity hazards, though this was overshadowed by PPE non-compliance.
- Event 2 showed mostly correct use of high-visibility vests, highlighting a potential model for improvement in other events.

SOP AUDIT CONTEXT

Inspect all individuals in the scene for Personal Protective Equipment (PPE) compliance. Specifically describe: 1) Presence of high-visibility safety vests (e.g. orange/yellow vests). 2) Presence of safety helmets. 3) Proximity to the moving forklift.

DETAILED FINDINGS & VISUAL EVIDENCE

Finding 1: Inspection Finding

TIMESTAMP 10:09:09
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 0%



AUDIT ANALYSIS:

The observer report consistently indicates that no individuals in the scene wore high-visibility safety vests or safety helmets throughout the observed duration, directly violating the specified INSPECTION RULES. Although proximity to a moving forklift could not be assessed due to its absence, the lack of basic PPE (vests and helmets) on all individuals is a critical non-compliance.

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No PPE violations observed. Both individuals are not wearing high-visibility vests or safety helmets. No forklift or moving machinery is present in the scene.

[4.0s - 9.0s]: **Focus Area Descriptions**

Personal Protective Equipment (PPE)

No PPE violations observed. The individual entering the scene wears a white shirt and dark pants, which do not include high-visibility safety vests or safety helmets. No additional protective gear is visible.

[8.0s - 13.0s]: **Focus Area Descriptions**

Personal Protective Equipment (PPE) Compliance:

The individual in motion is not wearing any visible PPE such as a high-visibility vest or helmet. Their attire consists of a plain white shirt and dark pants, which do not meet standard industrial safety requirements for PPE. The stationary individual in the background also does not appear to be wearing any protective gear. No additional personnel or equipment requiring PPE inspection are present in the scene.

[12.0s - 17.0s]: No PPE visible on either individual. No forklift in motion to assess proximity.

[16.0s - 21.0s]: **Focus Area Descriptions**

Personal Protective Equipment (PPE) Compliance

- **High-Visibility Safety Vests:** Neither individual is wearing a high-visibility vest. The first person wears a light-colored shirt, while the second has darker clothing; neither includes reflective elements typical of PPE.
- **Safety Helmets:** No safety helmets are observed on either individual. Their heads remain uncovered throughout the scene.

Proximity to Moving Forklift

No forklift is visible in the current frame, so proximity cannot be assessed. However, both individuals maintain a safe distance from potential machinery based on their positioning relative to the open space.

[20.0s - 21.4s]: No individuals are observed wearing high-visibility safety vests or safety helmets in the immediate vicinity of the camera's view. The person visible in the background does not exhibit any protective gear either. Since there is no forklift or other machinery in motion, proximity to a moving vehicle cannot be assessed in this particular segment of the video.

Finding 2: Inspection Finding

TIMESTAMP 10:09:28
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 60%



AUDIT ANALYSIS:

While most observations showed compliance with high-visibility vests and safe proximity to the forklift, the consistent absence of safety helmets in one scenario (16.0s - 21.0s) and an initial potential non-compliance (0.0s - 5.0s) without clear task context, indicate partial non-compliance with the inspection rules.

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No specific PPE-related violations observed. The individual is not wearing a high-visibility vest or helmet, which may indicate non-compliance if required for their task. However, no direct interaction with machinery or hazards is evident.

[4.0s - 9.0s]: Yes, the worker is wearing a high-visibility vest and a safety helmet, and they are operating the forklift without others nearby.

[8.0s - 13.0s]: Yes; Yes; Safe distance maintained between the approaching individual and the moving forklift.

[12.0s - 17.0s]: Yes; Yes

[16.0s - 21.0s]: Both individuals wear high-visibility safety vests. No safety helmets are visible. The proximity of the forklift to the workers remains consistent throughout the frames, with no significant change in distance.

[20.0s - 25.0s]: Yes

[24.0s - 25.067s]: Yes; the operator is wearing a yellow safety vest and a white hard hat.

Finding 3: Inspection Finding

TIMESTAMP 10:09:43
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 0%



AUDIT ANALYSIS:

Consistent absence of required PPE (high-visibility vests and safety helmets) across all observed time intervals, despite no forklift presence to mitigate one aspect of the inspection criteria.

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No PPE observed; individual in red clothing not wearing high-visibility vest or helmet. No forklift or moving machinery present to assess proximity risks.

[4.0s - 9.0s]: No PPE violations observed. The two individuals in protective suits are not wearing high-visibility vests or helmets, but no forklift is present to assess proximity.

[8.0s - 13.0s]: No individuals are observed wearing high-visibility safety vests or safety helmets. No proximity to a moving forklift is evident.

[12.0s - 13.3s]: No PPE observed. No forklift movement detected.