

MANUFACTURING QUALITY ASSURANCE REPORT

EXECUTIVE SUMMARY

INSPECTION DATE	2026-02-17 12:21:42
VIDEO SOURCE	stream_9a1bcc65_2026-02-17T12-20-35.833886Z_st_0.000_end_4.680_clip_1.mp4, stream_9a1bcc65_2026-02-17T12-20-35.833886Z_st_0.100_end_20.280_clip_2.mp4
OVERALL VERDICT	PASS

SUMMARY: The inspection yielded a perfect compliance score across all observed events, with no defects detected in any of the specified categories (crumpling, tearing, dents, creases, or open flaps/boxes) for all cardboard boxes inspected.

PROJECTED IMPROVEMENTS

- None identified in this inspection round.
- Consider implementing additional inspection points for enhanced quality control.
- No further training recommended based on current perfect compliance.

POSITIVE HIGHLIGHTS

- Achieved 100% compliance across both inspection events.
- No defects of any kind (crumpling, tearing, dents, creases, open flaps/boxes) were found in any inspected boxes.
- Consistent quality observed across all cardboard boxes (IDs 1-4 in Event 1 and all boxes in Event 2).

SOP AUDIT CONTEXT

Inspect the cardboard boxes on the conveyor belt for: 1) Crumpling, 2) Tearing, 3) Dents, 4) Creases, 5) Open flaps/boxes.

DETAILED FINDINGS & VISUAL EVIDENCE

Finding 1: Inspection Finding

TIMESTAMP 12:21:24
SOP SECTION Safety Protocols
COMPLIANCE SCORE 100%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 7.833s]: The video depicts an industrial conveyor belt system transporting cardboard boxes in a controlled environment. Four distinct cardboard boxes (IDs 1-4) move sequentially along the conveyor belt from right to left. All boxes appear intact, with no visible crumpling, tearing, dents, or creases. Their flaps remain closed and aligned properly throughout their motion. The boxes maintain consistent spacing and alignment as they travel along the belt. A human hand briefly enters the frame from the top-right corner, placing additional boxes onto the conveyor. The surrounding area includes stacked empty cardboard boxes on the left and structural elements typical of a warehouse or factory setting. No anomalies or irregularities in the boxes' appearance or movement are observed.

Finding 2: Inspection Finding

TIMESTAMP 12:21:37
SOP SECTION Safety Protocols
COMPLIANCE SCORE 100%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 33.667s]: None of the inspected boxes exhibit any of the specified defects.