

MANUFACTURING QUALITY ASSURANCE REPORT

EXECUTIVE SUMMARY

INSPECTION DATE	2026-02-27 10:19:37
VIDEO SOURCE	stream_258a9ddc_2026-02-27T10-17-50.301034Z_st_1.267_end_22.667_clip_1.mp4, stream_258a9ddc_2026-02-27T10-17-50.301034Z_st_33.367_end_58.400_clip_2.mp4, stream_258a9ddc_2026-02-27T10-17-50.301034Z_st_89.167_end_102.433_clip_3.mp4
OVERALL VERDICT	FAIL

SUMMARY: The inspection revealed widespread and critical violations of PPE compliance across multiple events, including consistent absence of high-visibility vests and safety helmets, posing significant safety risks. Compliance was inconsistent, with some events showing no adherence to safety standards. Overall, critical safety requirements were not met.

PROJECTED IMPROVEMENTS

- Mandatory enforcement of high-visibility safety vests for all individuals in the scene at all times.
- Strict adherence to safety helmet policy, especially for forklift operators, with immediate corrective action for violations.
- Comprehensive re-training on PPE compliance for all personnel to address the systemic lack of essential safety equipment.

POSITIVE HIGHLIGHTS

- In Event 2, most individuals wore high-visibility safety vests, indicating some level of awareness or policy enforcement.
- No forklift proximity issues were noted in Event 1, suggesting some safety protocols are in place.
- The absence of a forklift in Event 3 did not lead to additional safety violations beyond PPE, indicating controlled operational risks in that specific scenario.

SOP AUDIT CONTEXT

Inspect all individuals in the scene for Personal Protective Equipment (PPE) compliance. Specifically describe: 1) Presence of high-visibility safety vests (e.g. orange/yellow vests). 2) Presence of safety helmets. 3) Proximity to the moving forklift.

DETAILED FINDINGS & VISUAL EVIDENCE

Finding 1: Inspection Finding

TIMESTAMP 10:19:07
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 0%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No instances of non-compliance detected.

[4.0s - 9.0s]: Focus Area Descriptions

Personal Protective Equipment (PPE)

- **High-Visibility Safety Vests:** Not present. Both individuals are not wearing any high-visibility clothing such as orange or yellow safety vests.
- **Safety Helmets:** Not present. Neither individual is wearing a helmet or other head protection gear.

Proximity to Moving Forklift

No forklift is visible in the scene, so proximity to a moving forklift cannot be assessed.

[8.0s - 13.0s]: No PPE detected: Individual not wearing high-visibility vest or helmet. No interaction with forklift observed.

[12.0s - 17.0s]: Focus Area Descriptions

Personal Protective Equipment (PPE) Compliance:

The individual does not appear to be wearing any high-visibility safety vests or safety helmets. Their attire consists of a light-colored shirt and dark pants, which do not meet standard PPE requirements for an industrial setting.

Proximity to Moving Forklift:

There is no visible forklift in motion within these frames. Thus, there is no need to assess proximity to a moving vehicle.

[16.0s - 21.0s]: Final Answer:

No instances of non-compliance were detected. The person is not wearing a high-visibility vest or safety helmet, and they remain outside the immediate path of the forklift.

[20.0s - 21.433s]: Yes; Yes; Yes

Finding 2: Inspection Finding

TIMESTAMP 10:19:19
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 60%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No PPE violations observed. The individual is operating a forklift without visible safety gear (vest/helmet).

[4.0s - 9.0s]: Yes; Person 1 is wearing a yellow safety vest and helmet, and they remain close to the forklift during operation.

[8.0s - 13.0s]: Yes, the operator is wearing a high-visibility vest. No helmets are visible. The operator remains close to the forklift while maneuvering it.

[12.0s - 17.0s]: The worker is wearing a yellow safety vest and a white hard hat, adhering to PPE requirements. They maintain a secure position inside the forklift, showing no unsafe behavior or improper handling. Proximity to the forklift is consistent, with no signs of deviation from safe operational practices.


[16.0s - 21.0s]: The worker is wearing a high-visibility safety vest but lacks a visible safety helmet; they remain closely positioned to the forklift while operating it.

[20.0s - 25.0s]: Yes; both wear yellow safety vests and white hard hats, maintaining a safe distance from the forklift.

[24.0s - 25.067s]: Yes, two people are wearing high-visibility safety vests; both are wearing safety helmets; the proximity to the moving forklift remains consistent throughout the frames.

Finding 3: Inspection Finding

TIMESTAMP 10:19:30
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 0%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: Focus Area 1: Presence of high-visibility safety vests

No high-visibility safety vests are observed being worn by any individuals in the scene.

Focus Area 2: Presence of safety helmets

No safety helmets are visibly worn by any individuals in the scene.

Focus Area 3: Proximity to the moving forklift

There is no visible forklift or other mobile equipment in motion within the scene; therefore, proximity to a moving forklift cannot be assessed.

[4.0s - 9.0s]: **Focus Area Descriptions**

Personal Protective Equipment (PPE):

- **High-Visibility Safety Vests:** No one in the scene is wearing high-visibility safety vests; both individuals are dressed casually.
- **Safety Helmets:** Neither individual is wearing any head protection such as hard hats.

[8.0s - 13.0s]: No PPE detected on the individual; no interaction with machinery or forklifts observed.

[12.0s - 13.3s]: No PPE-related violations were observed; no individuals were present in the scene, and no interactions with forklifts occurred.